



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
4-12-MD <i>0592MD</i>	INSPECTION DOCUMENT MD	KMCO		MTH 04-Feb-2018 HRS 4035.2 LDG 4216		120 2400		29-Feb-2028 6435.2	109 m 20 d 1886.6
4-12-ME <i>0592ME</i>	INSPECTION DOCUMENT ME	*CF		MTH 19-Jan-2008 HRS 0		15000		15000	10451.4
4-12-MF <i>0592MF</i>	INSPECTION DOCUMENT MF	*CF		MTH 19-Jan-2008 HRS 0		7500		7500	2951.4
4-12-MJ <i>0592MJ</i>	INSPECTION DOCUMENT MJ	*CF		MTH 19-Jan-2008 HRS 0		13000		13000	8451.4
4-12-ML <i>0592ML</i>	INSPECTION DOCUMENT ML	*CF		MTH 19-Jan-2008 HRS 0		11500		11500	6951.4
4-12-MM <i>0592MM</i>	INSPECTION DOCUMENT MM	*CF		MTH 19-Jan-2008 HRS 0		11000		11000	6451.4
4-12-MN <i>0592MN</i>	INSPECTION DOCUMENT MN	*CF		MTH 19-Jan-2008 HRS 0		9000		9000	4451.4
4-12-MO <i>0592MO</i>	INSPECTION DOCUMENT MO	*CF		MTH 19-Jan-2008 HRS 0		12500		12500	7951.4
5-12-01	INSPECTION DOCUMENT 1			MTH		12		30-Jun-2019	5 m 21 d
26-22-00-2200 CABIN	CABIN PORTABLE FIRE EXTINGUISHER DETAILED AND (WEIGHT) FUNCTIONAL CHECK	KMCO	C352CS D-00397463	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		12		31-Jul-2019	6 m 22 d
26-22-00-2200 COCKPIT	COCKIT PORTABLE FIRE EXTINGUISHER DETAILED AND (WEIGHT) FUNCTIONAL CHECK	KMCO	C352CS D-00397605	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		12		31-Jul-2019	6 m 22 d
5-12-03	INSPECTION DOCUMENT 3			MTH		24		31-Dec-2019	11 m 22 d
5-12-06	INSPECTION DOCUMENT 6			MTH		48		30-Jun-2020	17 m 21 d
5-12-07	INSPECTION DOCUMENT 7			MTH 18-Jul-2018 HRS 4323.7 LDG 4518		1600		5923.7	1375.1
5-12-08	INSPECTION DOCUMENT 8			MTH HRS LDG		2400		6377.6	1829
5-12-11	INSPECTION DOCUMENT 11			MTH		48		31-Dec-2019	11 m 22 d
5-12-12	INSPECTION DOCUMENT 12			MTH 18-Jul-2018 HRS 4323.7 LDG 4518		60		18-Jul-2023	54 m 9 d
5-12-13	INSPECTION DOCUMENT 13			MTH 10-Dec-2015 HRS 3044.4 LDG 3068		72		10-Dec-2021	35 m 1 d
5-12-16	INSPECTION DOCUMENT 16			MTH		96		31-Dec-2023	59 m 22 d
5-12-17	INSPECTION DOCUMENT 17			MTH 19-Jan-2008 HRS 0		6000		6000	1451.4
5-12-19	INSPECTION DOCUMENT 19	KMCO		MTH 21-Dec-2018 HRS 4548.6 LDG 4775		300		4848.6	300
5-12-21	INSPECTION DOCUMENT 21	KMCO		MTH 21-Dec-2018 HRS 4548.6 LDG 4775		12 600			
24-32-00-7202	42 AMP-HOUR CONCORDE LEAD ACID MAIN BATTERY (CAPACITY CHECK) FUNCTIONAL CHECK	KMCO	RG-380E/44LA5 40894801	MTH 21-Dec-2018 HRS 4548.6 LDG 4775	6	12 600		31-Dec-2019 5148.6	11 m 22 d 600



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-22	INSPECTION DOCUMENT 22		MTH			6600		9644.4	5095.8
5-12-25	INSPECTION DOCUMENT 25		MTH			7200		11523.7	6975.1
055000 E1	FOD		MTH	19-Jan-2008		A/R			
055000 E2	FOD		MTH	19-Jan-2008		A/R			
055005 E1	BIRD STRIKE		MTH	19-Jan-2008		A/R			
055005 E2	BIRD STRIKE		MTH	19-Jan-2008		A/R			
055010 E1	ENGINE WINDMILLING IN FLIGHT		MTH	19-Jan-2008		A/R			
055010 E2	ENGINE WINDMILLING IN FLIGHT		MTH	19-Jan-2008		A/R			
055015 E1	LIGHTNING STRIKE		MTH	19-Jan-2008		A/R			
055015 E2	LIGHTNING STRIKE		MTH	19-Jan-2008		A/R			
055020 E1	FUEL FILTER IMPENDING BYPASS		MTH	19-Jan-2008		A/R			
055020 E2	FUEL FILTER IMPENDING BYPASS		MTH	19-Jan-2008		A/R			
055025 E1	ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT		MTH	19-Jan-2008		A/R			
055025 E2	ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT		MTH	19-Jan-2008		A/R			
055030 E1	INCORRECT ENGINE SHUTDOWN ON THE GROUND		MTH	19-Jan-2008		A/R			
055030 E2	INCORRECT ENGINE SHUTDOWN ON THE GROUND		MTH	19-Jan-2008		A/R			
055035 E1	HEAVY LANDING		MTH	19-Jan-2008		A/R			
055035 E2	HEAVY LANDING		MTH	19-Jan-2008		A/R			
055040 E1	SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE OF LIMITS		MTH	19-Jan-2008		A/R			
055040 E2	SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE OF LIMITS		MTH	19-Jan-2008		A/R			
055045 E1	ITT SPIKE ON ENGINE START DUE TO A FROZEN FAN		MTH	19-Jan-2008		A/R			
055045 E2	ITT SPIKE ON ENGINE START DUE TO A FROZEN FAN		MTH	19-Jan-2008		A/R			
055050 E1	LOOSE HIGH PRESSURE COMPRESSOR CASE BOLTS		MTH	19-Jan-2008		A/R			
055050 E2	LOOSE HIGH PRESSURE COMPRESSOR CASE BOLTS		MTH	19-Jan-2008		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
055055 E1	DATA COLLECTION UNIT (DCU) INOPERATIVE			MTH 19-Jan-2008		A/R			
055055 E2	DATA COLLECTION UNIT (DCU) INOPERATIVE			MTH 19-Jan-2008		A/R			
055060 E1	AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH			MTH 19-Jan-2008		A/R			
055060 E2	AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH			MTH 19-Jan-2008		A/R			
055065 E1	STARTER GENERATOR FAIL INDICATION			MTH 19-Jan-2008		A/R			
055065 E2	STARTER GENERATOR FAIL INDICATION			MTH 19-Jan-2008		A/R			
055070 E1	HYDRAULIC PUMP UNSCHEDULED REMOVAL			MTH 19-Jan-2008		A/R			
055070 E2	HYDRAULIC PUMP UNSCHEDULED REMOVAL			MTH 19-Jan-2008		A/R			
057120 E1	INSPECTION LOW UTILIZATION KMCO			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		24		29-Feb-2020	13 m 20 d
057120 E2	INSPECTION LOW UTILIZATION KMCO			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		24		29-Feb-2020	13 m 20 d
12-26-00-6001	15 DAY HIGH EXPOSURE AREA WASH			DAYS		A/R			
12-26-00-6002	45 DAY MEDIUM EXPOSURE AREA WASH			DAYS		A/R			
12-26-00-6003	90 DAY LOW EXPOSURE AREA WASH			DAYS		A/R			
23-90-20-7200 NO. 1 059245 : XPDR1	NO. 1 TRANSPONDER FUNCTIONAL CHECK (AIRPLANES -5001 THRU -6000) - (14 CFR PART 91.413) KMCO		7517400-922 05089525	MTH 06-Dec-2017		24		31-Dec-2019	11 m 22 d
23-90-20-7200 NO. 2 059245 : XPDR2	NO. 2 TRANSPONDER FUNCTIONAL CHECK (AIRPLANES -5001 THRU -6000) - (14 CFR PART 91.413) KMCO		7517400-922 97021228	MTH 06-Dec-2017		24		31-Dec-2019	11 m 22 d
25-60-10-7203	ARTEX C406-N EMERGENCY LOCATOR/TRANSMITTER SYSTEM DETAILED INSPECTION AND FUNCTIONAL CHECK (AIRPLANES -5565 AND ON) - (14 CFR PART 91.207) KMCO		453-5060 4196	MTH 21-Dec-2018 HRS 4548.6 LDG 4775		12		31-Dec-2019	11 m 22 d
26-21-01-7100 AFT	AFT ENGINE FIRE EXTINGUISHER BOTTLE LOW PRESSURE SWITCH OPERATIONAL CHECK 30400037-1 54573B1			MTH		60		31-Mar-2021	New Req
26-21-01-7100 FORWARD	FWD ENGINE FIRE EXTINGUISHER BOTTLE LOW PRESSURE SWITCH OPERATIONAL CHECK 30400037-1 55423B1			MTH		60		31-Dec-2022	New Req
26-21-01-7101 APU	AUXILIARY POWER UNIT FIRE EXTINGUISHER BOTTLE LOW PRESSURE SWITCH OPERATIONAL CHECK 30100033 46780A1			MTH		60		31-Dec-2022	New Req
26-21-01-7800 AFT 059238 : A	AFT ENGINE FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST) RESTORATION - (US DOT CFR 49 PART 180.209) KMCO		30400037-1 54573B1	MTH 02-Mar-2016		60		31-Mar-2021	26 m 22 d



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
26-21-01-7800 FORWARD <i>059238 : F</i>	FORWARD ENGINE FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST) RESTORATION - (US DOT CFR 49 PART 180.209)	KMCO		30400037-1 55423B1	MTH 06-Dec-2017		60		31-Dec-2022	47 m 22 d
26-21-01-9600.1 AFT/FWD	13083-5 AND AE13083-5 AFT ENGINE FIRE EXTINGUISHER FORWARD CARTRIDGE SQUIB CARTRIDGE - SERVICE LIFE			13083-5 09-2015	MTH 21-Aug-2016 HRS 3338.6 LDG 3371		72		21-Aug-2022	43 m 12 d
26-21-01-9600.1 AFT REAR	13083-5 AND AE13083-5 AFT ENGINE FIRE EXTINGUISHER AFT CARTRIDGE SQUIB DISCARD - SERVICE LIFE			13083-5 09-2015	MTH 21-Aug-2016 HRS 3338.6 LDG 3371		72		21-Aug-2022	43 m 12 d
26-21-01-9600.1 FORWARD/FORW ARD	13083-5 AND AE13083-5 FORWARD ENGINE FIRE EXTINGUISHER FORWARD CARTRIDGE SQUIB DISCARD - SERVICE LIFE			13083-5 18C710-001	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		72		18-Jul-2024	66 m 9 d
26-21-01-9600.1 FWD REAR	13083-5 AND AE13083-5 FORWARD ENGINE FIRE EXTINGUISHER AFT CARTRIDGE SQUIB DISCARD - SERVICE LIFE			13083-5 18C710-001	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		72		18-Jul-2024	66 m 9 d
26-21-01-9601.1	13083-5 AND AE13083-5 AUXILIARY POWER UNIT FIRE EXTINGUISHER CARTRIDGE SQUIB DISCARD - SERVICE LIFE			13083-5 18C710-001	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		72		18-Jul-2024	66 m 9 d
26-22-00-7800 CABIN <i>059241 : CABIN</i>	CABIN PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST) FUNCTIONAL CHECK	KMCO		C352CS D-00397463	MTH 01-Jan-2017		144		31-Jan-2029	120 m 22 d
26-22-00-7800 COCKPIT <i>059241 : CKPT</i>	COCKPIT PORTABLE FIRE EXTINGUISHER (HYDROSTATIC TEST) FUNCTIONAL CHECK	KMCO		C352CS D-00397605	MTH 01-Jan-2017		144		31-Jan-2029	120 m 22 d
26-23-00-7800 APU <i>059238 : APU</i>	APU FIRE EXTINGUISHER BOTTLE (HYDROSTATIC TEST) RESTORATION (US DOT CFR 49)	KMCO		30100033 46780A1	MTH 06-Dec-2017		60		31-Dec-2022	47 m 22 d
A262003 CABIN <i>059213 : CABIN</i>	RESTORATION PORTABLE HALON FIRE EXTINGUISHER (INTERNAL INSPECTION)	KMCO		C352CS D-00397463	MTH 01-Jan-2017		72		31-Jan-2023	48 m 22 d
A262003 COCKPIT <i>059213 : CKPT</i>	RESTORATION PORTABLE HALON FIRE EXTINGUISHER (INTERNAL INSPECTION)	KMCO		C352CS D-00397605	MTH 01-Jan-2017		72		31-Jan-2023	48 m 22 d
28-00-02-2200	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)				MTH 19-Jan-2008		A/R			
28-00-02-2201	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)				MTH 19-Jan-2008		A/R			
32-30-09-7800 <i>059237 : N2</i>	EMERGENCY PNEUMATIC STORAGE BOTTLE (HYDROSTATIC TEST) RESTORATION	KMCO		40005347-3 5483	MTH 01-Nov-2018		36		30-Nov-2021	34 m 21 d
32-40-00-2200 LEFT	LEFT LANDING GEAR BRAKES DETAILED INSPECTION			3-1571-6 3139	MTH 19-Jan-2008					WHL/C WHL/C
32-40-00-2200 RIGHT	RIGHT LANDING GEAR BRAKES DETAILED INSPECTION	KMCO		3-1571-6 2114	MTH 18-Jul-2018 HRS 4323.7 LDG 4518					WHL/C WHL/C WHL/C WHL/C
32-40-00-7200 LEFT	LEFT BRAKE ASSEMBLY (WEAR PIN) FUNCTIONAL CHECK			3-1571-6 3139	MTH 19-Jan-2008					WHL/C WHL/C
32-40-00-7200 RIGHT	RIGHT BRAKE ASSEMBLY (WEAR PIN) FUNCTIONAL CHECK			3-1571-6 2114	MTH 19-Jan-2008					WHL/C WHL/C



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
32-41-00-2100 LEFT	LEFT LANDING GEAR AXLE GENERAL VISUAL INSPECTION			3-1571-6 3139	MTH 19-Jan-2008		WHL/C WHL/C			
32-41-00-2100 NOSE	NOSE LANDING GEAR AXLE GENERAL VISUAL INSPECTION			3-1418-OPT2 8754	MTH 19-Jan-2008		WHL/C WHL/C			
32-41-00-2100 RIGHT	RIGHT LANDING GEAR AXLE GENERAL VISUAL INSPECTION			3-1571-6 2114	MTH 19-Jan-2008		WHL/C WHL/C			
32-41-00-2101 NOSE	OPTIONAL NOSE WHEEL SPIN UP GENERAL INSPECTION			3-1418-OPT2 8754	MTH 19-Jan-2008		WHL/C WHL/C			
32-41-00-2800 NOSE <i>059243 : N</i>	NOSE LANDING GEAR WHEEL (EDDY CURRENT) SPECIAL DETAILED INSPECTION	KMCO		3-1418-OPT2 8754	MTH 04-Feb-2018 HRS 4035.2 LDG 4216		A/R			
32-41-00-2801 LEFT <i>059243 : L</i>	LEFT MAIN LANDING GEAR WHEEL (EDDY CURRENT) SPECIAL DETAILED INSPECTION	KMCO		3-1571-6 3139	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		A/R			
32-41-00-2801 RIGHT <i>059243 : R</i>	RIGHT MAIN LANDING GEAR WHEEL (EDDY CURRENT) SPECIAL DETAILED INSPECTION	KMCO		3-1571-6 2114	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		A/R			
32-41-00-7200 NOSE	OPTIONAL NOSE WHEEL SPIN UP FUNCTIONAL CHECK			3-1418-OPT2 8754	MTH 19-Jan-2008		WHL/C WHL/C			
34-90-10-7200 NO. 1 <i>059245 : ADC#1</i>	NO.1 (PILOT) PITOT-STATIC SYSTEM FUNCTIONAL CHECK(AIRPLANES -5001 THRU -6000) (14 CFR 91.411, 91.413 ANDRVSM CERTIFICATION)	KMCO		7030700-71703 07081582	MTH 06-Dec-2017		24		31-Dec-2019	11 m 22 d
34-90-10-7200 NO. 2 <i>059245 : ADC#2</i>	NO. 2 (CO-PILOT) PITOT-STATIC SYSTEM FUNCTIONAL CHECK(AIRPLANES -5001 THRU -6000) (14 CFR 91.411, 91.413 ANDRVSM CERTIFICATION)	KMCO		7030700-71703 07081583	MTH 06-Dec-2017		24		31-Dec-2019	11 m 22 d
34-90-10-7200 RVSM <i>059245</i>	RVSM SKIN WAVINESS INSPECTION PITOT-STATIC SYSTEM FUNCTIONAL CHECK(AIRPLANES -5001 THRU -6000) (14 CFR 91.411, 91.413 ANDRVSM CERTIFICATION)	KMCO			MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		24		31-Dec-2019	11 m 22 d
34-90-10-7200 SECONDARY <i>059245 : ADU</i>	FUNCTIONAL CHECK SECONDARY (STANDBY) ADU PITOT-STATIC SYSTEM FUNCTIONAL CHECK(AIRPLANES -5001 THRU -6000) (14 CFR 91.411, 91.413 ANDRVSM CERTIFICATION)	KMCO		501-1890-02 2384	MTH 06-Dec-2017		24		31-Dec-2019	11 m 22 d
35-90-00-7800 <i>059237 : O2</i>	OXYGEN BOTTLE ASSEMBLY (HYDROSTATIC TEST) RESTORATION(DOT-SP 8162)	KMCO		804882-14 CO9040611-A	MTH 01-Sep-2018		60		30-Sep-2023	56 m 21 d
49-30-00-9600	AUXILIARY POWER UNIT FUEL FILTER ELEMENT DISCARD				MTH 14-Dec-2017 APUH 1898.5		24 900		31-Dec-2019 2798.5	11 m 22 d 595.5
49-40-00-2200	AUXILIARY POWER UNIT IGNITER PLUG DETAILED INSPECTION	KMCO			MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		24 900		18-Jul-2019 2798.5	6 m 9 d 595.5
49-70-01-2200	AUXILIARY POWER UNIT MAGNETIC CHIP COLLECTOR DETAILED INSPECTION				MTH 14-Dec-2017 APUH 1898.5		12 450		18-Jul-2019 2348.5	6 m 9 d 145.5

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
49-90-00-9600	AUXILIARY POWER UNIT OIL FILTER DISCARD AND OIL SERVICING			MTH 14-Dec-2017 APUH 1898.5		24 900		31-Dec-2019 2798.5	11 m 22 d 595.5
710010 E1	PERFORM COMPRESSOR WASH	KMCO		MTH 18-Jul-2018 HRS 4323.7 LDG 4518		A/R			
710010 E2	PERFORM COMPRESSOR WASH	KMCO		MTH 18-Jul-2018 HRS 4323.7 LDG 4518		A/R			
710020 E1	PERFORMANCE RECOVERY WASH			MTH 19-Jan-2008		A/R			
710020 E2	PERFORMANCE RECOVERY WASH			MTH 19-Jan-2008		A/R			
710060 E1	FUEL CONTROLLING - ENGINE WIRING HARNESS (CLEANING) RESTORATION: DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT AND CONNECT AGAIN. DO THE NECESSARY ENGINE CHECKS AFTER WIRING HARNESS REPLACEMENT	KMCO		MTH 18-Jul-2018 HRS 4323.1 LDG 4518		800		5223.1	674.5
710060 E2	FUEL CONTROLLING - ENGINE WIRING HARNESS (CLEANING) RESTORATION: DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT AND CONNECT AGAIN. DO THE NECESSARY ENGINE CHECKS AFTER WIRING HARNESS REPLACEMENT	KMCO		MTH 18-Jul-2018 HRS 4323.7 LDG 4518		800		5223.7	675.1
720010 E1	OVERHAUL-ENGINE *CF			MTH 19-Jan-2008 HRS 47		5000		5047	498.4
720010 E2	OVERHAUL-ENGINE *CF			MTH 19-Jan-2008 HRS 47		5000		5047	498.4
720060 E1	HOT SECTION INSPECTION			MTH 10-Sep-2014 HRS 2512.2 LDG 2402		2500		5012.2	463.6
720060 E2	HOT SECTION INSPECTION			MTH 10-Sep-2014 HRS 2512.2 LDG 2402		2500		5012.2	463.6
723100 E1	LP COMPRESSOR SECTION - EXTERNAL ENGINE GENERAL VISUAL INSPECTION: DO AN INSPECTION FOR FUEL AND OIL LEAKS, CORROSION, CRACKS AND SIGNS OF DAMAGE			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
723100 E2	LP COMPRESSOR SECTION - EXTERNAL ENGINE GENERAL VISUAL INSPECTION: DO AN INSPECTION FOR FUEL AND OIL LEAKS, CORROSION, CRACKS AND SIGNS OF DAMAGE			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
723110 E1	LP COMPRESSOR SECTION - ENGINE MOUNT GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY AND CONDITION OF THE ENGINE MOUNT			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	New Req
723110 E2	LP COMPRESSOR SECTION - ENGINE MOUNT GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY AND CONDITION OF THE ENGINE MOUNT			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	New Req
723120 E1	LP COMPRESSOR SECTION - COMPRESSOR INLET GENERAL VISUAL INSPECTION: DO AN INSPECTION OF THE COMPRESSOR INLET FAN, FAN EXIT STATOR VANES, ABRADABLE FAN SEAL FOR CLEANLINESS, DAMAGE, CORROSION, EROSION AND FOD			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
723120 E2	LP COMPRESSOR SECTION - COMPRESSOR INLET GENERAL VISUAL INSPECTION: DO AN INSPECTION OF THE COMPRESSOR INLET FAN, FAN EXIT STATOR VANES, ABRADABLE FAN SEAL FOR CLEANLINESS, DAMAGE, CORROSION, EROSION AND FOD			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
723130 E1	LP COMPRESSOR SECTION - EXAMINE THE BOTTOM CENTER AREA OF THE FAN CASE FOR ICE. MAKE SURE THAT THE FAN TURNS FREELY			MTH 19-Jan-2008		A/R			
723130 E2	LP COMPRESSOR SECTION - EXAMINE THE BOTTOM CENTER AREA OF THE FAN CASE FOR ICE. MAKE SURE THAT THE FAN TURNS FREELY			MTH 19-Jan-2008		A/R			
723140 E1	LP COMPRESSOR SECTION - LOW PRESSURE COMPRESSOR SECTION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
723140 E2	LP COMPRESSOR SECTION - LOW PRESSURE COMPRESSOR SECTION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
723200 E1	HP COMPRESSOR SECTION - COMPRESSOR SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
723200 E2	HP COMPRESSOR SECTION - COMPRESSOR SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
723210 E1	HP COMPRESSOR SECTION - HIGH PRESSURE COMPRESSOR SECTION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
723210 E2	HP COMPRESSOR SECTION - HIGH PRESSURE COMPRESSOR SECTION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
724000 E1	COMBUSTION SECTION - COMBUSTION SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
724000 E2	COMBUSTION SECTION - COMBUSTION SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
724010 E1	COMBUSTION SECTION - COMBUSTION SECTION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
724010 E2	COMBUSTION SECTION - COMBUSTION SECTION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
725000 E1	TURBINE SECTION - ACCELERATION/DECELERATION FUNCTIONAL CHECK			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
725000 E2	TURBINE SECTION - ACCELERATION/DECELERATION FUNCTIONAL CHECK			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
725050 E1	TURBINE SECTION - TURBINE SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
725050 E2	TURBINE SECTION - TURBINE SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
725060 E1	TURBINE SECTION - TURBINE SECTION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
725060 E2	TURBINE SECTION - TURBINE SECTION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
726000 E1	ACCESSORY GEARBOX - ENGINE ACCESSORY GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY OF INSTALLATION AND GENERAL CONDITION OF ACCESSORIES AND GEARBOX			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
726000 E2	ACCESSORY GEARBOX - ENGINE ACCESSORY GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY OF INSTALLATION AND GENERAL CONDITION OF ACCESSORIES AND GEARBOX			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
726010 E1	ACCESSORY GEARBOX - ACCESSORY GEARBOX (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
726010 E2	ACCESSORY GEARBOX - ACCESSORY GEARBOX (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
727000 E1	BYPASS SECTION - BYPASS SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
727000 E2	BYPASS SECTION - BYPASS SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
727010 E1	BYPASS SECTION - BYPASS DUCTS AND FAIRINGS GENERAL VISUAL INSPECTION: DO A CHECK FOR CLEANLINESS AND FOD. DO AN INSPECTION FOR CRACKS IN THE OUTER BYPASS DUCT, REAR BYPASS DUCT, STRUTS AND FAIRING			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
727010 E2	BYPASS SECTION - BYPASS DUCTS AND FAIRINGS GENERAL VISUAL INSPECTION: DO A CHECK FOR CLEANLINESS AND FOD. DO AN INSPECTION FOR CRACKS IN THE OUTER BYPASS DUCT, REAR BYPASS DUCT, STRUTS AND FAIRING			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
727030 E1	BYPASS SECTION - BYPASS SECTION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
727030 E2	BYPASS SECTION - BYPASS SECTION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731000 E1	FUEL DISTRIBUTION - EXTERNAL TUBING GENERAL VISUAL INSPECTION: EXAMINE FOR SIGNS OF WEAR, CHAFING, CRACKS, LEAKS AND CORROSION			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
731000 E2	FUEL DISTRIBUTION - EXTERNAL TUBING GENERAL VISUAL INSPECTION: EXAMINE FOR SIGNS OF WEAR, CHAFING, CRACKS, LEAKS AND CORROSION			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
731004 E1	INSPECT FUEL MANIFOLD			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731004 E2	INSPECT FUEL MANIFOLD			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731005 E1	FLOW DIVIDER - OVERHAUL/REFURBISH			MTH HRS		5000		5047	498.4
731005 E2	FLOW DIVIDER - OVERHAUL/REFURBISH			MTH HRS		5000		5047	498.4



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
731010 E1	FUEL DISTRIBUTION - EMERGENCY FUEL SHUTOFF SYSTEM DETAILED INSPECTION: DO AN INSPECTION OF CABLE AND LINKAGES			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
731010 E2	FUEL DISTRIBUTION - EMERGENCY FUEL SHUTOFF SYSTEM DETAILED INSPECTION: DO AN INSPECTION OF CABLE AND LINKAGES			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
731015 E1	INSPECT AND FUNCTIONAL TEST FUEL FILTER DIFFERENTIAL PRESSURE SWITCH			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731015 E2	INSPECT AND FUNCTIONAL TEST FUEL FILTER DIFFERENTIAL PRESSURE SWITCH			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731020 E1	FUEL DISTRIBUTION - FUEL FILTER ELEMENT DETAILED INSPECTION: DO AN INSPECTION FOR FOREIGN MATERIAL AND DAMAGE			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
731020 E2	FUEL DISTRIBUTION - FUEL FILTER ELEMENT DETAILED INSPECTION: DO AN INSPECTION FOR FOREIGN MATERIAL AND DAMAGE			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
731030 E1	INSTALL FILTER NEW FUEL FILTER ELEMENT	KMCO	PN SN-UNKNOWN	MTH 18-Jul-2018 HRS 4323.1 LDG 4518		1200		5523.1	974.5
731030 E2	INSTALL FILTER NEW FUEL FILTER ELEMENT	KMCO	PN SN-UNKNOWN	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		1200		5523.7	975.1
731040 E1	FUEL DISTRIBUTION - FUEL METERING AND CONTROL COMPONENTS GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY, LEAKAGE (NO LEAKAGE PERMITTED) AND GENERAL CONDITION			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
731040 E2	FUEL DISTRIBUTION - FUEL METERING AND CONTROL COMPONENTS GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY, LEAKAGE (NO LEAKAGE PERMITTED) AND GENERAL CONDITION			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
731050 E1	FUEL DISTRIBUTION - FUEL OIL HEAT EXCHANGER GENERAL VISUAL INSPECTION: DO AN INSPECTION FOR SECURITY, LEAKAGE AND GENERAL CONDITION			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
731050 E2	FUEL DISTRIBUTION - FUEL OIL HEAT EXCHANGER GENERAL VISUAL INSPECTION: DO AN INSPECTION FOR SECURITY, LEAKAGE AND GENERAL CONDITION			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
731060 E1	FUEL DISTRIBUTION - FUEL FILTER IMPENDING BYPASS INDICATOR OPERATIONAL CHECK: DO A CHECK OF COCKPIT INDICATOR LAMP			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
731060 E2	FUEL DISTRIBUTION - FUEL FILTER IMPENDING BYPASS INDICATOR OPERATIONAL CHECK: DO A CHECK OF COCKPIT INDICATOR LAMP			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
731070 E1	FUEL DISTRIBUTION - EMERGENCY FUEL SHUTOFF SYSTEM OPERATIONAL CHECK: DO A CHECK FOR THE RIGGING AND OPERATION OF THE EMERGENCY FUEL SHUTOFF SYSTEM			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
731070 E2	FUEL DISTRIBUTION - EMERGENCY FUEL SHUTOFF SYSTEM OPERATIONAL CHECK: DO A CHECK FOR THE RIGGING AND OPERATION OF THE EMERGENCY FUEL SHUTOFF SYSTEM			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
731080 E1	FUEL DISTRIBUTION - FUEL DISTRIBUTION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731080 E2	FUEL DISTRIBUTION - FUEL DISTRIBUTION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731100 E1	FUEL DISTRIBUTION - EMERGENCY FUEL SHUTOFF SYSTEM DETAILED INSPECTION: DO AN INSPECTION THROUGH HOLE IN THE EXHAUST CONE AND CHECK FOR SECURITY OF CONTROL LEVER, SIGNS OF OIL LEAKS OR CARBON AT NO.5 BEARING AREA	KMCO		MTH 30-Jun-2017 HRS 3796.2 LDG 3956		800		4696.2	147.6
731100 E2	FUEL DISTRIBUTION - EMERGENCY FUEL SHUTOFF SYSTEM DETAILED INSPECTION: DO AN INSPECTION THROUGH HOLE IN THE EXHAUST CONE AND CHECK FOR SECURITY OF CONTROL LEVER, SIGNS OF OIL LEAKS OR CARBON AT NO.5 BEARING AREA	KMCO		MTH 30-Jun-2017 HRS 3796.2 LDG 3956		800		4696.2	147.6
731105 E1	VISUAL INSPECTION AND CHECK FREEDOM OF MOVEMENT OF FUEL SHUT-OFF CABLE			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731105 E2	VISUAL INSPECTION AND CHECK FREEDOM OF MOVEMENT OF FUEL SHUT-OFF CABLE			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731125 E1	INSPECT FUEL SHUT-OFF VALVE		PN SN-UNKNOWN	MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731125 E2	INSPECT FUEL SHUT-OFF VALVE		PN SN-UNKNOWN	MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731151 E1	FUEL NOZZLE ASSEMBLY - OVERHAUL/REFURBISH			MTH HRS		5000		5047	498.4
731151 E2	FUEL NOZZLE ASSEMBLY - OVERHAUL/REFURBISH			MTH HRS		5000		5047	498.4
732003 E1	INSPECT EEC			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
732003 E2	INSPECT EEC			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
732005 E1	OVERHAUL - FUEL CONTROL UNIT AND PUMP		1012636-18 F63406	MTH HRS		5000		5047	498.4
732005 E2	OVERHAUL - FUEL CONTROL UNIT AND PUMP		1012636-18 F60010	MTH HRS		5000		5047	498.4
732010 E1	INSPECT T0 SENSOR			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
732010 E2	INSPECT T0 SENSOR			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
732015 E1	INSPECT T1 FCU SENSOR		818487-4 KC077251	MTH 19-Jan-2008 HRS 47		5000		5047	New Req
732015 E2	INSPECT T1 FCU SENSOR		818487-4 KC077248	MTH 19-Jan-2008 HRS 47		5000		5047	New Req
732020 E1	FUEL CONTROLLING - ENGINE WIRING HARNESS GENERAL VISUAL INSPECTION: EXAMINE THE CONTROL LINKAGE AND ROD END BEARINGS FOR FREEDOM OF MOVEMENT			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
732020 E2	FUEL CONTROLLING - ENGINE WIRING HARNESS GENERAL VISUAL INSPECTION: EXAMINE THE CONTROL LINKAGE AND ROD END BEARINGS FOR FREEDOM OF MOVEMENT			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
732030 E1	FUEL CONTROLLING - ENGINE WIRING HARNESS GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY OF ALL CLAMPS AND BRACKETS. EXAMINE THE CABLES FOR SIGN OF WEAR, FRAYING, CHAFING AND CRACKS.DO A CHECK FOR SECURITY OF ALL WIRING HARNESS CONNECTORS. EXAMINE THE OUTER SURFACES FOR CRACKS AND CORROSION			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
732030 E2	FUEL CONTROLLING - ENGINE WIRING HARNESS GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY OF ALL CLAMPS AND BRACKETS. EXAMINE THE CABLES FOR SIGN OF WEAR, FRAYING, CHAFING AND CRACKS.DO A CHECK FOR SECURITY OF ALL WIRING HARNESS CONNECTORS. EXAMINE THE OUTER SURFACES FOR CRACKS AND CORROSION			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
732040 E1	FUEL CONTROLLING - FUEL CONTROLLING (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
732040 E2	FUEL CONTROLLING - FUEL CONTROLLING (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
740010 E1	IGNITION - IGNITERS (TIP MEASUREMENT) FUNCTIONAL CHECK: DO A CHECK FOR CLEANLINESS AND MEASURE EROSION	KMCO		MTH 18-Jul-2018 HRS 4323.1 LDG 4518		800		5123.1	574.5
740010 E2	IGNITION - IGNITERS (TIP MEASUREMENT) FUNCTIONAL CHECK: DO A CHECK FOR CLEANLINESS AND MEASURE EROSION	KMCO		MTH 18-Jul-2018 HRS 4323.7 LDG 4518		800		5123.7	575.1
741000 E1	CLEAN AND INSPECT IGNITION EXCITER BOX			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
741000 E2	CLEAN AND INSPECT IGNITION EXCITER BOX			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
741015 E1	CLEAN AND INSPECT IGNITION PLUGS			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
741015 E2	CLEAN AND INSPECT IGNITION PLUGS			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
742020 E1	IGNITION - IGNITION CABLES GENERAL VISUAL INSPECTION: DO A CHECK FOR CHAFING, WEAR AND SECURITY			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
742020 E2	IGNITION - IGNITION CABLES GENERAL VISUAL INSPECTION: DO A CHECK FOR CHAFING, WEAR AND SECURITY			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
742030 E1	IGNITION - IGNITION EXCITER GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY AND GENERAL CONDITION			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
742030 E2	IGNITION - IGNITION EXCITER GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY AND GENERAL CONDITION			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
742040 E1	IGNITION - IGNITERS OPERATIONAL CHECK: DO AN OPERATIONAL TEST			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
742040 E2	IGNITION - IGNITERS OPERATIONAL CHECK: DO AN OPERATIONAL TEST			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
742050 E1	IGNITION - IGNITION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
742050 E2	IGNITION - IGNITION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
742060 E1	IGNITION - IGNITION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
742060 E2	IGNITION - IGNITION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
751006 E1	ANTI ICING VALVE - OVERHAUL/REFURBISH		540-0406-5 4203	MTH HRS		5000		5047	498.4
751006 E2	ANTI ICING VALVE - OVERHAUL/REFURBISH		540-0406-5 4240	MTH HRS		5000		5047	498.4
751010 E1	AIR SYSTEM - ANTI-ICE VALVE AND P3 ANTI-ICE TUBE (LEAK CHECK) GENERAL VISUAL INSPECTION: DO A CHECK FOR LEAKAGE AT P3 AIR SUPPLY TO BLEED VALVE, ANT-ICE VALVE, ANTI-ICE AIR TUBE AND FCU.			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
751010 E2	AIR SYSTEM - ANTI-ICE VALVE AND P3 ANTI-ICE TUBE (LEAK CHECK) GENERAL VISUAL INSPECTION: DO A CHECK FOR LEAKAGE AT P3 AIR SUPPLY TO BLEED VALVE, ANT-ICE VALVE, ANTI-ICE AIR TUBE AND FCU.			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
751030 E1	REPLACE INTERCOMPRESSORBLEEDVALVE SERVOVALVE			MTH 07-Dec-2011 HRS 1626 LDG 1356		-			
751030 E2	REPLACE INTERCOMPRESSORBLEEDVALVE SERVOVALVE			MTH 23-Nov-2011 HRS 1614 LDG 1345		-			
751040 E1	AIR SYSTEM - AIR SYSTEM (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
751040 E2	AIR SYSTEM - AIR SYSTEM (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
751050 E1	INSPECT LINEAR VARIABLE DIFFERENTIAL TRANSFORMER			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
751050 E2	INSPECT LINEAR VARIABLE DIFFERENTIAL TRANSFORMER			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
751060 E1	AIR SYSTEM - AIR SYSTEM (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
751060 E2	AIR SYSTEM - AIR SYSTEM (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task # City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
751070 E1	AIR SYSTEM - BLEED OFF VALVE GENERAL VISUAL INSPECTION: EXAMINE THE TORQUE MOTOR ELECTRICAL CONNECTION FOR SECURITY, FRAYING AND CORROSION		MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
751070 E2	AIR SYSTEM - BLEED OFF VALVE GENERAL VISUAL INSPECTION: EXAMINE THE TORQUE MOTOR ELECTRICAL CONNECTION FOR SECURITY, FRAYING AND CORROSION		MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
753000 E1	EXAMINE THE BOV TORQUE MOTOR		MTH 19-Jan-2008 HRS 47		5000		5047	New Req
753000 E2	EXAMINE THE BOV TORQUE MOTOR		MTH 19-Jan-2008 HRS 47		5000		5047	New Req
753001 E1	INSPECT P3 AIR INERTIAL SEPARATOR		MTH 19-Jan-2008 HRS 47		5000		5047	New Req
753001 E2	INSPECT P3 AIR INERTIAL SEPARATOR		MTH 19-Jan-2008 HRS 47		5000		5047	New Req
753005 E1	INSPECT COMPRESSOR AIR BLEED VALVE		MTH 19-Jan-2008 HRS 47		5000		5047	New Req
753005 E2	INSPECT COMPRESSOR AIR BLEED VALVE		MTH 19-Jan-2008 HRS 47		5000		5047	New Req
771000 E1	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE INDICATING SPEED SENSOR (ENGINE HSI) SPECIAL DETAILED INSPECTION		MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
771000 E2	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE INDICATING SPEED SENSOR (ENGINE HSI) SPECIAL DETAILED INSPECTION		MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
771010 E1	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE INDICATING SPEED SENSOR SYSTEM (ENGINE TBO) RESTORATION		MTH 19-Jan-2008 HRS 47		5000		5047	New Req
771010 E2	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE INDICATING SPEED SENSOR SYSTEM (ENGINE TBO) RESTORATION		MTH 19-Jan-2008 HRS 47		5000		5047	New Req
771014 E1	INSPECT N1 SPEED SENSOR	31J2072-01 CH1708	MTH 19-Jan-2008 HRS 47		5000		5047	New Req
771014 E2	INSPECT N1 SPEED SENSOR	31J2072-01 CH1720	MTH 19-Jan-2008 HRS 47		5000		5047	New Req
771015 E1	INSPECT N2 SPEED SENSOR	31J2073-01 CH2567	MTH 19-Jan-2008 HRS 47		5000		5047	New Req
771015 E2	INSPECT N2 SPEED SENSOR	31J2073-01 CH2570	MTH 19-Jan-2008 HRS 47		5000		5047	New Req
771020 E1	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE WIRING HARNESS GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY OF ALL CLAMPS AND BRACKETS, CABLES FOR SIGNS OF WEAR, FRAYING, CHAFING AND CRACKS DO A CHECK FOR SECURITY OF ALL WIRING HARNESS CONNECTORS. EXAMINE THE OUTER SURFACES FOR CRACKS AND CORROSION		MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
771020 E2	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE WIRING HARNESS GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY OF ALL CLAMPS AND BRACKETS, CABLES FOR SIGNS OF WEAR, FRAYING, CHAFING AND CRACKS DO A CHECK FOR SECURITY OF ALL WIRING HARNESS CONNECTORS. EXAMINE THE OUTER SURFACES FOR CRACKS AND CORROSION		MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
771030 E1	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE WIRING HARNESS (CLEANING) RESTORATION: DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT AND CONNECT AGAIN. DO THE NECESSARY ENGINE CHECKS AFTER WIRING HARNESS REPLACEMENT		MTH 18-Jul-2018 HRS 4323.1 LDG 4518		800		5223.1	674.5



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
771030 E2	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE WIRING HARNESS (CLEANING) RESTORATION: DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT AND CONNECT AGAIN. DO THE NECESSARY ENGINE CHECKS AFTER WIRING HARNESS REPLACEMENT			MTH 18-Jul-2018 HRS 4323.1 LDG 4518		800		5223.1	674.5
772002 E1	INSPECT AND FUNCTIONAL CHECK T6 HARNESS AND THERMOCOUPLES			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
772002 E2	INSPECT AND FUNCTIONAL CHECK T6 HARNESS AND THERMOCOUPLES			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
772010 E1	INSPECT AND FUNCTIONAL CHECK T1 HARNESS			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
772010 E2	INSPECT AND FUNCTIONAL CHECK T1 HARNESS			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
774040 E1	DATA COLLECTION UNIT - DOWNLOAD DATA 30J3469-02 13-584			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
774040 E2	DATA COLLECTION UNIT - DOWNLOAD DATA 30J3469-02 15033768			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
781000 E1	ENGINE EXHAUST - EXHAUST AND MIXER: GVI OBVIOUS SIGNS OF DAMAGE OR LOOSE DEBRIS			MTH 19-Jan-2008		BF/F BF/F			
781000 E2	ENGINE EXHAUST - EXHAUST AND MIXER: GVI OBVIOUS SIGNS OF DAMAGE OR LOOSE DEBRIS			MTH 19-Jan-2008		BF/F BF/F			
781010 E1	ENGINE EXHAUST - TURBINE EXHAUST CASE AND MIXER (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
781010 E2	ENGINE EXHAUST - TURBINE EXHAUST CASE AND MIXER (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
781020 E1	ENGINE EXHAUST - TURBINE EXHAUST CASE AND MIXER (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
781020 E2	ENGINE EXHAUST - TURBINE EXHAUST CASE AND MIXER (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
781030 E1	ENGINE EXHAUST - EMERGENCY FUEL SHUT OFF LEVER AND CABLE DETAILED INSPECTION: DO AN INSPECTION THROUGH HOLE IN THE EXHAUST CONE FOR SECURITY OF CONTROL LEVER, SIGNS OF OIL LEAKS OR CARBON AT NO.5 BEARING AREA, EXAMINE THE CABLE AND LINKAGES			MTH 30-Jun-2017 HRS 3796.2 LDG 3956		1600		5396.2	847.6
781030 E2	ENGINE EXHAUST - EMERGENCY FUEL SHUT OFF LEVER AND CABLE DETAILED INSPECTION: DO AN INSPECTION THROUGH HOLE IN THE EXHAUST CONE FOR SECURITY OF CONTROL LEVER, SIGNS OF OIL LEAKS OR CARBON AT NO.5 BEARING AREA, EXAMINE THE CABLE AND LINKAGES			MTH 30-Jun-2017 HRS 3796.2 LDG 3956		1600		5396.2	847.6
790020 E1	CHANGE OIL	BLL		MTH 28-Nov-2011 HRS 1616 LDG 1347		A/R			
790020 E2	CHANGE OIL	BLL		MTH 28-Nov-2011 HRS 1616 LDG 1347		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
790030 E1	MONITOR OIL QUALITY			MTH 19-Jan-2008		O/C			
790030 E2	MONITOR OIL QUALITY			MTH 19-Jan-2008		O/C			
790040 E1	INSTALL FILTER NEW OIL FILTER ELEMENT KMCO		PN SN-UNKNOWN	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		1200		5523.7	975.1
790040 E2	INSTALL FILTER NEW OIL FILTER ELEMENT KMCO		PN SN-UNKNOWN	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		1200		5523.7	975.1
791000 E1	OIL SYSTEM - OIL SPECIAL DETAILED INSPECTION: DO A CHECK FOR OIL LEVEL WITH THE OUTBOARD SIGHT GLASS			MTH 19-Jan-2008		BF/F BF/F			
791000 E2	OIL SYSTEM - OIL SPECIAL DETAILED INSPECTION: DO A CHECK FOR OIL LEVEL WITH THE OUTBOARD SIGHT GLASS			MTH 19-Jan-2008		BF/F BF/F			
791010 E1	OIL SYSTEM - OIL FILTER DETAILED INSPECTION: REMOVE AND DO A CHECK FOR FOREIGN MATERIAL AND DAMAGE			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
791010 E2	OIL SYSTEM - OIL FILTER DETAILED INSPECTION: REMOVE AND DO A CHECK FOR FOREIGN MATERIAL AND DAMAGE			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
791020 E1	OIL SYSTEM - IMPENDING BYPASS VALVE INDICATOR GENERAL VISUAL INSPECTION: DO A CHECK OF AIRCRAFT COCKPIT INDICATOR LAMP			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
791020 E2	OIL SYSTEM - IMPENDING BYPASS VALVE INDICATOR GENERAL VISUAL INSPECTION: DO A CHECK OF AIRCRAFT COCKPIT INDICATOR LAMP			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
791030 E1	OIL SYSTEM - MAGNETIC CHIP DETECTOR GENERAL VISUAL INSPECTION: REMOVE AND DO A CHECK FOR METALLIC DEBRIS			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
791030 E2	OIL SYSTEM - MAGNETIC CHIP DETECTOR GENERAL VISUAL INSPECTION: REMOVE AND DO A CHECK FOR METALLIC DEBRIS			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
791040 E1	OIL SYSTEM - ACCESSORY GEAR BOX PAD SEAL GENERAL VISUAL INSPECTION: EXAMINE THE PAD SEALS FOR OIL LEAKS			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
791040 E2	OIL SYSTEM - ACCESSORY GEAR BOX PAD SEAL GENERAL VISUAL INSPECTION: EXAMINE THE PAD SEALS FOR OIL LEAKS			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
791050 E1	OIL SYSTEM - EXTERNAL OIL TUBE GENERAL VISUAL INSPECTION: EXAMINE FOR SIGNS OF WEAR, CHAFING, CRACKS, LEAKS AND CORROSION			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
791050 E2	OIL SYSTEM - EXTERNAL OIL TUBE GENERAL VISUAL INSPECTION: EXAMINE FOR SIGNS OF WEAR, CHAFING, CRACKS, LEAKS AND CORROSION			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
791060 E1	OIL SYSTEM - EXTERNAL ENGINE GENERAL VISUAL INSPECTION: EXAMINE FOR FUEL AND OIL LEAKS, CORROSION, CRACKS AND SIGNS OF DAMAGE			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
791060 E2	OIL SYSTEM - EXTERNAL ENGINE GENERAL VISUAL INSPECTION: EXAMINE FOR FUEL AND OIL LEAKS, CORROSION, CRACKS AND SIGNS OF DAMAGE			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
791070 E1	OIL ANALYSIS			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
791070 E2	OIL ANALYSIS			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
791080 E1	OIL SYSTEM - FUEL OIL HEAT EXCHANGER GENERAL VISUAL INSPECTION: DO AN INSPECTION FOR SECURITY, LEAKAGE AND GENERAL CONDITION. NO LEAKAGE PERMITTED			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
791080 E2	OIL SYSTEM - FUEL OIL HEAT EXCHANGER GENERAL VISUAL INSPECTION: DO AN INSPECTION FOR SECURITY, LEAKAGE AND GENERAL CONDITION. NO LEAKAGE PERMITTED			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	276
792010 E1	INSPECT AND FUNCTIONAL TEST OIL FILTER DIFFERENTIAL PRESSURE SWITCH			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
792010 E2	INSPECT AND FUNCTIONAL TEST OIL FILTER DIFFERENTIAL PRESSURE SWITCH			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
793001 E1	INSPECT CHIP DETECTOR/COLLECTOR			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
793001 E2	INSPECT CHIP DETECTOR/COLLECTOR			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
793005 E1	FUEL TO OIL HEAT EXCHANGER - OVERHAUL/REFURBISH			MTH HRS		5000		5047	498.4
793005 E2	FUEL TO OIL HEAT EXCHANGER - OVERHAUL/REFURBISH			MTH HRS		5000		5047	498.4
793006 E1	INSPECT AND FUNCTION TEST OIL TANK FILLER CAP			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
793006 E2	INSPECT AND FUNCTION TEST OIL TANK FILLER CAP			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
793021 E1	INSPECT OIL LEVEL INDICATOR (SIGHT GLASS)			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
793021 E2	INSPECT OIL LEVEL INDICATOR (SIGHT GLASS)			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
80-11-00-2200 APU	AUXILIARY POWER UNIT STARTER - GENERATOR DETAILED INSPECTION	KMCO	300SGL138Q-6 4294XL	MTH 04-Feb-2018 HRS 4035.2 LDG 4216 APUH 1935		500		2435	232



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
251052	CABIN ROUTER ATG-2000	KMCO		P12083-001 1208373940	MTH 27-Dec-2017 HRS 3977.6 LDG 4149		O/C	0 0 0		
211002	EMERGENCY PRESSURIZATION FLOW (UY005) VALVE	*CF		4713-19 0954	MTH 19-Jan-2008		O/C			
211120 LEFT	BI LEVEL VALVE 9912492-1	*CF		1988-00-3 2675	MTH 19-Jan-2008		O/C			
211120 RIGHT	BI LEVEL VALVE 9912492-1	*CF		1988-00-3 2674	MTH 19-Jan-2008		O/C			
212100 LOWER LEFT	WARM AIR CHECK VALVE *CF			4001-20 3628A	MTH 19-Jan-2008		O/C			
212100 LOWER RIGHT	WARM AIR CHECK VALVE *CF			4001-20 3626A	MTH 19-Jan-2008		O/C			
212100 UPPER RIGHT	COOL AIR CHECK VALVE *CF			4001-20 3596A	MTH 19-Jan-2008		O/C			
212100 UPPER LEFT	COOL AIR CHECK VALVE *CF			4001-20 3634A	MTH 19-Jan-2008		O/C			
212200	MOTOR AND BLOWER ASSEMBLY *CF			7003-400 0696	MTH 19-Jan-2008		O/C			
213005	MANUAL TOGGLE VALVE 9912409-12	*CF		52773-114 1380	MTH 19-Jan-2008		O/C			
213006	CABIN ALTITUDE (U1005) CONTROLLER 9912409-13	*CF	G	52770-116 2691	MTH 19-Jan-2008		O/C			
213007 PRIMARY	OUTFLOW VALVE 9912409-19	*CF	A	52771-314 1179B	MTH 19-Jan-2008		O/C			
213007 SECONDARY	OUTFLOW VALVE 9912409-11	ICT	H	52772-114 1084B	MTH 27-Jun-2012 HRS 1715 LDG 1393		O/C	1 0		
213101	ALT PRESSURE SWITCH 9910095-6	ICT		GB300NA161 1144791	MTH 27-Jun-2012 HRS 1715 LDG 1393		O/C	0 0		
215001	ENVIRONMENTAL CONTROL UNIT 9912493-8	*CF		2215460-3 905	MTH 19-Jan-2008		O/C			
215004	PAC OVERHEAT SWITCH 1173T0570	*CF		927223-2-2 0411	MTH 19-Jan-2008		O/C			
215005	ACM COOLING TURBINE *CF			2206610-1 898	MTH 19-Jan-2008		O/C			
215006	HEAT EXCHANGER *CF			2340594-6 970	MTH 19-Jan-2008		O/C			
215100	WATER SPRAY ECU ASPIRATOR 9912493-3	*CF		2215605-1 NSN	MTH 19-Jan-2008		O/C			
215101	WATER SEPARATOR TEMP 1 SENSOR 9914130-20	*CF		1E62-1 9BC176	MTH 19-Jan-2008		O/C			
216002	ENVIRONMENTAL TEMP CONTROLLER 9912518-5	*CF	M3	1E64-2 3BC28	MTH 19-Jan-2008		O/C			
216003 NO. 1	CABIN TEMP SENSOR 9914130-20	KMCO		1E62-1 87BN64	MTH 29-Sep-2016 HRS 3382.3 LDG 3428		O/C	0 0		
216003 NO. 2	CABIN TEMP SENSOR 9914130-3	*CF		1E47-1 8BC213	MTH 19-Jan-2008		O/C			
216009 CABIN	ZONE TEMPERATURE (UC021) SENSOR 9914130-6	*CF		1E46-1 5BC151	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
216009 COCKPIT	ZONE TEMPERATURE (UF029) SENSOR 9914130-6	*CF		1E46-1 8BC284	MTH 19-Jan-2008		O/C			
216099 216100	ECU TEMP CONTROL VALVE 9912518-2	*CF		27241287-14 10BC330A	MTH 19-Jan-2008		O/C			
216100 LEFT	CABIN TEMPERATURE CONTROL (VT029) VALVE 9912518-2	KMCO		27241287-14 8AV141F	MTH 12-Nov-2016 HRS 3436.5 LDG 3517		O/C	2 0		
216100 RIGHT	COCKPIT TEMPERATURE CONTROL (VT030) VALVE 9912518-2	MCO		27241287-14 12BB414F	MTH 24-Oct-2015 HRS 2993.3 LDG 3013		O/C	2 0		
216101 LEFT	CABIN DUCT OVERHEAT (SC013) SWITCH 9914130-6	*CF		1173T42 3467	MTH 19-Jan-2008		O/C			
216101 RIGHT	COCKPIT DUCT OVERHEAT (SF034) SWITCH 9914130-6	*CF		1173T42 3435	MTH 19-Jan-2008		O/C			
217001	WATER SEPARATOR 9912493-7	*CF		2341316-2 903	MTH 19-Jan-2008		O/C			
217101 LEFT	OZONE CONVERTER 9914523-2	*CF		31A437-1 12992349	MTH 19-Jan-2008		O/C			
217101 RIGHT	OZONE CONVERTER 9914523-2	*CF		31A437-1 12492344	MTH 19-Jan-2008		O/C			
221009	AUTOPILOT (PC400) CONTROLLER PC-400	*CF	A	7003897-923 07083704	MTH 19-Jan-2008		O/C			
221010 AILERON	DRIVE SERVO 9914523-2	*CF	M	4006719-921 0706H823	MTH 19-Jan-2008		O/C			
221010 ELEVATOR	DRIVE SERVO 9914523-2	*CF		4006719-921 0707H895	MTH 19-Jan-2008		O/C			
221010 RUDDER	DRIVE SERVO 9914523-2	*CF		4006719-922 0707H888	MTH 19-Jan-2008		O/C			
23-70-00-9600 237006A	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY DISCARD 266-E0305-00	KMCO		810-2007/K SD36337	MTH 02-Jun-2014 HRS 2307.6 LDG 2139		DUE DUE DUE DUE	0	01-May-2020	15 m 22 d
Expiration Date: 01-May-2020										
231003	HIGH FREQUENCY RECEIVER/EXCITER HONEYWELL KHF-1050 RX 1053	*CF	0	064-01073-0101 3143	MTH 19-Jan-2008		O/C			
231111	AIRCELL CONFIGURATION MODULE 9914130-6	KMCO		P14126 1412613664	MTH 27-Dec-2017 HRS 3977.6 LDG 4149		O/C	0 0 0		
231501	FLITEPHONE VI ASSEMBLY ANTENNA IRIDIUM	*CF		S67-1575-109 7288	MTH 19-Jan-2008		O/C			
232003 NO. 1	COMM ANTENNA 9914130-6	*CF		S65-8282-1 2313	MTH 19-Jan-2008		O/C			
232003 NO. 2	COMM ANTENNA 9914130-6	KMCO		21-38-1RF/36 50886	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		O/C	0 0		
232004	FLITEPHONE 800 RADIOTELEPHONE (RT800) TRANCEIVER ST3100	*CF		400-10680-001 1068013155	MTH 19-Jan-2008		O/C			
232005	AFIS ANTENNA 9914130-6	*CF		21-38-1RF/36 11245	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
232008 NO. 1	HONEYWELL PRIMUS II SRZ850 INTEGRATED (RCZ851) COMMUNICATION UNIT RCZ-833K	KMCO	AW	7510700-665 05089497	MTH 10-Dec-2015 HRS 3044.4 LDG 3068		O/C			
232008 NO. 2	HONEYWELL PRIMUS II SRZ850 INTEGRATED (RCZ851) COMMUNICATION UNIT RCZ-833K	KJAX		7510700-665 97022312	MTH 29-Sep-2015 HRS 2965.2 LDG 2981		O/C			
232010 NO. 1	COMM TRANSCEIVER TR-833	ICT		7510763-901 0709B824	MTH 27-Jun-2012 HRS 1715 LDG 1393		O/C			
232010 NO. 2	COMM TRANSCEIVER TR-833	KJAX		7510763-901 99084374	MTH 29-Sep-2015 HRS 2965.2 LDG 2981		O/C			
232013 NO. 1	CLUSTER COMM MODULE KMCO	KMCO	L	7510764-901 105087121	MTH 10-Dec-2015 HRS 3044.4 LDG 3068		O/C			
232013 NO. 2	CLUSTER COMM MODULE XC-833	KJAX	J,K,L	7510784-835 99084374	MTH 29-Sep-2015 HRS 2965.2 LDG 2981		O/C			
235001 NO. 1	AUDIO CONTROL PANEL AMPLIFIER AV-850A	KMCO	AC	7511001-915 0708C285	MTH 09-Sep-2015 HRS 2938.2 LDG 2948		O/C			
235001 NO. 2	AUDIO CONTROL PANEL AMPLIFIER AV-850A	KMCO	AC	7511001-915 04049299	MTH 21-Aug-2016 HRS 3338.6 LDG 3371		O/C			
237001	COCKPIT VOICE RECORDER FA2100			2100-1020-02 *CF 000488534	MTH 19-Jan-2008		O/C			
237002	CVR GRAVITY SWITCH *CF			6895D1-X-5-5 7169	MTH 19-Jan-2008		O/C			
237006	CVR UNDERWATER LOCATOR BEACON KMCO	KMCO		DK120 SD36337	MTH 02-Jun-2014 HRS 2307.6 LDG 2139		O/C	0 0		
238001	STDBY CONTROL UNIT CD-850		H	7513000-835 07073521	MTH 19-Jan-2008		O/C			
240001 LEFT	POWER CONTROL (UD015) UNIT 9914216-6			91479-1 *CF 1797	MTH 19-Jan-2008		O/C			
240001 RIGHT	POWER CONTROL (UE016) UNIT 9914216-6			91479-1 *CF 1787	MTH 19-Jan-2008		O/C			
242050 LEFT	AC (UD017) GENERATOR 9914435-8			91372-3 *CF 1349	MTH 19-Jan-2008		O/C			
242050 RIGHT	AC (UE018) GENERATOR 9914435-8			91372-3 *CF 1347	MTH 19-Jan-2008		O/C			
243003 APU	GENERATOR (UT032) CONTROL UNIT *CF			51525-001F P3943	MTH 19-Jan-2008		O/C			
243003 LEFT	GENERATOR (UT007) CONTROL UNIT *CF			51525-001F P3986	MTH 19-Jan-2008		O/C			
243003 RIGHT	GENERATOR (UT008) CONTROL UNIT *CF			51525-001F P3925	MTH 19-Jan-2008		O/C			
243004 LEFT	DC (EI011) AMMETER S3439-1			MD144-1 *CF F0611149	MTH 19-Jan-2008		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
243004 RIGHT	DC (EI010) AMMETER S3439-1	*CF		MD144-1 F0611154	MTH 19-Jan-2008		O/C			
243005	DC (EI009) VOLTMETER MD129-1	*CF		C662502-0101 F0710977	MTH 19-Jan-2008		O/C			
243007	MAIN SHIP (UY006) BATTERY S3597-8	KMCO		RG-380E/44LA5 40894801	MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		O/C	0 0		
243008	OVERHEAT MONITOR	*CF		1529-1 4960	MTH 19-Jan-2008		O/C			
243009	BATTERY TEMP INDICATOR	*CF		1229-1 3484	MTH 19-Jan-2008		O/C			
243010	BATTERY TEMP SENSOR S3597-9	MCO		TS-C1A3 40004021	MTH 25-Oct-2014 HRS 2551.3 LDG 2446		O/C			
243015	BATTERY DISCONNECT (KY001) RELAY	*CF		A876K CP25926	MTH 19-Jan-2008		O/C			
243016	OVERVOLTAGE (UZ003) MONITOR	*CF		1645-1-3 4031	MTH 19-Jan-2008		O/C			
245079 LEFT	START CNTL NZ013 PCB	*CF		6318324-5 NSN	MTH 19-Jan-2008		O/C			
245079 RIGHT	START CNTL NZ012 PCB	*CF		6318324-5 NSN	MTH 19-Jan-2008		O/C			
245080	TRIM NZ001 PCB	*CF		6518351-7 1069	MTH 19-Jan-2008		O/C			
245081	PRESS NZ002 PCB	*CF		6518352-5 NSN	MTH 19-Jan-2008		O/C			
245082	DIMMING NZ023 PCB	*CF		6518366-3 0482	MTH 19-Jan-2008		O/C			
245083 LEFT	EEC INTERFACE NZ021 PCB	*CF		6618002-4 0565	MTH 19-Jan-2008		O/C			
245083 RIGHT	EEC INTERFACE NZ020 PCB	*CF		6618002-4 0564	MTH 19-Jan-2008		O/C			
245084	LANDING GEAR NZ004 PCB	*CF		6618704-6 0819	MTH 19-Jan-2008		O/C			
245086	SQUAT SW NZ006 PCB	*CF		6618706-1 0758	MTH 19-Jan-2008		O/C			
245087	CABIN DOOR NZ007 PCB	*CF		6618707-26 0317	MTH 19-Jan-2008		O/C			
245088	LANDING GEAR CONT NZ009 PCB	*CF		6618735-1 0364	MTH 19-Jan-2008		O/C			
245091	NO TAKE-OFF NZ008 PCB FDR OPTION	*CF		6618708-6 0302	MTH 19-Jan-2008		O/C			
245092 LEFT	FUEL NZ015 PCB	*CF		6618714-11 1425	MTH 19-Jan-2008		O/C			
245092 RIGHT	FUEL NZ014 PCB	*CF		6618714-11 1390A	MTH 19-Jan-2008		O/C			
245094	HYD NZ016 PCB	*CF		6618723-5 1375	MTH 19-Jan-2008		O/C			
245095	POS TAIL NZ017 PCB	*CF		6618721-1 0756	MTH 19-Jan-2008		O/C			
245096 LEFT	ANTI ICE NZ019 PCB	*CF		6618718-1 1387	MTH 19-Jan-2008		O/C			
245096 RIGHT	ANTI-ICE NZ018 PCB	*CF		6618718-1 1386	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
245098	RUDDER BIAS NZ029 PCB *CF			6618812-1 0765	MTH 19-Jan-2008		O/C			
245103	APU NZ025 PCB *CF			6618808-26 0461	MTH 19-Jan-2008		O/C			
245104	APU NZ026 PCB *CF			6618809-1 0715	MTH 19-Jan-2008		O/C			
245105	TAIL DEICE CONT NZ031 PCB *CF			6618730-1 0357	MTH 19-Jan-2008		O/C			
245106	TAIL DEICE MON NZ033 PCB *CF			6618731-1 0364	MTH 19-Jan-2008		O/C			
245107	MISCELLANEOUS NZ035 PCB *CF			6618732-1 0364	MTH 19-Jan-2008		O/C			
25-60-00-9600 NO. 10 <i>256001 : 10</i>	P01074-207 LIFE VEST (ACCOMPLISH SUPPLIER 120 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 10 KMCO			PO723E-105P 14110440008	MTH 10-Jul-2016		60 25		30-Jun-2019	5 m 21 d
					HRS 3318.1					
					LDG 3360					
					APUH 1533					
					APUS 3369					
25-60-00-9600 NO. 11 <i>256001 : 11</i>	NO. 11 LIFE JACKET KMCO			PO723E-105P 14110440006	MTH 10-Jul-2016		60 25		30-Jun-2019	5 m 21 d
					HRS 3318.1					
					LDG 3360					
					APUH 1533					
					APUS 3369					
25-60-00-9600 NO. 1 <i>256001 : 1</i>	P01074-207 LIFE VEST (ACCOMPLISH SUPPLIER 120 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 1 KMCO			PO723E-105P 14110440010	MTH 10-Jul-2016		60 25		30-Jun-2019	5 m 21 d
					HRS 3318.1					
					LDG 3360					
					APUH 1533					
					APUS 3369					
25-60-00-9600 NO. 2 <i>256001 : 2</i>	P01074-207 LIFE VEST (ACCOMPLISH SUPPLIER 120 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 2 ICT			P01074-207 12040090221	MTH 27-Jun-2012		120 2		30-Apr-2022	39 m 21 d
					HRS 1715					
					LDG 1393					
25-60-00-9600 NO. 3 <i>256001 : 3</i>	P01074-207 LIFE VEST (ACCOMPLISH SUPPLIER 120 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 3 KMCO			PO723E-105P 14110440003	MTH 10-Jul-2016		60 25		30-Jun-2019	5 m 21 d
					HRS 3318.1					
					LDG 3360					
					APUH 1533					
					APUS 3369					
25-60-00-9600 NO. 4 <i>256001 : 4</i>	P01074-207 LIFE VEST (ACCOMPLISH SUPPLIER 120 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 4 KMCO			PO723E-105P 14110440003	MTH 10-Jul-2016		60 25		30-Jun-2019	5 m 21 d
					HRS 3318.1					
					LDG 3360					
					APUH 1533					
					APUS 3369					
25-60-00-9600 NO. 5 <i>256001 : 5</i>	P01074-207 LIFE VEST (ACCOMPLISH SUPPLIER 120 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 5 KMCO			PO723E-105P 14110440005	MTH 10-Jul-2016		60 25		01-Dec-2019	10 m 22 d
					HRS 3318.1					
					LDG 3360					
					APUH 1533					
					APUS 3369					
25-60-00-9600 NO. 6 <i>256001 : 6</i>	P01074-207 LIFE VEST (ACCOMPLISH SUPPLIER 120 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 6 KMCO			PO723E-105P 14110440011	MTH 10-Jul-2016		60 25		30-Jun-2019	5 m 21 d
					HRS 3318.1					
					LDG 3360					
					APUH 1533					
					APUS 3369					
25-60-00-9600 NO. 7 <i>256001 : 7</i>	P01074-207 LIFE VEST (ACCOMPLISH SUPPLIER 120 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 7 KMCO			PO723E-105P 14110440004	MTH 10-Jul-2016		60 25		30-Jun-2019	5 m 21 d
					HRS 3318.1					
					LDG 3360					
					APUH 1533					
					APUS 3369					



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
25-60-00-9600 NO. 8 256001 : 8	P01074-207 LIFE VEST (ACCOMPLISH SUPPLIER 120 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 8	KMCO		PO723E-105P 14110440007	MTH 10-Jul-2016 HRS 3318.1 LDG 3360 APUH 1533 APUS 3369		60	25	30-Jun-2019	5 m 21 d
25-60-00-9600 NO. 9 256001 : 9	P01074-207 LIFE VEST (ACCOMPLISH SUPPLIER 120 MONTH MAINTENANCE INSPECTION) RESTORATION - NO. 9	KMCO		PO723E-105P 14110440009	MTH 31-Aug-2017 HRS 3826.6 LDG 3968 APUH 1794 APUS 4045		120	42	01-Dec-2019	10 m 22 d
25-60-10-9600 256003	ARTEX EMERGENCY LOCATOR TRANSMITTER BATTERY DISCARD	KMCO		452-0133 375075-019	MTH 31-Aug-2017 HRS 3826.6 LDG 3968 APUH 1794 APUS 4045		60	0	01-Oct-2022	44 m 22 d
250002	AV VISOR PLUS PROCESSOR BLL			90008-0031 43B00310	MTH 14-Jan-2009 HRS 536		O/C	0		
250003	AV VISOR DISPLAY	*CF	2	15004-00300 145606	MTH 19-Jan-2008		O/C			
251007 NO. 1	PBE MR10051N	KMCO		DP3113 E1705456	MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		120	0	31-Dec-2027	107 m 22 d
252003	TEMPERATURE PROBE *CF			102DB1AG A74482	MTH 19-Jan-2008		O/C			
252525	EXTERNALLY SERVICABLE TOILET EJA ONLY	KMCO		6619103-1 0091	MTH 17-Jul-2014 HRS 2385.8 LDG 2234		O/C	0 0 0		
256002	EMERGENCY LOCATOR TRANSMITTER C406N	*CF		453-5060 4196	MTH 19-Jan-2008		O/C			
256004	ELT ANTENNA	*CF		DMQ18-3 187052	MTH 19-Jan-2008		O/C			
26-21-01-9600 AFT/FWD 262003 : AL	13083-5 AND AE13083-5 AFT ENGINE FIRE EXTINGUISHER FORWARD CARTRIDGE SQUIB	KMCO		13083-5 09-2015	MTH 21-Aug-2016 HRS 3338.6 LDG 3371		108		30-Sep-2024	68 m 21 d
Manufacture Date: 30-Sep-2015										
26-21-01-9600 AFT REAR 262003 : AR	13083-5 AND AE13083-5 AFT ENGINE FIRE EXTINGUISHER AFT CARTRIDGE SQUIB DISCARD	KMCO		13083-5 09-2015	MTH 21-Aug-2016 HRS 3338.6 LDG 3371		108		30-Sep-2024	68 m 21 d
Manufacture Date: 30-Sep-2015										
26-21-01-9600 FORWARD/FORW ARD 262003 : FL	13083-5 AND AE13083-5 FORWARD ENGINE FIRE EXTINGUISHER FORWARD CARTRIDGE SQUIB	KMCO		13083-5 18C710-001	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		108		31-May-2027	100 m 22 d
Manufacture Date: 26-May-2018										
26-21-01-9600 FWD REAR 262003 : FR	13083-5 AND AE13083-5 FORWARD ENGINE FIRE EXTINGUISHER AFT CARTRIDGE SQUIB DISCARD	KMCO		13083-5 18C710-001	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		108		31-May-2027	100 m 22 d
Manufacture Date: 26-May-2018										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
26-21-01-9601 262003 : APU	13083-5 AND AE13083-5 AUXILIARY POWER UNIT FIRE EXTINGUISHER CARTRIDGE SQUIB DISCARD - MAX LIFE	KMCO		13083-5 18C710-001	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		108		31-May-2027	100 m 22 d
Manufacture Date: 26-May-2018										
261002 LEFT	ENGINE FIRE DETECT (UT021) CONTROL UNIT 9912036-12	*CF		377-02838 0734510	MTH 19-Jan-2008		O/C			
261002 RIGHT	ENGINE FIRE DETECT (UT020) CONTROL UNIT 9912036-12	*CF		377-02838 0734509	MTH 19-Jan-2008		O/C			
262001 AFT	ENGINE FIRE BOTTLE 9914513-3	KMCO		30400037-1 54573B1	MTH 21-Aug-2016 HRS 3338.6 LDG 3371		O/C	5 0		
262001 APU	FIRE BOTTLE 9914513-3	*CF		30100033 46780A1	MTH 19-Jan-2008		O/C	0		
262001 FORWARD	ENGINE FIRE BOTTLE 9914513-3	*CF		30400037-1 55423B1	MTH 19-Jan-2008		O/C	0		
262002 CABIN	PORTABLE HALON FIRE EXTINGUISHER 9912625-13	KMCO		C352CS D-00397463	MTH 30-Jun-2017 HRS 3749.2 LDG 3889		O/C	7 0		
262002 COCKPIT	PORTABLE HALON FIRE EXTINGUISHER 9912625-13	KMCO		C352CS D-00397605	MTH 30-Jun-2017 HRS 3749.2 LDG 3889		O/C	0 0		
272001	RUDDER BIAS SHUTOFF VALVE 9912625-13	*CF		5307-1 1194C	MTH 19-Jan-2008		O/C			
272002 LEFT	STICK SHAKER (MC001) UNIT 9912625-13	*CF	A	201 7715	MTH 19-Jan-2008		O/C			
272002 RIGHT	STICK SHAKER (MF004) UNIT 9912625-13	*CF	A	201 7716	MTH 19-Jan-2008		O/C			
272003	RUDDER BIAS ACTUATOR 9912625-13	*CF		6660613-12 NSN	MTH 19-Jan-2008		O/C			
273004	SERVO ACTUATOR 9912625-13	*CF		44430-3739 T772	MTH 19-Jan-2008		O/C			
273020	AFT ELEVATOR TRIM CABLE ASSEMBLY 9912625-13			PN SN-UNKNOWN	MTH 19-Jan-2008 HRS 0		4800	0	4800	251.4
273201	ELEV TRIM SWITCH 9912625-13	*CF		8-405-04 B63162	MTH 19-Jan-2008		O/C			
274000	HORIZONTAL STABILIZER ACTUATOR 9912548-7	MCO		41011680-108 1095	MTH 03-Nov-2014 HRS 2566.9 LDG 2468		O/C	0		
274001	HYDRAULIC MANIFOLD ASSEMBLY 9912625-19	*CF		8244-2 0256	MTH 19-Jan-2008		O/C			
274013	HORIZONTAL STABILIZER ISOLATION (UY015) VALVE 9912625-13	*CF		4220-1 0265	MTH 19-Jan-2008		O/C			
274044	HORIZONTAL STAB VALVE ASSY 9912625-12	*CF		4218-1 0258	MTH 19-Jan-2008		O/C			
275001	FLAP CONTROL (UY024) VALVE 9912625-5	*CF		4216-3 0250	MTH 19-Jan-2008		O/C			
275003 LEFT	FLAP ACTUATOR 9912007-1	*CF		1535000-1 2468	MTH 19-Jan-2008		O/C			
275003 RIGHT	FLAP ACTUATOR 9912007-1	*CF		1535000-1 2647	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
276001 LEFT	SPEED BRAKE ACTUATOR 9912344-1	*CF		1535500-1 3418	MTH 19-Jan-2008		O/C			
276001 RIGHT	SPEED BRAKE ACTUATOR 9912344-1	*CF		1535500-1 3430	MTH 19-Jan-2008		O/C			
276002	SPEED BRAKE CONTROL VALVE 9912625-6	*CF		4216-2 0255	MTH 19-Jan-2008		O/C			
276003	SPEED BRAKE SAFETY VALVE 9912625-7	*CF		4217-1 0078	MTH 19-Jan-2008		O/C			
280003 LEFT	FUEL RELIEF VALVE ASSY 9912501-2	*CF		840203-105 4691XPR	MTH 19-Jan-2008		O/C			
280003 RIGHT	FUEL RELIEF VALVE ASSY 9912501-2	*CF		840203-105 4855XPR	MTH 19-Jan-2008		O/C			
280004 LEFT	HIGH LVL FUEL VALVE 9914107-1	*CF		61087 4719	MTH 19-Jan-2008		O/C			
280004 RIGHT	HIGH LVL FUEL VALVE 9914107-1	*CF		61087 4718	MTH 19-Jan-2008		O/C			
281101 LEFT	FUEL VENT FLOAT VALVE 9914268-5	*CF		60221-4 1741	MTH 19-Jan-2008		O/C			
281101 RIGHT	FUEL VENT FLOAT VALVE 9914268-5	*CF		60221-4 1764	MTH 19-Jan-2008		O/C			
282011 LEFT AFT	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 3977	MTH 19-Jan-2008		O/C			
282011 LEFT FORWARD	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 3739	MTH 19-Jan-2008		O/C			
282011 LEFT MID	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 3748	MTH 19-Jan-2008		O/C			
282011 RIGHT AFT	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 4055	MTH 19-Jan-2008		O/C			
282011 RIGHT FORWARD	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 4051	MTH 19-Jan-2008		O/C			
282011 RIGHT MID	SCAVENGE FUEL EJECTOR PUMP 9912483-2	*CF		2950024-101 4052	MTH 19-Jan-2008		O/C			
282012 LEFT 282012A : L	FUEL BOOST CARTRIDGE 9914421-4	*CF		LR55505-2 D1483	MTH 19-Jan-2008		O/C			
282012 LEFT WING	BOOST FUEL ELECTRIC PUMP 9914421-4	*CF		LR55540B B1407	MTH 19-Jan-2008		O/C			
282012 RIGHT 282012A : R	FUEL BOOST CARTRIDGE 9914421-4	*CF		LR55505-2 D1482	MTH 19-Jan-2008		O/C			
282012 RIGHT WING	BOOST FUEL ELECTRIC PUMP 9914421-4	*CF		LR55540B B1406	MTH 19-Jan-2008		O/C			
282013 LEFT WING	PRIMARY MOTIVE FLOW EJECTOR PUMP 9912483-1	*CF		2950023-101 1379	MTH 19-Jan-2008		O/C			
282013 RIGHT WING	PRIMARY MOTIVE FLOW EJECTOR PUMP 9912483-1	*CF		2950023-101 1389	MTH 19-Jan-2008		O/C			
282014	FUEL CROSSFEED ACTUATOR 9914423-2	*CF		MA20A1029-1 AA69428	MTH 19-Jan-2008		O/C			
282100 LEFT WING	SINGLE PT REFUEL/DEFUEL SHUTOFF VALVE 9914423-2	*CF		80002-101 2035	MTH 19-Jan-2008		O/C			
282100 RIGHT WING	SINGLE PT REFUEL/DEFUEL SHUTOFF VALVE 9914423-2	*CF		80002-101 2041	MTH 19-Jan-2008		O/C			
282106	FUEL CROSSFEED VALVE 9914423-4	*CF		125838AW AA1000287	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
282108 LEFT	MOTIVE FLOW SHUTOFF (UY009) VALVE *CF			4151 1305	MTH 19-Jan-2008		O/C			
282108 RIGHT	MOTIVE FLOW SHUTOFF (UY008) VALVE *CF			4151 1288	MTH 19-Jan-2008		O/C			
282118 LEFT	FUEL SHUT-OFF VALVE 9914094-1 *CF			71498 AA105000	MTH 19-Jan-2008		O/C			
282118 RIGHT	FUEL SHUT-OFF VALVE 9914094-1 *CF			71498 AA104988	MTH 19-Jan-2008		O/C			
282200 LEFT	LOW LEVEL VALVE ASSY *CF			726400-1 1317	MTH 19-Jan-2008		O/C			
282200 RIGHT	LOW LEVEL VALVE ASSY *CF			726400-1 1319	MTH 19-Jan-2008		O/C			
282201	VALVE-REFUEL/DEFUEL *CF			9036-351-2 1466	MTH 19-Jan-2008		O/C			
282202 LEFT	FUEL VALVE ASSY *CF			750800-2 1398	MTH 19-Jan-2008		O/C			
282202 RIGHT	FUEL VALVE ASSY *CF			750800-2 1399	MTH 19-Jan-2008		O/C			
284012 LEFT	LOW FUEL LEVEL SENSOR 9914427-2 *CF			GIF5400-43 2718	MTH 19-Jan-2008		O/C			
284012 RIGHT	LOW FUEL LEVEL SENSOR 9914427-2 *CF			GIF5400-43 2731	MTH 19-Jan-2008		O/C			
284013 LEFT WING	FUEL QTY W0 PROBE 9912498-8 *CF			10634T07Y00 MN12567	MTH 19-Jan-2008		O/C			
284013 RIGHT WING	FUEL QTY W0 PROBE 9912498-8 *CF			10634T07Y00 MN12097	MTH 19-Jan-2008		O/C			
284014 LEFT WING	FUEL QTY W1 PROBE 9912498-1 *CF			10634T02Y00 MN12044	MTH 19-Jan-2008		O/C			
284014 RIGHT WING	FUEL QTY W1 PROBE 9912498-1 *CF			10634T02Y00 MN12041	MTH 19-Jan-2008		O/C			
284015 LEFT WING	FUEL QTY W2 PROBE 9912498-2 *CF			10634T03Y00 MN12093	MTH 19-Jan-2008		O/C			
284015 RIGHT WING	FUEL QTY W2 PROBE 9912498-2 *CF			10634T03Y00 MN12568	MTH 19-Jan-2008		O/C			
284016 LEFT WING	FUEL QTY W3 PROBE 9912498-3 *CF			10634T04Y00 MN10485	MTH 19-Jan-2008		O/C			
284016 RIGHT WING	FUEL QTY W3 PROBE 9912498-3 *CF			10634T04Y00 MN11875	MTH 19-Jan-2008		O/C			
284017 LEFT WING	FUEL QTY W4 PROBE 9912498-4 *CF			10634T05Y00 MN02544	MTH 19-Jan-2008		O/C			
284017 RIGHT WING	FUEL QTY W4 PROBE 9912498-4 *CF			10634T05Y00 MN11926	MTH 19-Jan-2008		O/C			
284018 LEFT WING	FUEL QTY W5 PROBE 9912498-5 *CF			10634T01Y00 MN06867	MTH 19-Jan-2008		O/C			
284018 RIGHT WING	FUEL QTY W5 PROBE 9912498-5 *CF			10634T01Y00 MN10683	MTH 19-Jan-2008		O/C			
284019 LEFT WING	FUEL QTY W6 PROBE 9912498-6 *CF			10634T06Y00 MN11898	MTH 19-Jan-2008		O/C			
284019 RIGHT WING	FUEL QTY W6 PROBE 9912498-6 KMCO			10634T06Y00 MN44291	MTH 14-Aug-2018 HRS 4367.6 LDG 4465		O/C	0 0		
284196	FUEL QUANTITY SIGNAL CONDITIONER 9912498-7 *CF			10635B01Y01 07091370	MTH 19-Jan-2008		O/C			
291001	HYDRAULIC RESERVOIR 9912542-1 *CF			7470 894	MTH 19-Jan-2008		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
291002 LEFT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 5580	MTH 19-Jan-2008		O/C			
291002 RIGHT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 5591	MTH 19-Jan-2008		O/C			
291005 LEFT	HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 07124	MTH 19-Jan-2008		O/C			
291005 RIGHT	HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 07132	MTH 19-Jan-2008		O/C			
291008	SPEED BRAKE THERMAL RELIEF VALVE 9912625-8	*CF		2664 0132	MTH 19-Jan-2008		O/C			
291010	HYD PRESS SWITCH 9912625-3	*CF		80637 0752	MTH 19-Jan-2008		O/C			
291013 LEFT	FIREWALL HYD SHUTOFF VALVE *CF			AV24B1325C5 AA119881	MTH 19-Jan-2008		O/C			
291013 RIGHT	FIREWALL HYD SHUTOFF VALVE *CF			AV24B1325C5 AA1222204	MTH 19-Jan-2008		O/C			
301001 LEFT WING	ANTI-ICE BLEED AIR UNDER TEMP SL013 SWITCH *CF			1173T42-4 3442	MTH 19-Jan-2008		O/C			
301001 RIGHT WING	ANTI-ICE BLEED AIR UNDER TEMP SR016 SWITCH *CF			1173T42-4 3569	MTH 19-Jan-2008		O/C			
301002	ISOLATION VALVE 9912403-2	*CF		2602-36 1713	MTH 19-Jan-2008		O/C			
301008 LEFT	DEICE TAIL VALVE *CF			3D2353-06 N072243	MTH 19-Jan-2008		O/C			
301008 RIGHT	DEICE TAIL VALVE *CF			3D2353-06 N072612	MTH 19-Jan-2008		O/C			
301020	WINDSHIELD RAIN REMOVAL MN001 FAN *CF			011598-501 C07010198	MTH 19-Jan-2008		O/C			
301137 LEFT WING	INLET ANTI-ICE PRESSURE REG SHUTOFF VD001 VALVE 9912495-1	*CF		1962-00-7 3713	MTH 19-Jan-2008		O/C			
301137 RIGHT WING	INLET ANTI-ICE PRESSURE REG SHUTOFF VE002 VALVE 9912495-1	*CF		1962-00-7 3721	MTH 19-Jan-2008		O/C			
301201 LEFT	TAIL DEICE PRESSURE SV005 SWITCH *CF			1106P55-1 4189A	MTH 19-Jan-2008		O/C			
301201 RIGHT	TAIL DEICE PRESSURE SV004 SWITCH *CF			1106P55-1 4216A	MTH 19-Jan-2008		O/C			
301202 LEFT	HORIZ STAB DEICE BOOT KSF	KSF		P29S4D5280-11 NCH8110	MTH 04-Jun-2015 HRS 2829.6 LDG 2820		O/C	0 0 0		
301202 RIGHT	HORIZ STAB DEICE BOOT KSF	KSF		P29S4D5280-12 NCH6570	MTH 04-Jun-2015 HRS 2829.6 LDG 2820		O/C	0 0 0		
302101 LEFT	PRESSURE REG VALVE 9912495-4	*CF		1946-00-19 4393	MTH 19-Jan-2008		O/C			
302101 RIGHT	PRESSURE REG VALVE 9912495-4	*CF		1946-00-19 4396	MTH 19-Jan-2008		O/C			
302104 LEFT	NACELLE INLET SWITCH *CF			1173T0759 3687	MTH 19-Jan-2008		O/C			
302104 RIGHT	NACELLE INLET SWITCH *CF			1173T0759 4276	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
303001 LEFT	PITOT TUBE *CF	PH1100-1-VCW 799507	MTH 19-Jan-2008		O/C			
303001 RIGHT	PITOT TUBE *CF	PH1100-1-VCW 810307	MTH 19-Jan-2008		O/C			
303001 STANDBY	PITOT TUBE *CF	PH1100-1-RCDW 782504	MTH 19-Jan-2008		O/C			
304100 LEFT	WINDSHIELD CONTROLLER 9914411-2 *CF	856-1-3 207350004	MTH 19-Jan-2008		O/C			
304100 RIGHT	WINDSHIELD CONTROLLER 9914411-2 *CF	856-1-3 207350002	MTH 19-Jan-2008		O/C			
302005 E1	ANTI-ICING VALVE 31J2879-05 *CF	540-0406-5 4203	MTH 19-Jan-2008		O/C			
302005 E2	ANTI-ICING VALVE 31J2879-05 *CF	540-0406-5 4240	MTH 19-Jan-2008		O/C			
31-30-04-9600 313007A	FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY DISCARD 266-E0305-00 MCO	810-2007/K SD20536	MTH 23-Aug-2013 HRS 1932.6 LDG 1685	3	72	0	30-Nov-2019	10 m 21 d
312001 LEFT HAND	DIGITAL CLOCK *CF	M877A5V 18534	MTH 19-Jan-2008		O/C			
312002I	INCLINOMETER *CF	N55DMG2RXA 0706193	MTH 19-Jan-2008		O/C			
313001	FDR ACCELEROMETER KMCO	3001-01-111-3 1112DTM8167	MTH 04-Dec-2014 HRS 2601.1 LDG 2533		O/C	0 0		
313002	FDR MFDAU UNIT ICT	2231230-5A 01938	MTH 27-Jun-2012 HRS 1715 LDG 1393		O/C	0 0		
313003 LEFT	ENGINE ACCELEROMETER *CF	6222SM15 21088	MTH 19-Jan-2008		O/C			
313003 RIGHT	ENGINE ACCELEROMETER *CF	6222SM15 20915	MTH 19-Jan-2008		O/C			
313006	FLIGHT DATA RECORDER ICT	980-4700-025 16502	MTH 27-Jun-2012 HRS 1715 LDG 1393		O/C	0 0		
313007	FDR UNDERWATER LOCATOR BEACON MCO	DK120 SD20536	MTH 23-Aug-2013 HRS 1932.6 LDG 1685		O/C	0 0 0		
313008	FDR IMPACT SWITCH *CF	6895-D-1-X-5-5 7170	MTH 19-Jan-2008		O/C			
315001	FDR FAIL ANNUNCIATOR 9912504-17 *CF	1304-1-17 207430095	MTH 19-Jan-2008		O/C			
315101 LEFT	WARNING GEN/MIXER UNIT *CF	1287-1-2 207160053	MTH 19-Jan-2008		O/C			
315101 RIGHT	WARNING GEN/MIXER UNIT *CF	1287-1-2 207030023	MTH 19-Jan-2008		O/C			
316001	TILT INDICATOR *CF	3001J72 24107	MTH 19-Jan-2008		O/C			
32-10-00-9601 LEFT MAIN LANDING GEAR 321003 : L	LEFT MAIN LANDING GEAR TRUNNION SUBASSEMBLY DISCARD *CF	6641630-27 NSN	MTH 19-Jan-2008 LDG 0		33300	0	33300	28522
32-10-00-9601 RIGHT MAIN LANDING GEAR 321003 : R	RIGHT MAIN LANDING GEAR TRUNNION SUBASSEMBLY DISCARD *CF	6641630-28 NSN	MTH 19-Jan-2008 LDG 0		33300	0	33300	28522

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
32-10-00-9602 LEFT MAIN LANDING GEAR 321004 : L	LEFT MAIN LANDING GEAR TRAILING LINK ASSEMBLY DISCARD ICT			6641530-1 287	MTH 27-Jun-2012 HRS 1715 LDG 1393		33300	0	34693	29915
32-10-00-9602 RIGHT MAIN LANDING GEAR 321004 : R	RIGHT MAIN LANDING GEAR TRAILING LINK ASSEMBLY DISCARD *CF			6641530-2 NSN	MTH 19-Jan-2008 LDG 0		33300	0	33300	28522
32-10-00-9603 LEFT MAIN LANDING GEAR 321011 : L	LEFT MAIN LANDING GEAR TRAILING LINK SPACER DISCARD *CF			6641533-1 NSN	MTH 19-Jan-2008 LDG 0		33300	0	33300	28522
32-10-00-9603 RIGHT MAIN LANDING GEAR 321011 : R	RIGHT MAIN LANDING GEAR TRAILING LINK SPACER DISCARD *CF			6641533-1 NSN	MTH 19-Jan-2008 LDG 0		33300	0	33300	28522
32-10-00-9604.1 LEFT MAIN LANDING GEAR 323011 : L	LEFT UPPER CAP MAIN LANDING GEAR OLEO ASSEMBLY DISCARD KMCO			6641616-4 N/A	MTH 10-Dec-2015 HRS 3044.4 LDG 3068		14900	0	17968	13190
32-10-00-9604.1 RIGHT MAIN LANDING GEAR 323011 : R	RIGHT UPPER CAP MAIN LANDING GEAR OLEO ASSEMBLY DISCARD *CF			6641616-4 NSN	MTH 19-Jan-2008 LDG 0		14900	0	14900	10122
32-10-00-9604 LEFT MAIN LANDING GEAR 323010 : L	LEFT (EXCEPT UPPER CAP) MAIN LANDING GEAR OLEO ASSEMBLY DISCARD KMCO			6641615-6 643	MTH 10-Dec-2015 HRS 3044.4 LDG 3068		38000	3012	38056	33278
32-10-00-9604 RIGHT MAIN LANDING GEAR 323010 : R	RIGHT (EXCEPT UPPER CAP) MAIN LANDING GEAR OLEO ASSEMBLY DISCARD KMCO			6641615-6 640	MTH 29-Mar-2016 HRS 3176.1 LDG 3221		38000	3068	38153	33375
32-10-00-9605 LEFT MAIN LANDING GEAR 323001 : L	LEFT MAIN LANDING GEAR ACTUATOR ASSEMBLY DISCARD 9912537-3 *CF			1550000-3 1340	MTH 19-Jan-2008 LDG 0		70200	0	70200	65422
32-10-00-9605 RIGHT MAIN LANDING GEAR 323002 : R	RIGHT MAIN LANDING GEAR ACTUATOR ASSEMBLY DISCARD KMCO			1550000-6B 1371B	MTH 12-Nov-2016 HRS 3436.5 LDG 3517		70200	3426	70291	65513
32-20-00-9600 NOSE 322001	NOSE LANDING GEAR ASSEMBLY DISCARD *CF			6642614-1-5 26	MTH 19-Jan-2008 LDG 0		33300	0	33300	28522
32-20-00-9601 NOSE LANDING GEAR 323003	NOSE LANDING GEAR ACTUATOR DISCARD 9912491-5 KMCO			1549300-9 0712A	MTH 04-Feb-2018 HRS 4035.2 LDG 4216		33300	778	36738	31960
32-30-09-9600 323006	EMERGENCY PNEUMATIC STORAGE BOTTLE ASSEMBLY DISCARD 9912505-2 KMCO			40005347-3 5483	MTH 21-Dec-2018 HRS 4548.6 LDG 4775		288	139	31-May-2031	148 m 22 d
Manufacture Date: 01-May-2007										
322002 NOSE GEAR	SHIMMY DAMPER KMCO			5543001-12 217-12X	MTH 06-Jun-2014 HRS 2311.6 LDG 2145		O/C	1 0		
322007 NOSE GEAR	TRUNNION *CF			6642611-9 NSN	MTH 19-Jan-2008 LDG 0		O/C			
323004 LEFT	UPLOCK ACTUATOR *CF			5527504-3 3892	MTH 19-Jan-2008 LDG 0		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code	Description	City	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
323004 NOSE	UPLOCK ACTUATOR	*CF	5527504-3 3918	MTH 19-Jan-2008		O/C			
323004 RIGHT	UPLOCK ACTUATOR	*CF	5527504-3 3869	MTH 19-Jan-2008		O/C			
323005	PRESSURE EMER GEAR GAUGE	*CF	19940929-1 022938	MTH 19-Jan-2008		O/C			
323007	LANDING GEAR CONTROL (VY047) VALVE	*CF	9912625-9 4219-1 0252	MTH 19-Jan-2008		O/C			
323008	DUMP VALVE	*CF	9912625-11 9615 0270	MTH 19-Jan-2008		O/C			
323009	LANDING GEAR CONTROL	*CF	049801-001 9912550-1 24107	MTH 19-Jan-2008		O/C			
323014 323010A	LOADING VALVE	*CF	4215-2 9912625-18 0153	MTH 19-Jan-2008		O/C			
324001 LEFT	MAIN WHEEL ASSEMBLY	KMCO	3-1571-6 9912487-11 3139	MTH 10-Jul-2016 HRS 3318.1 LDG 3360		O/C			
324001 RIGHT	MAIN WHEEL ASSEMBLY	KMCO	3-1571-6 9912487-11 2114	MTH 10-Jul-2016 HRS 3318.1 LDG 3360		O/C			
324002 NOSE	WHEEL ASSEMBLY	KMCO	3-1418-OPT2 8754	MTH 04-Feb-2018 HRS 4035.2 LDG 4216		O/C			
324003 LEFT	MAIN BRAKE ASSEMBLY	KMCO	2-1601 9912487-7 0613	MTH 10-Dec-2015 HRS 3044.4 LDG 3068		O/C	2 0		
324004 RIGHT	MAIN BRAKE ASSEMBLY	KMCO	2-1601 9912487-7 0585	MTH 10-Dec-2015 HRS 3044.4 LDG 3068		O/C	1 0		
324005 LEFT	MAIN TIRE	KMCO	M13702 9912488-3 7298S229	MTH 10-Oct-2018 HRS 4476.5 LDG 4682		O/C	0 0 0		
324005 RIGHT	MAIN TIRE	KMCO	M13702 9912488-3 7347S215	MTH 10-Oct-2018 HRS 4476.5 LDG 4682		O/C	0 0 0		
324006	NOSE TIRE	KMCO	031-613-8 9914070-1 8061S00487	MTH 15-Nov-2018 HRS 4523.4 LDG 4753		O/C	0 0 0		
324009	POWER BRAKE VALVE	BLL	32-105-3 9912627-6 230	MTH 07-Nov-2011 HRS 1552 LDG 1270		O/C	0 0 0		
324010 LEFT	EXTEND/RETRACT VALVE	*CF	98120 4048	MTH 19-Jan-2008		O/C			
324010 NOSE	EXTEND/RETRACT VALVE	*CF	98120 4231	MTH 19-Jan-2008		O/C			
324010 RIGHT	EXTEND/RETRACT VALVE	*CF	98120 3983	MTH 19-Jan-2008		O/C			
324014	EMERGENCY AIR BRAKE CONTROL VALVE	*CF	65830-4 1033	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324015 LEFT	BRAKE SHUTTLE VALVE EKBI			211-114 1068	MTH 08-Jul-2011 HRS 1442 LDG 1174		O/C	0 0		
324015 RIGHT	BRAKE SHUTTLE VALVE EKBI			211-114 618	MTH 08-Jul-2011 HRS 1442 LDG 1174		O/C	0 0		
324019	BRAKE PRESS PUMP ASSEMBLY 9912166-3 *CF			640931 6722	MTH 19-Jan-2008		O/C			
324020	ANTISKID CONTROL (UY009) VALVE 9912489-4 *CF			39-837 979	MTH 19-Jan-2008		O/C			
324022	ANTISKID DIGITAL CONTROL 9912489-9 *CF			42-985-2 675	MTH 19-Jan-2008		O/C			
324023	POWER BRAKE ACCUMULATOR 9912644-1 *CF			7551-1 0108	MTH 19-Jan-2008		O/C			
324024 LEFT	WHEEL TRANSDUCER 9912305-2 MCO			40-955 5880	MTH 25-Oct-2014 HRS 2551.3 LDG 2446		O/C	2 0		
324024 RIGHT	WHEEL TRANSDUCER 9912305-2 KMCO			40-955 7088	MTH 08-Mar-2017 HRS 3589.2 LDG 3691		O/C	4 0		
324025	PRESSURE (SN011) SWITCH *CF			GPP1250-52 0724931	MTH 19-Jan-2008		O/C			
324026	POWER PACK MOTOR *CF			MP50B1 3704	MTH 19-Jan-2008		O/C			
324027	ANTISKID FAULT DISPLAY 9912305-9 *CF			42-92750 2135A	MTH 19-Jan-2008		O/C			
324101	PARKING BRAKE VALVE 9912388-11 *CF			98433-2 0212	MTH 19-Jan-2008		O/C			
324153 3242153	PRESS ANTISKID BRK SWITCH *CF			GPP1250-73 0741694	MTH 19-Jan-2008		O/C			
324200 324201	ANTISKID PRESSURE GAUGE *CF			19940929-1 023848	MTH 19-Jan-2008		O/C			
324206	ANTISKID HYD RELIEF VALVE *CF			1785-2 954	MTH 19-Jan-2008		O/C			
325001	NOSE STEERING BUNGEE ASSEMBLY KOPF			6642643-8 N/A	MTH 13-Jul-2017 HRS 3760.5 LDG 3904		O/C	0 0 0		
326005 LEFT	MAIN GEAR UP & LOCKED (S3) SWITCH *CF			65-430087 NSN	MTH 19-Jan-2008		O/C			
326005 RIGHT	MAIN GEAR UP & LOCKED (S3) SWITCH *CF			65-430087 NSN	MTH 19-Jan-2008		O/C			
326005	NOSE GEAR UP & LOCKED (SN001) SWITCH *CF			65-430087 NSN	MTH 19-Jan-2008		O/C			
331001 CENTER	5 VDC UN004 DIMMER POWER SUPPLY MCO			273-1 4622	MTH 26-Oct-2015 HRS 2996.8 LDG 3019 APUH 1378.2 APUS 3056		O/C			
331001 LEFT	5 VDC UN002 DIMMER POWER SUPPLY *CF			273-1 207130010	MTH 19-Jan-2008		O/C			
331001 RIGHT	5 VDC UN006 DIMMER POWER SUPPLY *CF			273-1 207150089	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
331011	EL PANEL INVERTER			EM2044-1 4988A	MTH 19-Jan-2008		O/C			
		*CF								
331099	EL PANEL	KMCO		9912532-4 1602	MTH 03-May-2018 HRS 4196.4 LDG 4380		O/C	0 0 0		
332002	GLARESHIELD INVERTER			6900173 4188	MTH 19-Jan-2008		O/C			
		*CF								
334001	PULSE LITE CONTROL			2401C TR01173	MTH 19-Jan-2008		O/C			
		*CF								
334002	EMPENNAGE LIGHT ASSY			01-0790044-37 NSN	MTH 19-Jan-2008		O/C			
		*CF								
334003	TAIL LIGHT ASSY	KMCO		01-0770966-00 05402A	MTH 17-Jul-2015 HRS 2876.4 LDG 2881		O/C	0 0		
334006 LEFT	STROBE POWER SUPPLY	KMCO		01-0771120-00 00844	MTH 08-Nov-2013 HRS 2017.2 LDG 1794		O/C	0 0		
334006 RIGHT	STROBE POWER SUPPLY	KMCO		01-0771120-00 00842	MTH 08-Nov-2013 HRS 2017.2 LDG 1794		O/C	0 0		
335001 AFT	EMERGENCY LIGHTING UC020 BATTERY PACK	KMCO		9913-1 363	MTH 30-Jun-2017 HRS 3749.2 LDG 3889		O/C			
335001 FORWARD	EMERGENCY LIGHTING UC019 BATTERY PACK	KMCO		9913-1 2926	MTH 30-Jun-2017 HRS 3749.2 LDG 3889		O/C			
24-32-00-9600 STANDBY 342064S	SECURAPLANE BATTERY DISCARD	KMCO	2	100-2410-04 1127015	MTH 10-Jul-2016 HRS 3318.1 LDG 3360 APUH 1533 APUS 3369		48	0	31-Jul-2020	18 m 22 d
340037	MAGNETOMETER MAG-3000A	*CF		501-1826-03 2137	MTH 19-Jan-2008		O/C			
341009	SAFE FLIGHT AOA UF004 SENSOR	*CF		C-12717-1 1933	MTH 19-Jan-2008		O/C			
341011	SAFE FLIGHT AOA UC009 COMPUTER	*CF		C13006-3 1301	MTH 19-Jan-2008		O/C			
341014	SAFE FLIGHT AOA FI003 INDEXER	*CF		C12763-1 1223	MTH 19-Jan-2008		O/C			
341016 SECONDARY	ADU UF-031	*CF		501-1890-02 2384	MTH 19-Jan-2008		O/C			
341017	MEGGITT SECONDARY FLIGHT (EI016) DISPLAY	*CF	19	501-1741-2103 1808A	MTH 19-Jan-2008		O/C			
341101	DIFFERENTIAL PRESSURE SWITCH	*CF		D45C-24 1059	MTH 19-Jan-2008		O/C			
341107 NO. 1	(PILOT) AIR DATA COMPUTER	*CF	G	7030700-71703 07081582	MTH 19-Jan-2008		O/C			
341107 NO. 2	(COPILOT) AIR DATA COMPUTER	*CF	G	7030700-71703 07081583	MTH 19-Jan-2008		O/C			
342023	RADAR CONTROLLER WC-880	KMCO		7008471-407 97123197	MTH 08-Mar-2013 HRS 1786 LDG 1482		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342050 LEFT	FLUX DETECTOR FX-220	*CF		2594484 0706H914	MTH 19-Jan-2008		O/C			
342050 RIGHT	FLUX DETECTOR FX-220	*CF		2594484 0706H910	MTH 19-Jan-2008		O/C			
342053	AERONETICS HSI-15 STANDBY HORIZONTAL SITUATION INDICATOR HSI-315B	*CF	4	520-3151-003 25004	MTH 19-Jan-2008		O/C			
342065 NO. 1	AHRS 1 BATTERY PACK PS-855		9	501-1712-02 81826	MTH 04-Dec-2014 LDG 2533		O/C	HRS 2601.1		
342069	HONEYWELL PRIMUS 1000 EFIS MC800 MULTIFUNCTION DISPLAY CONTROLLER KTPA		A-C	7007062-987 07033371	MTH 16-Mar-2018 LDG 4279		O/C	HRS 4116.7		
342082 LEFT	LITEF LCR-93 AHRS TRAY *CF			140691 4500	MTH 19-Jan-2008		O/C			
342082 RIGHT	LITEF LCR-93 AHRS TRAY *CF			140691 4535	MTH 19-Jan-2008		O/C			
342083 LEFT	AHRS COMPUTER MCO			142185-1100 1860	MTH 30-Aug-2016 LDG 3387		O/C	HRS 3347.9		
342083 RIGHT	AHRS COMPUTER KTPA			142185-1100 1508	MTH 22-Sep-2016 LDG 3412 APUH 1561.7 APUS 3415		O/C	HRS 3368.9		
342104 LEFT	MSU CALIBRATION PROM UNIT *CF			124282 6606	MTH 19-Jan-2008		O/C			
342104 RIGHT	MSU CALIBRATION PROM UNIT *CF			124282 10024	MTH 19-Jan-2008		O/C			
342500	HONEYWELL PRIMUS 1000 EFIS RI553 REMOTE INSTRUMENT CONTROLLER RI-553	*CF		7016954-971 07092927	MTH 19-Jan-2008		O/C			
342504 COPILOT	HONEYWELL PRIMUS 1000 EFIS DC550 DISPLAY CONTROLLER *CF		M	7016986-759 07097029	MTH 19-Jan-2008		O/C			
342504 PILOT	HONEYWELL PRIMUS 1000 EFIS DC550 DISPLAY CONTROLLER *CF		M	7016986-759 07066903	MTH 19-Jan-2008		O/C			
342505 NO.1	HONEYWELL PRIMUS 1000 EFIS IC600/IC615 INTEGRATED AVIONICS COMPUTER IC-615		AT	7017000-96814 07037942	MTH 10-Jul-2016 LDG 3360 APUH 1533 APUS 3369		O/C	HRS 3318.1		
342505 NO.2	HONEYWELL PRIMUS 1000 EFIS IC600/IC615 INTEGRATED AVIONICS COMPUTER IC-615	*CF	AE	7017000-97814 07088176	MTH 19-Jan-2008		O/C			
342506 LEFT	AP/FD MODE SELECTOR MS-560		KMCO	7018341-803 98031185	MTH 08-Mar-2017 LDG 3691		O/C	2 0		
342506 RIGHT	AP/FD MODE SELECTOR MS-560	*CF		7018341-803 07093080	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342509 COPILOT 342501 : R	HONEYWELL PRIMUS 1000 EFIS DU870 MULTIFUNCTION DISPLAY UNIT DU-1080	MCO		7037625-15001 07110403	MTH 13-Mar-2014 HRS 2176.4 LDG 1972		O/C			
342509 PILOT 342501 : L	HONEYWELL PRIMUS 1000 EFIS DU870 MULTIFUNCTION DISPLAY UNIT DU-1080	*CF		7037625-15001 07090350	MTH 19-Jan-2008		O/C			
342510 CENTER 342501 : CNTR	ELECTRONIC DISPLAY UNIT DU-1080	KMCO		7037625-15001 17121032	MTH 09-Mar-2018 HRS 4111.3 LDG 4270		O/C	0 0		
342613 342501	HONEYWELL PRIMUS 1000 EFIS RI552 REVERSION CONTROLLER RI-552	KTPA		7016954-981 07102976	MTH 16-Mar-2018 HRS 4116.7 LDG 4279		O/C			
343001 NAVIGATION 343001A	ANTENNA COUPLER *CF			CI-120-5 131352	MTH 19-Jan-2008		O/C			
343001	GLIDESLOPE ANTENNA COUPLER *CF			CI503 202343	MTH 19-Jan-2008		O/C			
343002 343001 : B	MARKER BEACON ANTENNA COUPLER *CF			CI509 196372	MTH 19-Jan-2008		O/C			
344005	RADAR TRANSCEIVER WU-880	KMCO	P	7021450-801 07087716	MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		O/C			
344022	RADIO ALTIMETER ALT-55B TRANSCEIVER RT-300	*CF		7001840-936 0709E067	MTH 19-Jan-2008		O/C			
344023 AFT	RADIO ALT RECEIVER ANTENNA *CF			S67-2002 54341601	MTH 19-Jan-2008		O/C			
344023 FORWARD	RADIO ALT TRANSMITTER ANTENNA *CF			S67-2002 54341605	MTH 19-Jan-2008		O/C			
344024	EGPWS COMPUTER S2800-702	*CF	10	965-0976-040-219-219MTH 26421	19-Jan-2008		O/C			
345004 LEFT NO. 1	XPNDR BOTTOM ANTENNA *CF			DMNI50-2-2 114646	MTH 19-Jan-2008		O/C			
345004 RIGHT NO. 2	XPNDR BOTTOM ANTENNA *CF			DMNI50-2-2 114647	MTH 19-Jan-2008		O/C			
345005 LEFT NO. 1	TOP TRANSPONDER DIVERSITY ANTENNA 85226	*CF		DMNI50-2-2 114639	MTH 19-Jan-2008		O/C			
345005 RIGHT NO. 2	TOP TRANSPONDER DIVERSITY ANTENNA 85226	*CF		DMNI50-2-2 1146617	MTH 19-Jan-2008		O/C			
345007 NO.1	DISTANCE MEASURING EQUIPMENT (DME) ANTENNA 85226	*CF		DMNI50-2-2 115304	MTH 19-Jan-2008		O/C			
345007 NO.2	DISTANCE MEASURING EQUIPMENT (DME) ANTENNA 85226	*CF		DMNI50-2-2 115085	MTH 19-Jan-2008		O/C			
345011 NO. 1	ADF RECEIVER MODULE DF-850	*CF	K	7510114-901 0707C041	MTH 19-Jan-2008		O/C			
345011 NO. 2	ADF RECEIVER MODULE DF-850	*CF	K	7510114-901 0708C202	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345014 NO. 1	ADF ANTENNA AT-860	KMCO		7510300-901 1807Q710	MTH 15-Nov-2018 HRS 4523.4 LDG 4753		O/C			
345015 NO. 2	ADF ANTENNA AT-860	*CF		7510300-901 0708C964	MTH 19-Jan-2008		O/C			
<i>345014 : 2</i>										
345017	MARKER BEACON ANTENNA *CF			MB10-754 0716	MTH 19-Jan-2008		O/C			
345018	GLIDESLOPE ANTENNA *CF			RGS10-48 12646	MTH 19-Jan-2008		O/C			
345029 NO. 1	NAV CLUSTER MODULE XN-850	*CF	E	7510164-921 0708B345	MTH 19-Jan-2008		O/C			
345029 NO. 2	NAV CLUSTER MODULE XN-850	*CF	E	7510164-921 0709B374	MTH 19-Jan-2008		O/C			
345032 NO. 1	VHF NAV RECEIVER NV-850	*CF	T	7510134-731 0708B399	MTH 19-Jan-2008		O/C			
345032 NO. 2	VHF NAV RECEIVER NV-850	*CF	T	7510134-731 0709B401	MTH 19-Jan-2008		O/C			
345034 NO. 1	ATC TRANSPONDER	KMCO	Z	7517400-922 05089525	MTH 10-Dec-2015 HRS 3044.4 LDG 3068		O/C			
345034 NO. 2	ATC TRANSPONDER	KJAX	V,Z	7517400-922 97021228	MTH 29-Sep-2015 HRS 2965.2 LDG 2981		O/C			
345036 NO. 1	DME INTERROGATOR DM-850	*CF	M	7510184-902 0708C919	MTH 19-Jan-2008		O/C			
345036 NO. 2	DME INTERROGATOR DM-850	*CF	M	7510184-902 0708C925	MTH 19-Jan-2008		O/C			
345038 NO. 1	INTEGRATED NAV UNIT RNZ-850	*CF	AS	7510100-731 0708B330	MTH 19-Jan-2008		O/C			
345038 NO. 2	INTEGRATED NAV UNIT RNZ-850	*CF	AS	7510100-731 0709B350	MTH 19-Jan-2008		O/C			
345066	DATA INTERFACE UNIT UL-701 UNILINK	*CF	0	1068-00-000 435	MTH 19-Jan-2008		O/C			
345077	DATA TRANSFER UNIT DTU-100	*CF	2	1406-01-1 4728	MTH 19-Jan-2008		O/C			
345079 NO. 1	GPS FLT MGMT COMPUTER UNS-1ESP	KMCO	6	2019-41-201 840	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		O/C			
345079 NO. 2	GPS FLT MGMT COMPUTER UNS-1ESP	KMCO		2019-41-201 683	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		O/C			
345088 NO. 1	RADIO MANAGEMENT UNIT *CF		S	7013270-963 07095974	MTH 19-Jan-2008		O/C			
345088 NO. 2	RADIO MANAGEMENT UNIT BLL			7013270-963 04094493	MTH 25-Sep-2008 HRS 402		O/C	2141		
345093 NO.1	GPS ANTENNA ANTENNA	*CF		10706 12012	MTH 19-Jan-2008		O/C			
345093 NO.2	GPS ANTENNA ANTENNA	*CF		10705 12103	MTH 19-Jan-2008		O/C			
345201 LEFT	NAV ANTENNA DMN4-17/P	*CF		DMN4-17-1N 126619	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345201 RIGHT	NAV ANTENNA DMN4-17/P	*CF		DMN4-17-1N 126618	MTH 19-Jan-2008		O/C			
346001	TCAS PROCESSOR RT-951 (S3100-196)	*CF	A	7517900-55003 20009320	MTH 19-Jan-2008		O/C			
346002 BOTTOM	TCAS ANTENNA AT-910	*CF		7514081-910 ANE28130	MTH 19-Jan-2008		O/C			
346002 TOP	TCAS ANTENNA AT-910	*CF		7514081-910 ANE27605	MTH 19-Jan-2008		O/C			
35-01-01-9600 351006	OXYGEN BOTTLE ASSEMBLY (DISCARD) RESTORATION	MCO		804882-14 CO9040611-A	MTH 27-Feb-2014 HRS 2154.4 LDG 1952		180		30-Nov-2023	58 m 21 d
Manufacture Date: 27-Nov-2008										
35-10-00-9600 COPILOT 351004 : CP	MC10-16-150 AND MLD20-505 CO-PILOT CREW MASK (ACCOMPLISH SUPPLIER TESTING AND FAULT ISOLATION TASK) RESTORATION	MCO		MC10-16-150 S18769	MTH 23-Aug-2013 HRS 1932.6 LDG 1685		72	0	31-Aug-2019	7 m 22 d
35-10-00-9600 PILOT 351004 : P	MC10-16-150 AND MLD20-505 PILOT CREW MASK (ACCOMPLISH SUPPLIER TESTING AND FAULT ISOLATION TASK) RESTORATION	MCO		MC10-16-150 122811	MTH 23-Aug-2013 HRS 1932.6 LDG 1685		72	0	31-Aug-2019	7 m 22 d
351001	OXYGEN PRESSURE (EI002) GAGE MD-97	*CF		C668512-0101 G0710703	MTH 19-Jan-2008		O/C			
351007	OXYGEN REGULATOR	*CF		804881-01 C07050828	MTH 19-Jan-2008		O/C	0		
351008	PASSENGER OXYGEN CONTROL VALVE 9914067-19	*CF		P21006 2628	MTH 19-Jan-2008		O/C			
352001	PASSENGER OXYGEN ALTITUDE PRESSURE SWITCH	*CF		P24032 1309	MTH 19-Jan-2008		O/C			
361010	DOOR SOLENOID VALVE	KMCO		5035-00-1 2096	MTH 09-Mar-2018 HRS 4111.3 LDG 4270		O/C	0 0		
361011 LEFT	HEAT EXCHANGER ACTUATOR 9914519-4	*CF		1E50-2 10BC191	MTH 19-Jan-2008		O/C			
361011 RIGHT	HEAT EXCHANGER ACTUATOR 9914519-4	*CF		1E50-2 9BC176	MTH 19-Jan-2008		O/C			
361101 LEFT	BLEED AIR OVERTEMP (ST017) SWITCH 9914149-2	*CF		1173T181-2 6017	MTH 19-Jan-2008		O/C			
361101 RIGHT	BLEED AIR OVERTEMP (ST014) SWITCH 9914149-2	*CF		1173T181-2 6050	MTH 19-Jan-2008		O/C			
361102 LEFT	BLEED AIR MANIFOLD TEMPERATURE (TT001) SENSOR 9914519-2	*CF		1E51-1 9BC476	MTH 19-Jan-2008		O/C			
361102 RIGHT	BLEED AIR MANIFOLD TEMPERATURE (TT002) SENSOR 9914519-2	*CF		1E51-1 9BC475	MTH 19-Jan-2008		O/C			
361103 LEFT	HEAT B/A EXCHANGER 9912486-2	KMCO		8230-2 S4883T3275	MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		O/C	0 0		
361103 RIGHT	HEAT B/A EXCHANGER 9912486-2	KMCO		8230-2 S4883T3398	MTH 10-Oct-2018 HRS 4476.5 LDG 4682		O/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
361104 LEFT	PRECOOLER VD003 VALVE *CF	1406-7 0648	MTH 19-Jan-2008		O/C			
361104 RIGHT	PRECOOLER VD003 VALVE *CF	1406-8 0677	MTH 19-Jan-2008		O/C			
361208 APU	APU-CHECK VALVE 9914171-1 *CF	8C210 6807	MTH 19-Jan-2008		O/C			
361208	RUDDER BIAS CHECK VALVE 9914171-1 *CF	8C210 6642	MTH 19-Jan-2008		O/C			
361500 NO. 1	B/A CHECK VALVE 9914171-1 *CF	8C210 6815	MTH 19-Jan-2008		O/C			
361500 NO. 2	B/A CHECK VALVE 9914171-1 *CF	8C210 6794	MTH 19-Jan-2008		O/C			
361534	SERVICE AIR REGULATOR 9912510-1 *CF	1H75-18 7BC148	MTH 19-Jan-2008		O/C			
49APU1 490000	APU 9912484-1	3800722-1 P715	MTH 27-Dec-2017 LDG 4149		E/C	1898.5		
490001	APU ELECTRONIC CONTROL *CF	2119552-3 77L0165	19-Jan-2008		O/C			
490003	BLEED AIR SHUTOFF VALVE *CF	1413-7 0275	19-Jan-2008		O/C			
490004	DC AMMETER S3439-3 *CF	MD144-3 F0710045	19-Jan-2008		O/C			
490005	OVERHEAT DETECTOR 9912416-1 *CF	3001-212-1004/455-9 208093	19-Jan-2008		O/C			
490006	HOURLY METER *CF	C664503-0104 NSN	19-Jan-2008		O/C			
492003	COMPRESSOR ROTOR *CF	3822523-003 070350104740	APUS 19-Jan-2008 0		12000	0	12000	7171
492004	TURBINE ROTOR	3842340-2 17-156101-09263	APUH 14-Dec-2017 APUS 1898.5 4229		4000	0	8229	3400
493000	FUEL CONTROL ASSEMBLY KMCO	3883900-1 0601177	APUH 04-Feb-2018 APUS 1935 4282		O/C			
493001	TEE-FLOW DIVIDER VALVE *CF	3883921-2 NSN	19-Jan-2008		O/C			
493002	FUEL SHUT-OFF VALVE	PN SN-UNKNOWN	19-Jan-2008		O/C	0		
494000	ELECTRICAL IGNITER LEAD *CF	3888302-20 NSN	19-Jan-2008		O/C			
494001	IGNITER PLUG UNK	304634-2 SN-UNKNOWN	APUH 14-Dec-2017 APUS 1898.5 4229		O/C	0 0 0		
494002	IGNITION UNIT *CF	3888000-7 070218079630	19-Jan-2008		O/C			
497006	RPM/MAX INDICATOR *CF	M453 25578	19-Jan-2008		O/C			
499000	LOW OIL PRESSURE SWITCH *CF	3876351-1 070922701316	19-Jan-2008		O/C			
499001	LUBE PUMP ASSEMBLY *CF	3881825-1 P1239	19-Jan-2008		O/C			
499002	OIL LEVEL SWITCH *CF	3876318-3 070147000519	19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
521003	ACOUSTIC LOWER FWD SEAL KMCO			9522-15 NSN	MTH 20-May-2016 HRS 3269.6 LDG 3306		O/C	0 0		
521004	ACOUSTIC UPPER SEAL KMCO			9522-11 0660	MTH 15-Nov-2018 HRS 4523.4 LDG 4753		O/C	0 0		
521005	ACOUSTIC LOWER AFT SEAL KMCO			9522-15 0316	MTH 15-Nov-2018 HRS 4523.4 LDG 4753		O/C	0 0		
527000	EMERGENCY EXIT SWITCH KMCO			8-405-04 B81529	MTH 14-Aug-2018 HRS 4367.6 LDG 4465		O/C	0 0		
53-00-00-9600 LEFT NOSE LANDING GEAR <i>531001 : L</i>	LEFT NOSE LANDING GEAR TRUNNION SUPPORT ASSEMBLY DISCARD *CF			6613020-55 NSN	MTH 19-Jan-2008 LDG 0		25500	0	25500	20722
53-00-00-9600 RIGHT NOSE LANDING GEAR <i>531001 : R</i>	RIGHT NOSE LANDING GEAR TRUNNION SUPPORT ASSEMBLY DISCARD *CF			6613020-56 NSN	MTH 19-Jan-2008 LDG 0		25500	0	25500	20722
53-00-00-9601 NOSE GEAR <i>531002</i>	NOSE LANDING GEAR ACTUATOR FITTING ASSEMBLY DISCARD *CF			6611591-9 NSN	MTH 19-Jan-2008 LDG 0		25500	0	25500	20722
531201	RADOME ASSEMBLY KMCO			6613101-833 471	MTH 22-Dec-2014 HRS 2627.8 LDG 2583		O/C			
561001 LEFT	MAIN WINDSHIELD MCO			9914380-13 16225H2199	MTH 29-Dec-2016 HRS 3493.6 LDG 3584		O/C	0 0		
561001 RIGHT	MAIN WINDSHIELD KMCO			9914380-14 1729H9676	MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		O/C	0 0		
561004 LEFT	ELECTRICALLY HEATED COCKPIT FORWARD SIDE WINDOW 9914379-7	*CF		NP139722-7 07194H3142	MTH 19-Jan-2008		O/C			
561004 RIGHT	ELECTRICALLY HEATED COCKPIT FORWARD SIDE WINDOW 9914379-8	*CF		NP139722-8 07163H8913	MTH 19-Jan-2008		O/C			
561005 LEFT	OPENABLE COCKPIT AFT SIDE WINDOW 9914116-33	*CF		NP139703-3 2147	MTH 19-Jan-2008		O/C			
561005 RIGHT	OPENABLE COCKPIT AFT SIDE WINDOW 9914116-34	*CF		NP139703-4 2148	MTH 19-Jan-2008		O/C			
562001 LEFT NO. 2	CABIN WINDOW 9914159-12	*CF		167400-03 1216	MTH 19-Jan-2008		O/C			
562001 LEFT NO. 3	CABIN WINDOW 9914159-12	*CF		167400-03 1133	MTH 19-Jan-2008		O/C			
562001 LEFT NO. 4	CABIN WINDOW 9914159-12	*CF		167400-03 0814	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
562001 LEFT NO. 5	CABIN WINDOW 9914159-12	*CF		167400-03 1355	MTH 19-Jan-2008		O/C			
562001 LEFT NO. 6	CABIN WINDOW 9914159-12	*CF		167400-03 0958	MTH 19-Jan-2008		O/C			
562001 RIGHT NO. 1	EMERGENCY DOOR WINDOW 9914159-12	*CF		167400-03 0795	MTH 19-Jan-2008		O/C			
562001 RIGHT NO. 2	CABIN WINDOW 9914159-12	*CF		167400-03 0949	MTH 19-Jan-2008		O/C			
562001 RIGHT NO. 3	CABIN WINDOW 9914159-12	*CF		167400-03 0958	MTH 19-Jan-2008		O/C			
562001 RIGHT NO. 4	CABIN WINDOW 9914159-12	*CF		167400-03 0809	MTH 19-Jan-2008		O/C			
562001 RIGHT NO. 5	CABIN WINDOW 9914159-12	*CF		167400-03 1008	MTH 19-Jan-2008		O/C			
562001 RIGHT NO. 6	CABIN WINDOW 9914159-12	*CF		167400-03 0421	MTH 19-Jan-2008		O/C			
57-10-00-9600 LEFT MAIN LANDING GEAR <i>571001 : L</i>	LEFT MAIN LANDING GEAR FORWARD TRUNNION FITTING DISCARD *CF			6622123-1 NSN	MTH 19-Jan-2008 LDG 0		23800 0		23800	19022
57-10-00-9600 RIGHT MAIN LANDING GEAR <i>571001 : R</i>	RIGHT MAIN LANDING GEAR FORWARD TRUNNION FITTING DISCARD *CF			6622123-2 NSN	MTH 19-Jan-2008 LDG 0		23800 0		23800	19022
57-10-00-9601 LEFT MAIN LANDING GEAR <i>571002 : L</i>	LEFT MAIN LANDING GEAR AFT TRUNNION FITTING DISCARD *CF			6622124-1 NSN	MTH 19-Jan-2008 LDG 0		23800 0		23800	19022
57-10-00-9601 RIGHT MAIN LANDING GEAR <i>571002 : R</i>	RIGHT MAIN LANDING GEAR AFT TRUNNION FITTING DISCARD *CF			6622124-2 NSN	MTH 19-Jan-2008 LDG 0		23800 0		23800	19022
57-10-00-9602 LEFT MAIN LANDING GEAR <i>571003 : L</i>	LEFT MAIN LANDING GEAR ACTUATOR FITTING DISCARD *CF			6621125-5 NSN	MTH 19-Jan-2008 LDG 0		23800 0		23800	19022
57-10-00-9602 RIGHT MAIN LANDING GEAR <i>571003 : R</i>	RIGHT MAIN LANDING GEAR ACTUATOR FITTING DISCARD *CF			6621125-6 NSN	MTH 19-Jan-2008 LDG 0		23800 0		23800	19022
57-50-04-9600.1 LEFT WING LEFT INBOARD <i>275005 : LWLI</i>	LEFT WING LEFT INBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8) CF-2920 *CF			S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000 0		5000	222
57-50-04-9600.1 LEFT WING LEFT OUTBOARD <i>275005 : LWLO</i>	LEFT WING LEFT OUTBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8) CF-2920 *CF			S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000 0		5000	222
57-50-04-9600.1 LEFT WING RIGHT INBOARD <i>275005 : LWRI</i>	LEFT WING RIGHT INBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8) CF-2920 *CF			S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000 0		5000	222
57-50-04-9600.1 LEFT WING RIGHT OUTBOARD <i>275005 : LWRO</i>	LEFT WING RIGHT OUTBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8) CF-2920 *CF			S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000 0		5000	222
57-50-04-9600.1 RIGHT WING LEFT INBOARD <i>275005 : RWLI</i>	RIGHT WING LEFT INBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8) CF-2920 *CF			S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000 0		5000	222



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
57-50-04-9600.1 RIGHT WING LEFT OUTBOARD	RIGHT WING LEFT OUTBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8) CF-2920	*CF		S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000	0	5000	222
<i>275005 : RWLO</i>										
57-50-04-9600.1 RIGHT WING RIGHT INBOARD	RIGHT WING RIGHT INBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8) CF-2920	*CF		S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000	0	5000	222
<i>275005 : RWRI</i>										
57-50-04-9600.1 RIGHT WING RIGHT OUTBOARD	RIGHT WING RIGHT OUTBOARD FORWARD FLAP ROLLER DISCARD (S3049-5F8) CF-2920	*CF		S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000	0	5000	222
<i>275005 : RWRO</i>										
57-50-04-9600 LEFT WING LEFT INBOARD	LEFT WING LEFT INBOARD AFT FLAP ROLLER DISCARD (S3049-5F8) CF-2920	*CF		S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000	0	5000	222
<i>275004 : LWLI</i>										
57-50-04-9600 LEFT WING LEFT OUTBOARD	LEFT WING LEFT OUTBOARD AFT FLAP ROLLER DISCARD (S3049-5F8) CF-2920	*CF		S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000	0	5000	222
<i>275004 : LWLO</i>										
57-50-04-9600 LEFT WING RIGHT INBOARD	LEFT WING RIGHT INBOARD AFT FLAP ROLLER DISCARD (S3049-5F8) CF-2920	*CF		S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000	0	5000	222
<i>275004 : LWRI</i>										
57-50-04-9600 LEFT WING RIGHT OUTBOARD	LEFT WING RIGHT OUTBOARD AFT FLAP ROLLER DISCARD (S3049-5F8) CF-2920	*CF		S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000	0	5000	222
<i>275004 : LWRO</i>										
57-50-04-9600 RIGHT WING LEFT INBOARD	RIGHT WING LEFT INBOARD AFT FLAP ROLLER DISCARD (S3049-5F8) CF-2920	*CF		S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000	0	5000	222
<i>275004 : RWLI</i>										
57-50-04-9600 RIGHT WING LEFT OUTBOARD	RIGHT WING LEFT OUTBOARD AFT FLAP ROLLER DISCARD (S3049-5F8) CF-2920	*CF		S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000	0	5000	222
<i>275004 : RWLO</i>										
57-50-04-9600 RIGHT WING RIGHT INBOARD	RIGHT WING RIGHT INBOARD AFT FLAP ROLLER DISCARD (S3049-5F8) CF-2920	*CF		S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000	0	5000	222
<i>275004 : RWRI</i>										
57-50-04-9600 RIGHT WING RIGHT OUTBOARD	RIGHT WING RIGHT OUTBOARD AFT FLAP ROLLER DISCARD (S3049-5F8) CF-2920	*CF		S3049-5F8 NSN	MTH 19-Jan-2008 LDG 0		5000	0	5000	222
<i>275004 : RWRO</i>										
71-22-00-9600 LEFT	LEFT AFT ENGINE ISOLATOR MOUNT (METAL PARTS DETAILED INSPECTION AND SPECIAL DETAILED INSPECTION AND HOUSING BUSHING FUNCTIONAL CHECK) RESTORATION	*CF		LM451-SA2 LK1303	MTH 19-Jan-2008 HRS 0		10000	0	10000	5451.4
<i>712001 : L</i>										
71-22-00-9600 LEFT BOTTOM	LEFT BOTTOM FORWARD ENGINE ISOLATOR MOUNT (METAL PARTS DETAILED INSPECTION AND SPECIAL DETAILED INSPECTION AND HOUSING BUSHING FUNCTIONAL CHECK) RESTORATION	KMCO		9912480-1 LK2812	MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		10000	0	13977.6	9429
<i>712002 : LB</i>										
71-22-00-9600 LEFT UPPER	LEFT UPPER FORWARD ENGINE ISOLATOR MOUNT (METAL PARTS DETAILED INSPECTION AND SPECIAL DETAILED INSPECTION AND HOUSING BUSHING FUNCTIONAL CHECK) RESTORATION	KMCO		9912480-1 LK0653	MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		10000	0	13977.6	9429
<i>712002 : LT</i>										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
71-22-00-9600 RIGHT 712001 : R	RIGHT AFT ENGINE ISOLATOR MOUNT (METAL PARTS DETAILED INSPECTION AND SPECIAL DETAILED INSPECTION AND HOUSING BUSHING FUNCTIONAL CHECK) RESTORATION 9912480-2	*CF	LM451-SA2 LK1551	MTH 19-Jan-2008 HRS 0		10000	0	10000	5451.4
71-22-00-9600 RIGHT BOTTOM 712002 : RB	RIGHT BOTTOM FORWARD ENGINE ISOLATOR MOUNT (METAL PARTS DETAILED INSPECTION AND SPECIAL DETAILED INSPECTION AND HOUSING BUSHING FUNCTIONAL CHECK) RESTORATION 9912480-1	KMCO	LK1779	MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		10000	0	13977.6	9429
71-22-00-9600 RIGHT UPPER 712002 : RT	RIGHT UPPER FORWARD ENGINE ISOLATOR MOUNT (METAL PARTS DETAILED INSPECTION AND SPECIAL DETAILED INSPECTION AND HOUSING BUSHING FUNCTIONAL CHECK) RESTORATION 9912480-1	KMCO	LK1061	MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		10000	0	13977.6	9429
712005	ENG VIBRATION MONITOR 9912519-2	*CF	2789 010768	MTH 19-Jan-2008		O/C			
71EN1 NO. 1 710001 : E1**L	ENGINE KMCO		PW545B DD0529	MTH 04-Feb-2018 HRS 4035.2 LDG 4216		E/C			
71EN2 NO. 2 710001 : E2**R	ENGINE KMCO		PW545B DD0530	MTH 04-Feb-2018 HRS 4035.2 LDG 4216		E/C			
721010 E1	ACCESS GEARBOX SHAFT *CF		30J2201-01 RWA91A235	MTH 19-Jan-2008		O/C			
721010 E2	ACCESS GEARBOX SHAFT *CF		30J2201-01 RWA91A242	MTH 19-Jan-2008		O/C			
722001 E1	OIL PUMP ASSEMBLY *CF		30J2705-02 EC01A001A268	MTH 19-Jan-2008		O/C			
722001 E2	OIL PUMP ASSEMBLY *CF		30J2705-02 EC01A001A270	MTH 19-Jan-2008		O/C			
723010 E1	LP COMPRESSOR FAN ROTOR *CF		30J2681-01 A0028EY9	MTH 19-Jan-2008 LDG 67		15000	0	15067	10289
723010 E2	LP COMPRESSOR FAN ROTOR *CF		30J2681-01 A0028HMC	MTH 19-Jan-2008 LDG 67		15000	0	15067	10289
723020 E1	LP COMPRESSOR BOOST ROTOR *CF		30J2210-01 TXA1B3426	MTH 19-Jan-2008 LDG 67		13500	0	13567	8789
723020 E2	LP COMPRESSOR BOOST ROTOR *CF		30J2210-01 TXA1B3844	MTH 19-Jan-2008 LDG 67		13500	0	13567	8789
723030 E1	1ST STAGE HP COMPRESSOR ROTOR *CF		30J2821-01 A00286DD	MTH 19-Jan-2008 LDG 67		13500	0	13567	8789
723030 E2	1ST STAGE HP COMPRESSOR ROTOR *CF		30J2821-01 A00286DB	MTH 19-Jan-2008 LDG 67		13500	0	13567	8789
723040 E1	2ND STAGE HP COMPRESSOR ROTOR *CF		30J2429-01 A0028DPE	MTH 19-Jan-2008 HRS 47 LDG 67		5000 13500	0	5047 13567	498.4 8789
723040 E2	2ND STAGE HP COMPRESSOR ROTOR *CF		30J2429-01 A002818Y	MTH 19-Jan-2008 HRS 47 LDG 67		5000 13500	0	5047 13567	498.4 8789
723060 E1	CENTRIFUGAL IMPELLER *CF		30J1450-01 A00283K4	MTH 19-Jan-2008 LDG 67		13500	0	13567	8789
723060 E2	CENTRIFUGAL IMPELLER *CF		30J1450-01 A00283K3	MTH 19-Jan-2008 LDG 67		13500	0	13567	8789
724001 E1 INNER	COMBUSTION CHAMBER LINER *CF		30J2342-01 A002842P	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
724001 E1 OUTER	COMBUSTION CHAMBER LINER *CF			30J2590-01 A002838F	MTH 19-Jan-2008		O/C			
724001 E2 INNER	COMBUSTION CHAMBER LINER *CF			30J2342-01 A0028DFX	MTH 19-Jan-2008		O/C			
724001 E2 OUTER	COMBUSTION CHAMBER LINER *CF			30J2590-01 A002838M	MTH 19-Jan-2008		O/C			
725010 E1	1ST-STAGE TURBINE DISK *CF			30J1551-01 A00280FN	MTH 19-Jan-2008 LDG 67		13500	0	13567	8789
725010 E2	1ST-STAGE TURBINE DISK *CF			30J1551-01 A00280FX	MTH 19-Jan-2008 LDG 67		13500	0	13567	8789
725020 E1	2ND-STAGE TURBINE DISK *CF			30H3172 ABT00148	MTH 19-Jan-2008 LDG 67		13500	0	13567	8789
725020 E2	2ND-STAGE TURBINE DISK *CF			30H3152 MAA45503	MTH 19-Jan-2008 LDG 67		13500	0	13567	8789
725030 E1	3RD-STAGE TURBINE DISK *CF			30H3173 ABT00069	MTH 19-Jan-2008 LDG 67		13500	0	13567	8789
725030 E2	3RD-STAGE TURBINE DISK *CF			30H3153 MAA45046	MTH 19-Jan-2008 LDG 67		13500	0	13567	8789
725040 E1	4TH-STAGE TURBINE DISK *CF			30H3174 ABT00054	MTH 19-Jan-2008 LDG 67		13500	0	13567	8789
725040 E2	4TH-STAGE TURBINE DISK *CF			30H3154 MAA45221	MTH 19-Jan-2008 LDG 67		13500	0	13567	8789
733001 LEFT	FUEL FLOW TRANSMITTER 9914413-1 *CF			9-231-28 L9611	MTH 19-Jan-2008		O/C			
733001 RIGHT	FUEL FLOW TRANSMITTER 9914413-1 KMCO			9-231-28 L7987	MTH 03-Jan-2018 HRS 3985.7 LDG 4157		O/C	9 0		
733004 LEFT	FUEL PRESSURE SWITCH 9914112-3 *CF			6057-3 2575	MTH 19-Jan-2008		O/C			
733004 RIGHT	FUEL PRESSURE SWITCH 9914112-3 *CF			6057-3 2586	MTH 19-Jan-2008		O/C			
731002 E1	FLOW DIVIDER VALVE 30J2887-01 KMCO			1006479-1 F5492	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		O/C	0 0		
731002 E2	FLOW DIVIDER VALVE 30J2887-01 KMCO			1006479-1 F66460	MTH 08-Mar-2017 HRS 3617 LDG 3742		O/C			
731035 E1	FUEL FILTER ELEMENT			PN SN-UNKNOWN	MTH 19-Jan-2008		O/C	0		
731035 E2	FUEL FILTER ELEMENT			PN SN-UNKNOWN	MTH 19-Jan-2008		O/C	0		
731120 E1	EMERGENCY FUEL SHUTOFF VALVE			PN SN-UNKNOWN	MTH 19-Jan-2008		O/C	0		
731120 E2	EMERGENCY FUEL SHUTOFF VALVE			PN SN-UNKNOWN	MTH 19-Jan-2008		O/C	0		
732001 E1	HYDROMECHANICAL FUEL CONTROL KMCO			1012636-18 F63406	MTH 26-Dec-2017 HRS 4024.6 LDG 4216		1000	0	5024.6	476
732001 E2	HYDROMECHANICAL FUEL CONTROL KMCO			1012636-18 F60010	MTH 26-Dec-2017 HRS 4024.6 LDG 4216		1000	0	5024.6	476
732011 E1	T1/FCU TEMP SENSOR 30J1580-04 *CF			818487-4 KC077251	MTH 19-Jan-2008		O/C			
732011 E2	T1/FCU TEMP SENSOR 30J1580-04 *CF			818487-4 KC077248	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
741001 E1	IGNITION EXCITER 31J2807-07			500335-1 NNA13070207	MTH 27-Dec-2017		O/C	1		
741001 E2	IGNITION EXCITER 31J2807-07	KMCO		500335-1 NNA04298666	MTH 19-Jun-2015 HRS 2888.5 LDG 2899		O/C	4 0 0		
742001 E1 INBOARD	IGNITOR 30J2825-01	KMCO	POST	502600-1 NNA18210202	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		O/C	0 0		
742001 E1 OUTBOARD	IGNITOR 30J2825-01	KMCO	POST	502600-1 NNA18210186	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		O/C	1 0		
742001 E2 INBOARD	IGNITOR 30J2825-01	KMCO	POST	502600-1 NNA18210202	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		O/C	0 0		
742001 E2 OUTBOARD	IGNITOR 30J2825-01	KMCO	POST	502600-1 NNA18210186	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		O/C	0 0		
742002 E1	SHORT IGNITOR LEAD 30J3125-01	BLL		508122-1 NNAO8292730	MTH 21-Dec-2009 HRS 933		O/C	0		
742002 E2	SHORT IGNITOR LEAD 30J3125-01	KMCO	POST	508122-1 NNA15140258	MTH 20-May-2016 HRS 3316.6 LDG 3373		O/C	0 0		
742003 E1	LONG IGNITOR LEAD 30J3125-02	KMCO	POST	508122-2 NNA16020041	MTH 30-Jun-2017 HRS 3796.2 LDG 3956		O/C	0 0		
742003 E2	LONG IGNITOR LEAD 30J3125-02	BLL	POST	508122-2 NNAO8229566	MTH 21-Dec-2009 HRS 933		O/C	0		
751003 E1	COMPRESSOR BLEED VALVE ASSY *CF			30J2954-01 AHX009437	MTH 19-Jan-2008		O/C			
751003 E2	COMPRESSOR BLEED VALVE ASSY *CF			30J2954-01 AHX009406	MTH 19-Jan-2008		O/C			
751004 E1	INTERCOMPRESSOR BLEED VALVE SERVO VALVE	BLL		30J3491-01 TR5137	MTH 07-Dec-2011 HRS 1626 LDG 1356		O/C	0 0		
751004 E2	INTERCOMPRESSOR BLEED VALVE SERVO VALVE	BLL		30J3491-01 TR5136	MTH 23-Nov-2011 HRS 1614 LDG 1345		O/C	0 0		
751005 E1	LINEAR TRANSDUCER *CF			31J2071-01 2476	MTH 19-Jan-2008		O/C			
751005 E2	LINEAR TRANSDUCER *CF			31J2071-01 2477	MTH 19-Jan-2008		O/C			
761001 LEFT	THROTTLE DETENT VALVE *CF			5303-2A 4127A	MTH 19-Jan-2008		O/C			
761001 RIGHT	THROTTLE DETENT VALVE *CF			5303-2A 4198A	MTH 19-Jan-2008		O/C			
761001 E1	ELECTRONIC ENGINE CONTROL 30J2659-03			1004855-2-002 *CF 07083400	MTH 19-Jan-2008		O/C			
761001 E2	ELECTRONIC ENGINE CONTROL 30J2659-03			1004855-2-002 *CF 07087090	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
771006	ENGINE (AMLCD) INDICATOR 9912574-5	KMCO		10644D02M05 07080734A	MTH 05-Jul-2017 HRS 3749.2 LDG 3889 APUH 1756.9 APUS 3990		O/C	1 0		
771004 E1	SPEED N1 SENSOR	*CF		31J2072-01 CH1708	MTH 19-Jan-2008		O/C			
771004 E2	SPEED N1 SENSOR	*CF		31J2072-01 CH1720	MTH 19-Jan-2008		O/C			
771005 E1	SPEED N2 SENSOR	*CF		31J2073-01 CH2567	MTH 19-Jan-2008		O/C			
771005 E2	SPEED N2 SENSOR	*CF		31J2073-01 CH2570	MTH 19-Jan-2008		O/C			
772001 E1	TEMPERATURE SENSOR	*CF		31J2113-03 RTM0352	MTH 19-Jan-2008		O/C			
772001 E2	TEMPERATURE SENSOR	*CF		31J2113-03 RTM0022	MTH 19-Jan-2008		O/C			
774001 E1	DATA COLLECTION UNIT	KMCO		30J3469-02 13-584	MTH 13-Jun-2013 HRS 1909.3 LDG 1667		O/C	0 0 0		
774001 E2	DATA COLLECTION UNIT	KMCO		30J3469-02 15033768	MTH 29-Mar-2016		O/C	0		
783001 <i>783001X : E1**L</i>	THRUST REVERSER ASSEMBLY LEFT ENGINE 9912609-13	*CF		64ND-78002-5 1263	MTH 19-Jan-2008		O/C			
783001 <i>783001X : E2**R</i>	THRUST REVERSER ASSEMBLY RIGHT ENGINE 9912609-14	*CF		64ND-78002-6 1266	MTH 19-Jan-2008		O/C			
783002 LEFT	THRUST REVERSER VALVE	*CF		4221 0568	MTH 19-Jan-2008		O/C			
783002 RIGHT	THRUST REVERSER VALVE	*CF		4221 0571	MTH 19-Jan-2008		O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR	*CF		64ND-78204-7 2777	MTH 19-Jan-2008		O/C			
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR	KMCO		2564000-7 2505	MTH 03-May-2018 HRS 4196.4 LDG 4380		O/C	4 0		
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR	*CF		64ND-78204-7 2743	MTH 19-Jan-2008		O/C			
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR	*CF		64ND-78204-7 2780	MTH 19-Jan-2008		O/C			
783100 LEFT	THRUST REVERSER MANIFOLD ASSEMBLY	*CF		8245 0559	MTH 19-Jan-2008		O/C			
783100 RIGHT	THRUST REVERSER MANIFOLD ASSEMBLY	*CF		8245 0568	MTH 19-Jan-2008		O/C			
783101 LEFT	ARM PRESSURE SWITCH	*CF		80637-1 0915	MTH 19-Jan-2008		O/C			
783101 RIGHT	ARM PRESSURE SWITCH	*CF		80637-1 0897	MTH 19-Jan-2008		O/C			
783102 LEFT	THRUST REVERSER ISOLATION VALVE	*CF		4222 0563M	MTH 19-Jan-2008		O/C			
783102 RIGHT	THRUST REVERSER ISOLATION VALVE	*CF		4222 0570M	MTH 19-Jan-2008		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
783103 LEFT INBOARD	STOW LIMIT SWITCH *CF			53ND78304-1 NSN	MTH 19-Jan-2008		O/C			
783103 LEFT OUTBOARD	STOW LIMIT SWITCH *CF			53ND78304-1 NSN	MTH 19-Jan-2008		O/C			
783103 RIGHT INBOARD	STOW LIMIT SWITCH *CF			53ND78304-1 NSN	MTH 19-Jan-2008		O/C			
783103 RIGHT OUTBOARD	STOW LIMIT SWITCH *CF			53ND78304-1 NSN	MTH 19-Jan-2008		O/C			
783104 LEFT	DEPLOY LIMIT SWITCH *CF			53ND78304-5 NSN	MTH 19-Jan-2008		O/C			
783104 RIGHT	DEPLOY LIMIT SWITCH *CF			53ND78304-5 NSN	MTH 19-Jan-2008		O/C			
793002 LEFT	OIL TEMP XMTR SENSOR *CF			102-00083 06040	MTH 19-Jan-2008		O/C			
793002 RIGHT	OIL TEMP XMTR SENSOR *CF			102-00083 06069	MTH 19-Jan-2008		O/C			
793102 LEFT	ENGINE OIL TRANSMITTER 9912464-1 *CF			APTE-237E-1000- 250D 739011201	MTH 19-Jan-2008		O/C			
793102 RIGHT	ENGINE OIL TRANSMITTER 9912464-1 *CF			APTE-237E-1000- 250D 69501161	MTH 19-Jan-2008		O/C			
793117 LEFT	OIL PRESSURE SWITCH 9912466-2 *CF			1153P0098-01 1971	MTH 19-Jan-2008		O/C			
793117 RIGHT	OIL PRESSURE SWITCH 9912466-2 *CF			1153P0098-01 1964	MTH 19-Jan-2008		O/C			
790010 E1	OIL FILTER ELEMENT			PN SN-UNKNOWN	MTH 19-Jan-2008		O/C	0		
790010 E2	OIL FILTER ELEMENT			PN SN-UNKNOWN	MTH 19-Jan-2008		O/C	0		
793003 E1	FUEL OIL HEAT EXCHANGER D2552-600B *CF			31J2955-02 03676058	MTH 19-Jan-2008		O/C			
793003 E2	FUEL OIL HEAT EXCHANGER D2552-600B *CF			31J2955-02 03741823	MTH 19-Jan-2008		O/C			
80-10-00-9600 LEFT ENGINE <i>801000 : L</i>	LEFT ENGINE STARTER - GENERATOR (SECTION II OVERHAUL) RESTORATION 9912499-6 KMCO M-1			300SGL138Q-4 6107XL	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		1000	4	5319.7	771.1
80-10-00-9600 RIGHT ENGINE <i>801000 : R</i>	RIGHT ENGINE STARTER - GENERATOR (SECTION II OVERHAUL) RESTORATION 9912499-6 KMCO M-1			300SGL138Q-4 3662XL	MTH 31-Aug-2017 HRS 3826.6 LDG 3968 APUH 1794 APUS 4045		1000	0	4826.6	278
80-11-00-9600 APU <i>801100 : APU</i>	AUXILIARY POWER UNIT STARTER - GENERATOR (SECTION II OVERHAUL) RESTORATION 9912499-31 KMCO			300SGL138Q-6 4294XL	MTH 04-Feb-2018 HRS 4035.2 LDG 4216 APUH 1935		1000	0	2935	732



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 560XL-03-01 R01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (SUPERSEDED BY CIL-03-01)			INFORMATIONAL			-			
	MOC :									
SL 560XL-99-01 R04	CESCOM PRICES			INFORMATIONAL			-			
	MOC :									
SL 560XL-99-03 R01	MISCELLANEOUS - TRANSMITTAL OF CESSNA'S CERTIFICATION REQUIREMENTS FOR PORTABLE ELECTRONIC DEVICE USAGE			INFORMATIONAL			-			
	MOC :									
SL 560XL-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 560XL-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL 560XL-99-07	MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED			INFORMATIONAL			-			
	MOC :									
SB 560XL-05-01 R01	TIME LIMITS/MAINTENANCE CHECKS - CONVERSION FROM CALENDAR SCHEDULE MAINTENANCE PROGRAM TO MSG-3 SCHEDULE MAINTENANCE PROGRAM (CANCELLED AND SUPERSEDED BY SL560XL-05-03)			CANCELLED			-			
	MOC :									
SL 560XL-05-05 R01	TIME LIMITS/MAINTENANCE CHECKS - MSG-3 SCHEDULED MAINTENANCE PROGRAM CHANGE BRIDGING DOCUMENT			INFORMATIONAL			-			
	MOC :									
SL 560XL-05-05	TIME LIMITS/MAINTENANCE CHECKS - MSG-3 SCHEDULED MAINTENANCE PROGRAM CHANGE BRIDGING DOCUMENT			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 R01	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R02)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 R02	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R01)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			MTH RECOMMENDED			-			
	MOC :									
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 R01)			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 R01)			RECOMMENDED MTH			-			
	MOC :									
SL 560XL-20-01 R10	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL560XL-20-01 R11)			INFORMATIONAL			A/R			
	MOC :									
SL 560XL-20-04	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL			-			
	MOC :									
SL CIL-21-03	AIR CONDITIONING - TRANSMITTAL OF HONEYWELL SB 2341316-21-2828, INSPECTION AND REPAIR OF THE INTERIOR SURFACES OF THE WATER SEPARATOR, PN 2341316-2 AND -3, FOR CORROSION			INFORMATIONAL			-			
	MOC :									
SL 560XL-23-10	COMMUNICATIONS - ATG 4000 SOFTWARE UPDATE			OPTIONAL			-			
	MOC :									
SL 560XL-23-11	COMMUNICATIONS - ATG 4000 SOFTWARE UPDATE TO VERSION 2.8			OPTIONAL			-			
	MOC :									
SB 560XL-24-02 R01 <i>24SB-02 : XLR1</i>	ELECTRICAL POWER - CONCORDE BATTERY INSTALLATION	ICT		OPTIONAL	MTH 17-Dec-2012 HRS 1715 LDG 1393		-			Complete
	MOC : COMPLIED WITH - ACCOMPLISHED SB560XL-24-02 REV. 1; CONCORDE BATTERY INSTALLATION									
SB 560XL-24-14 R02 <i>24SB-14 : XLR2</i>	ELECTRICAL POWER - APU STARTER/GENERATOR REWIRING IMPROVEMENT	ZRH		RECOMMENDED	MTH 07-May-2010 HRS 1037 LDG 829		A/R			Complete
	MOC : COMPLIED WITH									
SB 560XL-24-15 <i>24SB-15 : XL</i>	ELECTRICAL POWER - TAILCONE/STINGER ELECTRICAL CONNECTOR IMPROVEMENT	ZRH		DISCRETIONARY	MTH 07-May-2010 HRS 1037 LDG 829		A/R			Complete
	MOC : COMPLIED WITH									
SB 560XL-24-17	ELECTRICAL POWER - TAILCONE INVERTER RELOCATION			DISCRETIONARY			A/R			
	MOC :									
SB 560XL-24-20	ELECTRICAL POWER - AC J-BOX WIRE BUNDLE ANCHOR INSTALLATION			MANDATORY	MTH HRS		24 2600		03-Oct-2019 6493.48	8 m 24 d 1944.88
	MOC :									
SL 560XL-24-07	ELECTRICAL POWER - RIGHT AC GENERATOR WIRE ROUTING VERIFICATION	KMCO		MANDATORY	DAYS 08-Mar-2017 HRS 3589.2 LDG 3691		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SERVICE LETTER INSTRUCTIONS AND SENT REPORT TO TEAM XL.									
SL 560XL-24-09	ELECTRICAL POWER - BATTERY TEMPERATURE INDICATOR GAGE BLANKING PLATE INSTALLATION			OPTIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-25-11 R01 <i>25SB-11 : XLR1</i>	EQUIPMENT/FURNISHINGS - ARTEX C406-2 *CF			THREE-FREQUENCY OPTIONAL	EMERGENCY LOCATOR TRANSMITTER (ELT) (SUPERSEDED BY 560XL-25-11 R02) MTH		A/R			
MOC :										
SB 560XL-25-12 R01 <i>25SB-12 : XLR1</i>	EQUIPMENT/FURNISHINGS - GLARESHIELD LEATHER STRIP INSTALLATION *CF			OPTIONAL	MTH		-			
MOC :										
SL 560XL-25-13	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF ROCKWELL COLLINS AIRSHOW 4000 SERVICE BULLETIN 30, CORRECTION OF HARD DRIVE MOUNTING SCREWS - MOD U	BLL		RECOMMENDED	MTH 07-Jun-2010 HRS 1083 LDG 867		A/R			N/A
MOC : NOT APPLICABLE										
SL 560XL-25-17	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 1423-25-003 REVISION C LUMBAR ASSEMBLY CABLE WEAR	KMCO		RECOMMENDED	MTH 13-Jun-2013 HRS 1862.3 LDG 1600		-			Complete
MOC : COMPLIED WITH										
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING	MCO		MANDATORY	MTH 10-Jul-2016 HRS 3318.1 LDG 3360		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH TORQUE CHECK ON FIRE EXTINGUISHING BOTTLES IAW SERVICE LETTER INSTRUCTIONS, NO DEFECTS NOTED.										
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING (SUPERSEDED BY CIL-26-01 R01)			MANDATORY	MTH		-			
MOC :										
SB 560XL-27-31 <i>27SB-31 : XL</i>	FLIGHT CONTROLS - FLAP HANDLE AND FLAP HANDLE GUARD IMPROVEMENT			OPTIONAL	MTH		A/R			
MOC :										
SB 560XL-27-32 R01	FLIGHT CONTROLS - RUDDER PEDAL POSITION MODIFICATION (SUPERSEDED BY 560XL-27-32 R02)	KMCO		RECOMMENDED	MTH 13-Jun-2013 HRS 1862.3 LDG 1600		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-27-32 R02	FLIGHT CONTROLS - RUDDER PEDAL POSITION MODIFICATION	KMCO		RECOMMENDED	MTH 13-Jun-2013 HRS 1862.3 LDG 1600		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-27-32	FLIGHT CONTROLS - RUDDER PEDAL POSITION MODIFICATION (SUPERSEDED BY 560XL-27-32 R01)	KMCO		RECOMMENDED	MTH 13-Jun-2013 HRS 1862.3 LDG 1600		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-27-35 R01	FLIGHT CONTROLS - STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT			OPTIONAL			-			
MOC :										
SB 560XL-27-35	FLIGHT CONTROLS - STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT (SUPERSEDED BY 560XL-27-35 R01)			OPTIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-27-14 27SL-14 : XL	FLIGHT CONTROLS - HORIZONTAL AND VERTICAL STABILIZER EROSION BOOT INSTALLATION	*CF	OPTIONAL			-			
MOC :									
SL 560XL-27-17 27SL-17 : XL	FLIGHT CONTROLS - ELEVATOR TRIM WHEEL INSPECTION	BLL	RECOMMENDED	MTH 24-Mar-2009 HRS 602		A/R			Complete
MOC : COMPLIED WITH									
SL 560XL-27-18	FLIGHT CONTROLS - ELEVATOR TRIM CABLE REPLACEMENT INTERVALS		INFORMATIONAL			-			
MOC :									
SL 560XL-27-20 R01	FLIGHT CONTROLS - RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION (SUPERSEDED BY SL560XL-27-20 R02)	KMCO	MANDATORY	MTH 08-Nov-2013 HRS 2017.2 LDG 1794		-			Complete
MOC : COMPLIED WITH									
SL 560XL-27-20 R02	FLIGHT CONTROLS - RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION	KMCO	MANDATORY	MTH 13-Feb-2014 HRS 2130.2 LDG 1918		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH BY VISUALLY INSPECTING RUDDER TORQUE TUBE FOR CRACKS AND CHECKING FOR PROPPER CLEARANCE OF TORQUE TUBE AND RUDDER BELL CRANK PER SL INSTRUCTIONS									
SL 560XL-27-20	FLIGHT CONTROLS - RUDDER TORQUE TUBE/SECTOR ASSEMBLY GAP INSPECTION (SUPERSEDED BY SL560XL-27-20 R01)	KMCO	MANDATORY	MTH 08-Nov-2013 HRS 2017.2 LDG 1794		-			Complete
MOC : COMPLIED WITH									
SL 560XL-27-21	FLIGHT CONTROLS - RUDDER TORQUE TUBE/SECTOR ASSEMBLY INSPECTION	KMCO	MANDATORY	MTH 13-Feb-2014 HRS 2130.2 LDG 1918		-			N/A
MOC : NOT APPLICABLE - SL560XL-27-21 IS N/A DUE TO THE INCORPORATION OF SL560XL-27-20R2.									
SL 560XL-27-33	FLIGHT CONTROLS - ELEVATOR CABLE INSPECTION AT THE AFT CANTED BULKHEAD	KMCO	MANDATORY	MTH 04-Dec-2014 HRS 2601.1 LDG 2533		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL560XL 27-33 ELEVATOR CABLE INSPECTION AT CANTED BULKHEAD. CABLE CLEARANCE CHECKS GOOD ALL WORK PERFORMED IAW SL560XL 27-33 ACCOMPLISHMENT INSTRUCTIONS.									
SL 560XL-27-34 R01	FLIGHT CONTROLS - RIGHT OUTBOARD AILERON WING UP CABLE ASSEMBLY INSPECTION		MANDATORY	MTH 04-Jun-2015 HRS 2829.6 LDG 2820		-			Complete
MOC : COMPLIED WITH - INSPECTED CABLE PN 6660002-14, FOUND TO BE PROPER DOUBLE SHANK SWAAED END PN MS20663 LAW CESSNA 560XL AMM 27-10-03.									
SL 560XL-27-34	FLIGHT CONTROLS - RIGHT OUTBOARD AILERON WING UP CABLE ASSEMBLY INSPECTION (SUPERSEDED BY SL560XL-27-34 R01)		MANDATORY	MTH		-			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-27-35	FLIGHT CONTROLS - AFT AILERON SECTOR ASSEMBLY INSPECTION	KMCO	MANDATORY	MTH 10-Dec-2015 DAYS 3044.4 HRS 3068 LDG		-			Complete
MOC : COMPLIED WITH - C/W SL560XL-27-35 AFT AILERON ASSEMBLY INSPECTION IAW SL INSTRUCTIONS. NO CORROSION NOTED AT THIS TIME.									
SL 560XL-28-03	FUEL - MOTIVE FLOW SHUTOFF VALVE O-RING REPLACEMENT	BLL	RECOMMENDED	MTH 14-Oct-2011 HRS 1533 LDG 1255		A/R			Complete
MOC : COMPLIED WITH									
SL 560XL-29-03 29SL-03 : XL	HYDRAULIC POWER - ENGINE HYDRAULIC HOSE INSPECTION	LL7	RECOMMENDED	MTH 28-Aug-2009 HRS 758		A/R			Complete
MOC : COMPLIED WITH									
SL 560XL-29-04	HYDRAULIC POWER - HYDRAULIC MANIFOLD CONTROL VALVE WIRE BUNDLE INSPECTION	KMCO	RECOMMENDED	MTH 10-Dec-2015 HRS 3044.4 LDG 3068		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH BY VISUAL INSPECTION OF WIRE BUNDLES AND INSTALLING PROTECTIVE SLEEVES PER SL INSTRUCTIONS.									
SL 560XL-29-05	HYDRAULIC POWER - ENGINE DRIVEN PUMP HYDRAULIC VERIFICATION	KMCO	RECOMMENDED	MTH 04-Feb-2018 HRS 4035.2 LDG 4216		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH SL560XL-29-05 BY INSPECTION OF THE ENGINE DRIVEN HYDRAULIC PUMPS PART NUMBERS AND FOUND 9912062-4 PUMPS INSTALLED. NO FURTHER ACTION REQUIRED AT THIS TIME.									
SB 560XL-30-06 30SB-06 : XL	ICE AND RAIN PROTECTION - HORIZONTAL STABILIZER DEICE SYSTEM PRESSURE SWITCH INSTALLATION IMPROVEMENT	BLL	DISCRETIONARY	MTH 09-Jul-2009 HRS 732		A/R			Complete
MOC : COMPLIED WITH									
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			-			
MOC :									
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION		INFORMATIONAL			-			
MOC :									
SL 560XL-31-05	INDICATING/RECORDING SYSTEMS - TRANSMITTAL OF L-3 COMMUNICATIONS ALERT BULLETIN NO. CESSNA SB 001	BLL	MANDATORY	MTH 30-Aug-2011 HRS 1482 LDG 1212		A/R			N/A
MOC : NOT APPLICABLE - BY PART NUMBER SL IS NOT EFFECTIV TO PARTS INSTALLED NO PARTS REPLACED AFTER DELIVERY OF AIRCRAFT 23 - JAN - 2008. L3 CESSNA SB 001 PARTS NOT EFFECTED TO SN INSTALLED IN AIRCRAFT.									
SB 560XL-32-38 R01	LANDING GEAR - REMOVE THE QUICK DISCONNECT FROM THE NOSE LANDING GEAR TORQUE LINK		OPTIONAL			A/R			
MOC :									
SB 560XL-32-38 32SB-38 : XL	LANDING GEAR - REMOVE THE QUICK DISCONNECT FROM THE NOSE LANDING GEAR TORQUE LINK (SUPERSEDED BY 560XL-32-38 R01)	*CF	OPTIONAL	MTH		A/R			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-32-41 R01	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE BULLETIN 3-1571-32-7	BLL		MANDATORY	MTH 16-Nov-2011 HRS 1564 LDG 1276		A/R			Complete
	MOC : COMPLIED WITH - PERF. PR. SB									
SB 560XL-32-42 R01	LANDING GEAR - STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT (SUPERSEDED BY 560XL-32-42 R02)			OPTIONAL			-			
	MOC :									
SB 560XL-32-42 R02	LANDING GEAR - STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT			OPTIONAL			-			
	MOC :									
SB 560XL-32-42	LANDING GEAR - STAINLESS STEEL HYDRAULIC TUBE REPLACEMENT (SUPERSEDED BY 560XL-32-42 R01)			OPTIONAL			-			
	MOC :									
SB 560XL-32-44 R01	LANDING GEAR - NOSE LANDING GEAR BEARING GREASE FITTING INSTALLATION			OPTIONAL			-			
	MOC :									
SB 560XL-32-44	LANDING GEAR - NOSE LANDING GEAR BEARING GREASE FITTING INSTALLATION (SUPERSEDED BY 560XL-32-44 R01)			OPTIONAL			-			
	MOC :									
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL			INFORMATIONAL			-			
	MOC :									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL			-			
	MOC :									
SL 560XL-32-22 32SL-22 : XL	LANDING GEAR - COMPONENT PLACARD INSTALLATION			OPTIONAL	MTH		A/R			
	MOC :									
SL 560XL-32-23 32SL-23 : XL	LANDING GEAR - EMERGENCY GEAR RELEASE INSPECTION	BLL		RECOMMENDED	MTH 24-Nov-2009 HRS 864		A/R			Complete
	MOC : COMPLIED WITH									
SL 560XL-32-24 R01	LANDING GEAR - TRANSMITTAL OF CURTISS WRIGHT SB 049801-32-01, LANDING GEAR CONTROL ALTERNATE LED LIGHTING BULB (CANCELLED)			CANCELLED			-			
	MOC :									
SL 560XL-32-26	LANDING GEAR - REPLACEMENT OF THE COTTER PIN FOR THE EMERGENCY GEAR-RELEASE	BLL		MANDATORY	MTH 17-Jun-2011 HRS 1416 LDG 1152		A/R			Complete
	MOC : COMPLIED WITH									
SL 560XL-32-27 R01	LANDING GEAR - HYDRAULIC LOADING VALVE WIRE BUNDLE INSPECTION			MANDATORY	DAYS		-			
	MOC :									
SL 560XL-32-27	LANDING GEAR - HYDRAULIC LOADING VALVE WIRE BUNDLE INSPECTION (SUPERSEDED BY SL560XL-32-27 R01)	KMCO		MANDATORY	DAYS 17-Jul-2014 HRS 2385.8 LDG 2234		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SL560XL-32-27 BY INSPECTING THE CANNON PLUG AND WIRE BUNDLE FOR THE HYDRAULIC LOADING VALVE AND INSTALL PROTECTIVE SLEEVING									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-33-14 33SB-14 : XL	LIGHTS - BAGGAGE COMPARTMENT LIGHT ASSEMBLY REPLACEMENT	BLL		MANDATORY	MTH 30-Oct-2008 HRS 475		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-33-15 33SB-15 : XL	LIGHTS - WING TIP NAVIGATION AND ANTI-COLLISION LED LIGHT INSTALLATION	KMCO		OPTIONAL	MTH 08-Nov-2013 HRS 2017.2 LDG 1794		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-33-16 33SB-16 : XL	LIGHTS - GROUND RECOGNITION LIGHT LED UPGRADE			OPTIONAL	MTH		A/R			
MOC :										
SB 560XL-34-32 R02	NAVIGATION - CATEGORY II OPERATIONS			OPTIONAL			-			
MOC :										
SB 560XL-34-37 34SB-37 : XL	NAVIGATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) STEEP APPROACH SWITCH INSTALLATION	*CF		OPTIONAL	MTH		-			
MOC :										
SB 560XL-34-40 R01 34SB-40 : XLR1	NAVIGATION - ENHANCED GROUND PROXIMITY WARNING SYSTEM (EGPWS) RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) UPGRADE	*CF		OPTIONAL	MTH		A/R			
MOC :										
SB 560XL-34-41 R02 34SB-41 : XLR2	NAVIGATION - HONEYWELL TRANSPONDER UPGRADE FOR ELEMENTARY SURVEILLANCE	*CF		OPTIONAL	MTH		A/R			
MOC :										
SB 560XL-34-43 R01 34SB-43 : XLR1	NAVIGATION - UNIVERSAL AVIONICS PERFORMANCE DATABASE UPGRADE	BLL		OPTIONAL	MTH 08-Dec-2008 HRS 506		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-34-44 R02 34SB-44 : XLR2	NAVIGATION - HONEYWELL MODE S TRANSPONDER UPGRADE FOR ENHANCED SURVEILLANCE (SUPERSEDED BY 560XL-34-44 R03)	*CF		OPTIONAL	MTH		A/R			
MOC :										
SB 560XL-34-44 R03	NAVIGATION - HONEYWELL MODE S TRANSPONDER UPGRADE FOR ENHANCED SURVEILLANCE			OPTIONAL			A/R			
MOC :										
SB 560XL-34-45 R01 34SB-45 : XLR1	NAVIGATION - ENHANCED VISION SYSTEMS (EVS) INSTALLATION	*CF		OPTIONAL	MTH		A/R			
MOC :										
SB 560XL-34-49 R01 34SB-49 : XLR1	NAVIGATION - RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) AUDIO INHIBIT SWITCH INSTALLATION			OPTIONAL			A/R			
MOC :										
SB 560XL-34-60	NAVIGATION - UNIVERSAL UNS-1ESPW FMS WIDE AREA AUGMENTATION SYSTEM (WAAS) UPGRADE			OPTIONAL			-			
MOC :										
SB 560XL-34-61 34SB-61 : XL	NAVIGATION - STANDBY COMPASS INSTALLATION	*CF		OPTIONAL	MTH		A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-34-62 <i>34SB-62 : XL</i>	NAVIGATION - STANDBY GYRO BATTERY WIRING MODIFICATION			RECOMMENDED	MTH 21-Jul-2008 HRS 285		A/R			Complete
MOC : COMPLIED WITH										
SB 560XL-34-66 R01	NAVIGATION - INSTALLATION OF SCN 802.8 FOR UNS-1 FMS			RECOMMENDED			-			
MOC :										
SB 560XL-34-66	NAVIGATION - INSTALLATION OF SCN 802.8 FOR UNS-1 FMS (SUPERSEDED BY 560XL-34-66 R01)	BLL		RECOMMENDED	MTH 05-Jul-2011 HRS 1442 LDG 1174		-			N/A
MOC : NOT APPLICABLE - N/A TO AC										
SB 560XL-34-70	NAVIGATION - UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE			OPTIONAL			A/R			
MOC :										
SB 560XL-34-71 R01	NAVIGATION - TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0	KMCO		MANDATORY	MTH 13-Jun-2013 HRS 1862.3 LDG 1600		-			Complete
MOC : COMPLIED WITH										
SB 560XL-34-71 R01	NAVIGATION - TCAS 2000 INTERFERENCE LIMITING FUNCTIONALITY UPGRADE FOR SOFTWARE VERSION 7.0 (SUPERSEDED BY 560XL-34-71 R01)	KMCO		MANDATORY	MTH 13-Jun-2013 HRS 1862.3 LDG 1600		-			Complete
MOC : COMPLIED WITH										
SB 560XL-34-72 R01	NAVIGATION - TCAS 2000 UPDATE SOFTWARE TO VERSION 7.1			OPTIONAL			-			
MOC :										
SB 560XL-34-72 R01	NAVIGATION - TCAS 2000 UPDATE SOFTWARE TO VERSION 7.1 (SUPERSEDED BY 560XL-34-72 R01)			OPTIONAL			-			
MOC :										
SB 560XL-34-75 R01	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE			OPTIONAL			-			
MOC :										
SB 560XL-34-75 R01	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE (SUPERSEDED BY 560XL-34-75 R01)			OPTIONAL			-			
MOC :										
SB 560XL-34-77 R01	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION (SUPERSEDED BY 560XL-34-77 R02)			OPTIONAL			-			
MOC :										
SB 560XL-34-77 R02	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION (SUPERSEDED BY 560XL-34-77 R03)			OPTIONAL			-			
MOC :										
SB 560XL-34-77 R03	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDERINSTALLATION (SUPERSEDED BY 560XL-34-77 R04)			OPTIONAL			-			
MOC :										
SB 560XL-34-77 R04	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION			OPTIONAL			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-34-77	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION (SUPERSEDED BY 560XL-34-77 R01)		OPTIONAL			-			
MOC :									
SB 560XL-34-78	NAVIGATION - UNIVERSAL UNS-1ESPW FMS SOFTWARE UPGRADE 1000.8		OPTIONAL			-			
MOC :									
SB 560XL-34-80	NAVIGATION - LITEF LCR-93 AHRS OBSOLESCENCE		OPTIONAL			-			
MOC :									
ASL 560XL-34-08 34ASL08 : XL	NAVIGATION - TRANSMITTAL OF HONEYWELL TECHNICAL NEWSLETTER A23-3850-001	ICT	MANDATORY	MTH 19-Jan-2008 HRS 8		-			N/A
MOC : NOT APPLICABLE									
SL CIL-34-01	NAVIGATION - TRANSMIT UNIVERSAL AVIONICS ALERT SERVICE BULLETIN 3XXX.()-34-3508		INFORMATIONAL			-			
MOC :									
SL CIL-34-02	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D201301000032, PRIMUS II INTEGRATED RADIO SYSTEM		MANDATORY	MTH 09-Apr-2010 HRS 1020 LDG 817		-			Complete
MOC : COMPLIED WITH - D PERF. MOD T PERF. FROM MANUFACTOR.									
SL CIL-34-06 R01	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D201206000008R002, PRIMUS EPIC AND PRIMUS II MODE S TRANSPONDER; (1) TCAS, CHANGE 7.1, REPORTS AN EARLIER TCAS II VERSION NUMBER TO ATC GROUND STATIONS, (2) IMPROPER SUPPORT OF EHS IN MODE S RADAR COVERAGE USING A SI CODE		INFORMATIONAL			-			
MOC :									
SL CIL-34-06	NAVIGATION - TRANSMITTAL OF HONEYWELL SIL D201206000008R002, PRIMUS EPIC AND PRIMUS II MODE S TRANSPONDER; (1) TCAS, CHANGE 7.1, REPORTS AN EARLIER TCAS II VERSION NUMBER TO ATC GROUND STATIONS, (2) IMPROPER SUPPORT OF EHS IN MODE S RADAR COVERAGE USING A SI CODE (SUPERSEDED BY CIL-34-06 R01)		INFORMATIONAL			-			
MOC :									
SL 560XL-34-24 R01	NAVIGATION - SERVICE INFORMATION FROM HONEYWELL	BLL	INFORMATIONAL	MTH 20-Feb-2012 HRS 1622 LDG 1326		-			N/A
MOC : NOT APPLICABLE									
SL 560XL-34-24 R01	NAVIGATION - SERVICE INFORMATION FROM HONEYWELL (SUPERSEDED BY SL560XL-34-24 R01)	BLL	INFORMATIONAL	MTH 17-Jun-2011 HRS 1416 LDG 1152		-			N/A
MOC : NOT APPLICABLE - SL560XL-34-24 N/A. AC EQUIPT WITH UNIVERSAL FMS UNS 1 ESP									
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	KMCO	MANDATORY	MTH 29-Mar-2016 DAYS 3176.1 HRS 3221 LDG		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SERVICE LETTER CIL-35-05 DATED JANUARY 8, 2016 BY VERIFYING THAT THE PART NUMBERS OF THE FLIGHT CREW OXYGEN MASKS INSTALLED ARE NOT APPLICABLE PER APPENDIX 1 OF ZODIACAEROSPACE SERVICE BULLETING MCF-SBU-35-001 DATED DECEMBER 3, 2012.									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560XL-35-04 R01	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL560XL-35-04 R02)	BLL		MANDATORY	MTH 20-Feb-2012 HRS 1622 LDG 1326		-			N/A
MOC : NOT APPLICABLE										
SL 560XL-35-04 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
MOC :										
SL 560XL-35-04	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL560XL-35-04 R01)	EKBI		MANDATORY	MTH 15-Sep-2011 HRS 1503 LDG 1226		-			N/A
MOC : NOT APPLICABLE - BY SERIAL NUMBER SL N/A TO EQUIPMENT INSTALLED MC10-16-150 SN 122963 AND 122653.HARNES MANUFACTURED IN 082007 AND 102007										
SB 560XL-38-03	WATER/WASTE - TOILET OVERRIDE RELAY INSTALLATION			OPTIONAL			-			
MOC :										
SL 560XL-38-01	WATER/WASTE - TRANSMITTAL OF MONOGRAM SYSTEMS SERVICE INFORMATION LETTER SIL15900-023	BLL		RECOMMENDED	MTH 05-Jul-2011 HRS 1442 LDG 1174		A/R			Complete
MOC : COMPLIED WITH - SL560XL-38-01 PERF. PR. SL.										
SB 560XL-49-17	AUXILIARY POWER - AUXILIARY POWER UNIT MOUNT BOLT CHANGE			OPTIONAL			-			
MOC :										
SL 560XL-49-13	AUXILIARY POWER - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN RE100-49-8250 AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LUBE MODULE, PN 3881825-1 WITH PN 3881825-2, FOR THE RE100[CS] AND RE100[XL] AUXILIARY POWER UNIT (APU)			INFORMATIONAL			-			
MOC :										
SB 3615880-49- 8149 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS			RECOMMENDED			-			
MOC :										
SB 3615880-49- 8149 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE TURBINE ROTORS, PN 3615880-1, PN 3615880-002, PN 3615880-3, AND PN 3615880-4, ON MULTIPLE APUS			RECOMMENDED			-			
MOC :										
SB 3822101-49- 8148 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS			RECOMMENDED			-			
MOC :										
SB 3822101-49- 8148 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTORS, PN 3822101-1, ON MULTIPLE APUS			RECOMMENDED			-			
MOC :										
SB 3881800-49- 7523 R04	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LOW OIL PRESSURE SWITCH, PN 3876255-2 WITH PN 3876351-1 AND REIDENTIFY LUBE PUMP FROM PN 3881800-1 TO PN 3881825-1, ON RE100[XL] AND RE100[LJ] APUS			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SB 3883900-49-7976	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - INSTALL FUEL FLOW DEFLECTOR, PN 70720001-1 ON THE FUEL CONTROL DIFFERENTIAL PRESSURE (DELTA P) SLEEVE UNK	RECOMMENDED	APUH 14-Dec-2017 APUS 1898.5 4229	-	-	-	-	Complete
MOC : COMPLIED WITH								
SB 49-7933 R03	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS RECOMMENDED				-			
MOC :								
SB 49-7933 R04	OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R5)				-			
MOC :								
SB 49-7933 R05	OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R6)				-			
MOC :								
SB 49-7933 R06	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R7)				-			
MOC :								
SB 49-7933 R07	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS (SUPERSEDED BY 49-7933 R08)				-			
MOC :								
SB 49-7933 R08	AIRBORNE AUXILIARY POWER UNIT (APU) - OIL - GENERAL - APPROVED OILS				-			
MOC :								
SB 49-7997 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES				-			
MOC :								
SB 49-7997 R03	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES				-			
MOC :								
SB 49-7997 R04	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES				-			
MOC :								
SB 49-7997 R05	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES				-			
MOC :								
SB 49-7997	GAS TURBINE ENGINE - STANDARD STORAGE AND PRESERVATION GUIDELINES UNK		APUH 14-Dec-2017 APUS 1898.5 4229		-			Complete
MOC : COMPLIED WITH								
SB 70721598-49-8168 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS RECOMMENDED				-			
MOC :								
SB 70721598-49-8168 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF COMPRESSOR ROTOR, PN 70721598-1, ON MULTIPLE APUS RECOMMENDED				-			
MOC :								
SB 70721725-49-8152 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS RECOMMENDED				-			
MOC :								



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 70721725-49-8152 R02	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - BALANCE REPAIR OF THE DUAL PILOT TURBINE ROTORS, PN 70721725-2 AND PN 70721725-5, ON MULTIPLE APUS			RECOMMENDED						
	MOC :									
SIL APU-49 R10	IMPLEMENTATION OF THE HONEYWELL SPECTROMETRIC OIL AND FILTER ANALYSIS PROGRAM (SOAP) FOR HONEYWELL AUXILIARY POWER UNITS (APUS)			RECOMMENDED						
	MOC :									
SB RE100-49-7896 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE OIL FILLER NECK AND (DIPSTICK) CAP, PN 361-530-9354, WITH OIL FILLER NECK CAP, PN 361-530-9355, ON THE RE100 APU			OPTIONAL						
	MOC :									
SB RE100-49-7992 R01	REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4			OPTIONAL						
	MOC :									
SB RE100-49-7992	REMOVE AND REPLACE ELECTRONIC CONTROL UNIT, PN 2119552-2 OR PN 2119552-3, WITH ELECTRONIC CONTROL UNIT, PN 2119552-4			OPTIONAL						
	MOC :									
SB RE100-49-8139	INCREASE THE INSTALLATION TORQUE AND ADD THE USE OF LOCKING COMPOUND DURING CARBON SEAL ASSEMBLY ON THE RE100 APU	UNK		RECOMMENDED	APUH 14-Dec-2017 APUS 1898.5 4229					Complete
	MOC : COMPLIED WITH									
SB RE100-49-8250 R01	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE LUBE MODULE, PN 3881825-1 WITH PN3881825-2, FOR THE RE100[CS] AND RE100 [XL] AUXILIARY POWER UNIT (APU)			ATTRITION						
	MOC :									
SL 560XL-52-07	DOORS - EXTERIOR DOOR SWITCH IMPROVEMENT			INFORMATIONAL			A/R			
	MOC :									
SB 560XL-53-13 R01	FUSELAGE - NOSE DRIP CAP BOND INSPECTION	ICT		MANDATORY	MTH 27-Jun-2012 HRS 1715 LDG 1393		A/R			Complete
	MOC : COMPLIED WITH									
SB 560XL-53-13	FUSELAGE - NOSE DRIP CAP BOND INSPECTION (SUPERSEDED BY 560XL-53-13 R01)			MANDATORY	MTH		A/R			
	MOC :									
SB 560XL-53-14	FUSELAGE - CARBON FIBER STRAKE MODIFICATION			OPTIONAL						
	MOC :									
SB 560XL-53-16	FUSELAGE - STINGER DRAIN INSTALLATION	ICT		MANDATORY	MTH 27-Jun-2012 HRS 1715 LDG 1393		A/R			Complete
	MOC : COMPLIED WITH									
ASL 560XL-53-08 R01	FUSELAGE - AFT CANTED BULKHEAD DRAIN INSTALLATION	BLL		MANDATORY	DAYS 09-Mar-2011 HRS 1320 LDG 1076		A/R			Complete
	MOC : COMPLIED WITH - ASL560XL-53-08 AND R1 PERF. PR. SB.									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
ASL 560XL-53-08	FUSELAGE - AFT CANTED BULKHEAD DRAIN INSTALLATION (SUPERSEDED BY ASL560XL-53-08 R01)	MANDATORY	DAYS		A/R			
MOC : - SUPERSEDED BY REVISION 1								
SL 560XL-53-07 53SL-07 : XL	FUSELAGE - LOWER SKIN ASSEMBLY FASTENER INSPECTION ZRH	MANDATORY	DAYS 07-May-2010		-			Complete
MOC : COMPLIED WITH								
SL 560XL-53-17	FUSELAGE - DORSAL DUCT INSPECTION KMCO	RECOMMENDED	MTH 13-Jun-2013		-			Complete
MOC : COMPLIED WITH								
SL 560XL-55-01 R01	STABILIZERS - PIVOT FITTING INSPECTION (SUPERSEDED BY SL560XL-55-01 R02)	MANDATORY	MTH 19-Jan-2008		-			
MOC :								
SL 560XL-55-01 R02	STABILIZERS - PIVOT FITTING INSPECTION (SUPERSEDED BY SL560XL-55-01 R03)	MANDATORY			-			
MOC :								
SL 560XL-55-01 R03	STABILIZERS - PIVOT FITTING INSPECTION	CANCELLED			-			
MOC :								
SL 560XL-55-01	STABILIZERS - PIVOT FITTING INSPECTION (SUPERSEDED BY SL560XL-55-01 R01)	MANDATORY	MTH		-			
MOC :								
SL 560XL-56-03	WINDOWS - OPENABLE COCKPIT WINDOW HINGE AND LATCH INSPECTION BLL	MANDATORY	MTH 09-Mar-2011		A/R			Complete
MOC : COMPLIED WITH - SL560XL-56-03 PERF. PR. SL.								
SB 560XL-71-11 R01	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION	OPTIONAL			-			
MOC :								
SB 560XL-71-11	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION (SUPERSEDED BY 560XL-71-11 R01)	OPTIONAL			A/R			
MOC :								
SB 560XL-71-12	POWER PLANT - ENGINE FUEL MANIFOLD DRAIN LINE REMOVAL	OPTIONAL			-			
MOC :								
SL CIL-71-01	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30463	OPTIONAL			-			
MOC :								
ASL 560XL-72-19 LEFT ENGINE	TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO - VALVE - INSPECTION/REPLACEMENT OF	MANDATORY	MTH 02-Nov-2010		A/R			N/A
MOC : NOT APPLICABLE - ASB PW500-72-A30421 R1 IS NOT ACTUEL ON INSTALLED PART. PART HAS MORE THAN 250 HRS OF RUNNING TIME.SB PW500-72-30420 IS DUE FOR REPLACEMENT AT 1788 HRS REF ITEM CODE SB PW500-72-30420 R1.								



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
ASL 560XL-72-19 RIGHT ENGINE	TRANSMITTAL OF P&WC SERVICE DOCUMENTS - INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE-INSPECTION/REPLACEMENT OF	BLL		MANDATORY	MTH 02-Nov-2010 HRS 1235 LDG 992		A/R			N/A
MOC : NOT APPLICABLE - ASB PW500-72-A30421 R1 IS NOT ACTUEL ON INSTALLED PART. PART HAS MORE THAN 250 HRS OF RUNNING TIME.SB PW500-72-30420 IS DUE FOR REPLACEMENT AT 1788 HRS REF ITEM CODE SB PW500-72-30420 R1										
SL 560XL-72-15 72SL-15 : XL	ENGINE - TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30383, INSPECTION OF TURBOFAN ENGINE INTERCOMPRESSOR BLEED VALVE SERVO VALVE	BLL		RECOMMENDED	MTH 02-Sep-2009 HRS 758		A/R			N/A
MOC : NOT APPLICABLE										
SL 560XL-72-16 72SL-16 : XL	ENGINE - TRANSMITTAL OF PRATT AND WHITNEY CANADA TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30368, TURBOFAN ENGINE INTERCOMPRESSOR BLEEDVALVE SERVO VALVE - INSPECTION	BLL		RECOMMENDED	MTH 02-Sep-2009 HRS 758		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-72-17 LEFT ENGINE 72SL-17 : E1**L	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT,MODIFICATION OF	ICT		MANDATORY	MTH 01-Nov-2012 HRS 1715 LDG 1393		A/R			Complete
MOC : COMPLIED WITH										
SL 560XL-72-17 RIGHT ENGINE 72SL-17 : E2**R	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT,MODIFICATION OF	ICT		MANDATORY	MTH 01-Nov-2012 HRS 1715 LDG 1393		A/R			Complete
MOC : COMPLIED WITH										
SB PW300-72-30446 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY CATEGORY 7						A/R			
MOC :										
SB PW300-72-30446 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY CATEGORY 7						A/R			
MOC :										
SB PW500-72-30215 R02 E1	MODIFICATION/REWORK OF TURBINE EXHAUST CASE CATEGORY 6						-			
MOC :										
SB PW500-72-30215 R02 E2	MODIFICATION/REWORK OF TURBINE EXHAUST CASE CATEGORY 6						-			
MOC :										
SB PW500-72-30269 R01 E1	REPLACEMENT OF GAS GENERATOR DIFFUSER SET AND NO. 4 BEARING CATEGORY 7						-			
MOC :										
SB PW500-72-30269 R01 E2	REPLACEMENT OF GAS GENERATOR DIFFUSER SET AND NO. 4 BEARING CATEGORY 7						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30270 R01 E1	REPLACEMENT OF TURBINE EXHAUST CASE ASSY			CATEGORY 7			-			
MOC :										
SB PW500-72-30270 R01 E2	REPLACEMENT OF TURBINE EXHAUST CASE ASSY			CATEGORY 7			-			
MOC :										
SB PW500-72-30281 R02 E1	REPLACEMENT OF FUEL NOZZLE GASKET			CATEGORY 6			-			
MOC :										
SB PW500-72-30281 R02 E2	REPLACEMENT OF FUEL NOZZLE GASKET			CATEGORY 6			-			
MOC :										
SB PW500-72-30288 R02 E1	MODIFICATION OF TURBINE CASE ASSEMBLY			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30288 R02 E2	MODIFICATION OF TURBINE CASE ASSEMBLY			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30306 R05 E1	NEW TRANSFER TUBES WITH HEAT SHIELD			CATEGORY 5			-			
MOC :										
SB PW500-72-30306 R05 E2	NEW TRANSFER TUBES WITH HEAT SHIELD			CATEGORY 5			-			
MOC :										
SB PW500-72-30309 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 6			-			
MOC :										
SB PW500-72-30309 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 6			-			
MOC :										
SB PW500-72-30311 R03 E1	REPLACEMENT OF COMPRESSOR BLEED VALVE ASSEMBLY AND SERVO VALVE			CATEGORY 8			-			
MOC :										
SB PW500-72-30311 R03 E2	REPLACEMENT OF COMPRESSOR BLEED VALVE ASSEMBLY AND SERVO VALVE			CATEGORY 8			-			
MOC :										
SB PW500-72-30325 R02 E1	REPLACEMENT OF OIL-PUMP PLAIN SEAL (SUPERSEDED BY PW500-72-30325 R03)			CATEGORY 6			-			
MOC :										
SB PW500-72-30325 R02 E2	REPLACEMENT OF OIL-PUMP PLAIN SEAL (SUPERSEDED BY PW500-72-30325 R03)			CATEGORY 6			-			
MOC :										
SB PW500-72-30325 R03 E1	REPLACEMENT OF OIL-PUMP PLAIN SEAL			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30325 R03 E2	REPLACEMENT OF OIL-PUMP PLAIN SEAL			CATEGORY 6						
MOC :										
SB PW500-72-30332 R02 E1	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING	ICT		CATEGORY 6	MTH 27-Jun-2012 HRS 1762 LDG 1460		A/R			N/A
MOC : NOT APPLICABLE										
SB PW500-72-30332 R02 E2	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30336 R01 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 7						
MOC :										
SB PW500-72-30336 R01 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 7						
MOC :										
SB PW500-72-30339 R02 E1	REPLACEMENT/MODIFICATION OF FRONT FAN CASE ASSEMBLY			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30339 R02 E2	REPLACEMENT/MODIFICATION OF FRONT FAN CASE ASSEMBLY			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30343 R06 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7						
MOC :										
SB PW500-72-30343 R06 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7						
MOC :										
SB PW500-72-30344 R01 E1	REPLACEMENT OF VARIOUS CADMIUM PLATED PARTS			CATEGORY 7						
MOC :										
SB PW500-72-30344 R01 E2	REPLACEMENT OF VARIOUS CADMIUM PLATED PARTS			CATEGORY 7						
MOC :										
SB PW500-72-30356 R02 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS			CATEGORY 6						
MOC :										
SB PW500-72-30356 R02 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS			CATEGORY 6						
MOC :										
SB PW500-72-30362 E1	REPLACEMENT HP TURBINE DISK BALANCING ASSEMBLY WITH THICKER FEATHER SEALS	UNK		CATEGORY 6	MTH 10-Sep-2014 HRS 2512.2 LDG 2402					Complete
MOC : COMPLIED WITH - THE FOLLOWING SERVICE BULLETINS WERE EMBODIED THIS VISIT:30387 R4,30362										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30362 E2	REPLACEMENT HP TURBINE DISK BALANCING ASSEMBLY WITH THICKER FEATHER SEALS	UNK		CATEGORY 6	MTH 10-Sep-2014 HRS 2512.2 LDG 2402		-			Complete
MOC : COMPLIED WITH - THE FOLLOWING SERVICE BULLETINS WERE EMBODIED THIS VISIT:30387 R4,30362										
SB PW500-72-30364 R01 E1	REPLACEMENT ACCESSORY GEARBOX PLAIN SEALS			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30364 R01 E2	REPLACEMENT ACCESSORY GEARBOX PLAIN SEALS			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30368 R01 E1	INTERCOMPRESSOR-BLEED-VALVE SERVO VALVE - INSPECTION (SUPERSEDED BY PW500-72-30368 R02)	BLL		CATEGORY 3	MTH 21-Jan-2009 HRS 583 LDG 497		-			Complete
MOC : COMPLIED WITH - PWC SB 30368R1 CW PR SB										
SB PW500-72-30368 R01 E2	INTERCOMPRESSOR-BLEED-VALVE SERVO VALVE - INSPECTION (SUPERSEDED BY PW500-72-30368 R02)	BLL		CATEGORY 3	MTH 21-Jan-2009 HRS 583 LDG 497		-			Complete
MOC : COMPLIED WITH - PWC SB 30368R1 CW PR SB										
SB PW500-72-30369 R01 E1	REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY WITH A NEW REAR OIL PUMP HOUSING			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30369 R01 E2	REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY WITH A NEW REAR OIL PUMP HOUSING			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30371 R01 E1	TURBOFAN ENGINE - ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE - INTRODUCTION (SUPERSEDED BY PW500-72-30371 R02)			CATEGORY 6			-			
MOC :										
SB PW500-72-30371 R01 E2	TURBOFAN ENGINE - ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE - INTRODUCTION (SUPERSEDED BY PW500-72-30371 R02)			CATEGORY 6			-			
MOC :										
SB PW500-72-30371 R02 E1	INTRODUCTION ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE			CATEGORY 10			-			
MOC :										
SB PW500-72-30371 R02 E2	INTRODUCTION ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE			CATEGORY 10			-			
MOC :										
SB PW500-72-30376 R01 E1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR (SUPERSEDED BY PW500-72-30371 R02)			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30376 R01 E2	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR (SUPERSEDED BY PW500-72-30371 R02)			CATEGORY 7			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30376 R02 E1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR			CATEGORY 7			-			
MOC :										
SB PW500-72-30376 R02 E2	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR			CATEGORY 7			-			
MOC :										
SB PW500-72-30384 R01 E1	REPLACEMENT OF AIR/OIL SEPARATOR			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30384 R01 E2	REPLACEMENT OF AIR/OIL SEPARATOR			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30387 R02 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R03)			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R02 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R03)			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R03 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY(SUPERSEDED BY PW500-72-30387 R04)			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R03 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY(SUPERSEDED BY PW500-72-30387 R04)			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R04 E1	REPLACEMENT / MODIFICATION OF REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R05)	UNK		CATEGORY 6	MTH 10-Sep-2014		-			Complete
MOC : COMPLIED WITH - THE FOLLOWING SERVICE BULLETINS WERE EMBODIED THIS VISIT:30387 R4,30362										
SB PW500-72-30387 R04 E2	REPLACEMENT / MODIFICATION OF REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R05)	UNK		CATEGORY 6	MTH 10-Sep-2014		-			Complete
MOC : COMPLIED WITH - THE FOLLOWING SERVICE BULLETINS WERE EMBODIED THIS VISIT:30387 R4,30362										
SB PW500-72-30387 R05 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R06)			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R05 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY (SUPERSEDED BY PW500-72-30387 R06)			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R06 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R06 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30390 R05 E1	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY SB PW500-72-30409 R08)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30390 R05 E2	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY SB PW500-72-30409 R08)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30399 E1	REPLACEMENT OF BOLTS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30399 E2	REPLACEMENT OF BOLTS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30400 R01 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30400 R01 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30400 R02 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R03)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30400 R02 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R03)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30400 R03 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30400 R03 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30400 R04 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			-			
	MOC :									
SB PW500-72-30400 R04 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			-			
	MOC :									
SB PW500-72-30400 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R01)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30400 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER (SUPERSEDED BY PW500-72-30400 R01)			CATEGORY 6			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30403 R02 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES (SUPERSEDED BY PW500-72-30403 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30403 R02 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES (SUPERSEDED BY PW500-72-30403 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30403 R03 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
	MOC :									
SB PW500-72-30403 R03 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
	MOC :									
SB PW500-72-30405 R01 E1	REPLACEMENT OF FUEL NOZZLE MANIFOLD (SUPERSEDED BY PW500-72-30405 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30405 R01 E2	REPLACEMENT OF FUEL NOZZLE MANIFOLD (SUPERSEDED BY PW500-72-30405 R02)			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30405 R02 E1	REPLACEMENT OF FUEL NOZZLE MANIFOLD (SUPERSEDED BY PW500-72-30405 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30405 R02 E2	REPLACEMENT OF FUEL NOZZLE MANIFOLD (SUPERSEDED BY PW500-72-30405 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30405 R03 E1	REPLACEMENT OF - FUEL NOZZLE MANIFOLD (SUPERSEDED BY PW500-72-30405 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30405 R03 E2	REPLACEMENT OF - FUEL NOZZLE MANIFOLD (SUPERSEDED BY PW500-72-30405 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30405 R04 E1	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
	MOC :									
SB PW500-72-30405 R04 E2	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
	MOC :									
SB PW500-72-30408 E1	REPLACEMENT OF ENGINE GASKET			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30408 E2	REPLACEMENT OF ENGINE GASKET			CATEGORY 6			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30409 R08 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R09)	ICT		CATEGORY 3	MTH 01-Nov-2012 HRS 1762 LDG 1460		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30409 R08 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R09)	ICT		CATEGORY 3	MTH 01-Nov-2012 HRS 1762 LDG 1460		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30409 R09 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R10)			CATEGORY 7			-			
MOC :										
SB PW500-72-30409 R09 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30409 R10)			CATEGORY 7			-			
MOC :										
SB PW500-72-30409 R10 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	KMCO		CATEGORY 3	MTH 26-Dec-2017 HRS 4024.6 LDG 4216		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH BY INSTALLING A REPAIRED FCU, P/N:1012636-18, S/N:F63406 ON THE LEFT ENGINE WHICH FULLY MEETS OR EXCEEDS THE REQUIREMENT IN THIS SERVICE BULLETIN.										
SB PW500-72-30409 R10 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	KMCO		CATEGORY 3	MTH 26-Dec-2017 HRS 4024.6 LDG 4216		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH BY INSTALLING A REPAIRED FCU, P/N:1012636-18, S/N:F60010 ON THE RIGHT ENGINE WHICH FULLY MEETS OR EXCEEDS THE REQUIREMENT IN THIS SERVICE BULLETIN.										
SB PW500-72-30413 R01 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R02)			CATEGORY 6						A/R
MOC :										
SB PW500-72-30413 R01 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R02)			CATEGORY 6						A/R
MOC :										
SB PW500-72-30413 R02 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R03)			CATEGORY 6						A/R
MOC :										
SB PW500-72-30413 R02 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R03)			CATEGORY 6						A/R
MOC :										
SB PW500-72-30413 R03 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R04)			CATEGORY 6						A/R
MOC :										
SB PW500-72-30413 R03 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R04)			CATEGORY 6						A/R
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task # City Mod Lvl Part Serial No		C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SB PW500-72-30413 R04 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R05) CATEGORY 6				A/R			
	MOC :							
SB PW500-72-30413 R04 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R05) CATEGORY 6				A/R			
	MOC :							
SB PW500-72-30413 R05 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R06) CATEGORY 6				-			
	MOC :							
SB PW500-72-30413 R05 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R06) CATEGORY 6				-			
	MOC :							
SB PW500-72-30413 R06 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R07) CATEGORY 6				-			
	MOC :							
SB PW500-72-30413 R06 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R07) CATEGORY 6				-			
	MOC :							
SB PW500-72-30413 R07 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R08) CATEGORY 6				-			
	MOC :							
SB PW500-72-30413 R07 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R08) CATEGORY 6				-			
	MOC :							
SB PW500-72-30413 R08 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R09) CATEGORY 6				-			
	MOC :							
SB PW500-72-30413 R08 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R09) CATEGORY 6				-			
	MOC :							
SB PW500-72-30413 R09 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R10) CATEGORY 6				-			
	MOC :							
SB PW500-72-30413 R09 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R10) CATEGORY 6				-			
	MOC :							
SB PW500-72-30413 R10 E1	INTRODUCTION OF DEEPER SUMP CATEGORY 6				-			
	MOC :							
SB PW500-72-30413 R10 E2	INTRODUCTION OF DEEPER SUMP CATEGORY 6				-			
	MOC :							
SB PW500-72-30413 R11 E1	INTRODUCTION OF DEEPER SUMP CATEGORY 6				-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30413 R11 E2	INTRODUCTION OF DEEPER SUMP			CATEGORY 6			-			
MOC :										
SB PW500-72-30413 E1	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30413 E2	INTRODUCTION OF DEEPER SUMP (SUPERSEDED BY PW500-72-30413 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30415 R01 E1	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R02)			CATEGORY 6			-			
MOC :										
SB PW500-72-30415 R01 E2	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R02)			CATEGORY 6			-			
MOC :										
SB PW500-72-30415 R02 E1	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R03)			CATEGORY 6			-			
MOC :										
SB PW500-72-30415 R02 E2	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R03)			CATEGORY 6			-			
MOC :										
SB PW500-72-30415 R03 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30415 R03 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30415 E1	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30415 E2	REPLACEMENT OF NO. 4 ROLLER BEARING (SUPERSEDED BY PW500-72-30415 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30416 R01 E1	REPLACEMENT OF NO.4 BEARING CARBON SEAL			CATEGORY 10			-			
MOC :										
SB PW500-72-30416 R01 E2	REPLACEMENT OF NO.4 BEARING CARBON SEAL			CATEGORY 10			-			
MOC :										
SB PW500-72-30416 E1	REPLACEMENT OF NO.4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30416 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30416 E2	REPLACEMENT OF NO.4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30416 R01)			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30417 R01 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R02)			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R01 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R02)			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R02 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R03)			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R02 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R03)			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R03 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R04)			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R03 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R04)			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R04 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R05)			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R04 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R05)			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R05 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R06)			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R05 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R06)			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R06 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R07)			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R06 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R07)			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 R07 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R08)			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30417 R07 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R08)			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30417 R08 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 10			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30417 R08 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING			CATEGORY 10			-			
MOC :										
SB PW500-72-30417 E1	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R01)			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30417 E2	REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING (SUPERSEDED BY PW500-72-30417 R01)			CATEGORY 5			A/R			
MOC :										
SB PW500-72-30419 R01 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
MOC :										
SB PW500-72-30419 R01 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
MOC :										
SB PW500-72-30419 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30419 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30419 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30419 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30420 R01 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R02)			CATEGORY 3			-			
MOC : - -SUPERSEDED BY REVISION 2										
SB PW500-72-30420 R01 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R02)			CATEGORY 3			-			
MOC : - -SUPERSEDED BY REVISION 2										
SB PW500-72-30420 R02 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R03)	BLL		CATEGORY 3	MTH 07-Dec-2011 HRS 1626 LDG 1356		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30420 R02 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R03)	BLL		CATEGORY 3	MTH 23-Nov-2011 HRS 1614 LDG 1345		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30420 R03 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R04)			CATEGORY 3			-			
MOC :										
SB PW500-72-30420 R03 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R04)			CATEGORY 3			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30420 R04 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R05)			CATEGORY 6			-			
MOC :										
SB PW500-72-30420 R04 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R05)			CATEGORY 6			-			
MOC :										
SB PW500-72-30420 R05 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			
MOC :										
SB PW500-72-30420 R05 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			
MOC :										
SB PW500-72-30420 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R01)			CATEGORY 3			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW500-72-30420 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R01)			CATEGORY 3			-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY REVISION 1										
SB PW500-72-30423 R01 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30423 R01 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30423 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30423 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30423 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30423 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30425 R01 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30425 R02)			CATEGORY 3			A/R			
MOC :										
SB PW500-72-30425 R01 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30425 R02)			CATEGORY 3			A/R			
MOC :										
SB PW500-72-30425 R02 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30425 R03)						A/R			
MOC :										
SB PW500-72-30425 R02 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30425 R03)						A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30425 R03 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 10						
MOC :										
SB PW500-72-30425 R03 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL			CATEGORY 10						
MOC :										
SB PW500-72-30425 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30425 R01)			CATEGORY 3			A/R			
MOC :										
SB PW500-72-30425 E2	REPLACEMENT OF NO. 4 BEARING CARBON SEAL (SUPERSEDED BY PW500-72-30425 R01)			CATEGORY 3			A/R			
MOC :										
SB PW500-72-30427 R01 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30427 R02)			CATEGORY 7						
MOC :										
SB PW500-72-30427 R01 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30427 R02)			CATEGORY 7						
MOC :										
SB PW500-72-30427 R02 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30427 R03)			CATEGORY 7						
MOC :										
SB PW500-72-30427 R02 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30427 R03)			CATEGORY 7						
MOC :										
SB PW500-72-30427 R03 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7						
MOC :										
SB PW500-72-30427 R03 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7						
MOC :										
SB PW500-72-30427 R04 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7						
MOC :										
SB PW500-72-30427 R04 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7						
MOC :										
SB PW500-72-30428 R01 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R02)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30428 R01 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R02)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30428 R02 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R02)			CATEGORY 6						
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30428 R02 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R02)			CATEGORY 6			-			
MOC :										
SB PW500-72-30428 R03 E1	REPLACEMENT OF - FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R04)			CATEGORY 6			-			
MOC :										
SB PW500-72-30428 R03 E2	REPLACEMENT OF - FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R04)			CATEGORY 6			-			
MOC :										
SB PW500-72-30428 R04 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R05)			CATEGORY 6			-			
MOC :										
SB PW500-72-30428 R04 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE (SUPERSEDED BY PW500-72-30428 R05)			CATEGORY 6			-			
MOC :										
SB PW500-72-30428 R05 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
MOC :										
SB PW500-72-30428 R05 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
MOC :										
SB PW500-72-30429 R01 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R02)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30429 R01 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R02)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30429 R02 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R03)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30429 R02 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R03)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30429 R03 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R04)			CATEGORY 6			-			
MOC :										
SB PW500-72-30429 R03 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R04)			CATEGORY 6			-			
MOC :										
SB PW500-72-30429 R04 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R05)			CATEGORY 6			-			
MOC :										
SB PW500-72-30429 R04 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R05)			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30429 R05 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R06)			CATEGORY 6			-			
MOC :										
SB PW500-72-30429 R05 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R06)			CATEGORY 6			-			
MOC :										
SB PW500-72-30429 R06 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30429 R06 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30429 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30429 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30429 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30432 R01 E1	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30432 R01 E2	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30432 E1	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF (SUPERSEDED BY PW500-72-30432 R01)			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30432 E2	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF (SUPERSEDED BY PW500-72-30432 R01)			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30436 R01 E1	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY (SUPERSEDED BY PW500-72-30436 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30436 R01 E2	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY (SUPERSEDED BY PW500-72-30436 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30436 R02 E1	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY (SUPERSEDED BY PW500-72-30436 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30436 R02 E2	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY (SUPERSEDED BY PW500-72-30436 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30436 R03 E1	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY (SUPERSEDED BY PW500-72-30436 R04)			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30436 R03 E2	REPLACEMENT / MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY (SUPERSEDED BY PW500-72-30436 R04)			CATEGORY 7			-			
MOC :										
SB PW500-72-30436 R04 E1	REPLACEMENT/MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30436 R04 E2	REPLACEMENT/MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30436 E1	LPT 2ND STAGE VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW500-72-30436 R01)						A/R			
MOC :										
SB PW500-72-30436 E2	LPT 2ND STAGE VANE ASSEMBLY - REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW500-72-30436 R01)						A/R			
MOC :										
SB PW500-72-30440 R01 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R02)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30440 R01 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R02)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30440 R02 E1	REPLACEMENT OF TURBOFAN ENGINE NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R03)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30440 R02 E2	REPLACEMENT OF TURBOFAN ENGINE NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R03)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30440 R03 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R04)			CATEGORY 6			-			
MOC :										
SB PW500-72-30440 R03 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R04)			CATEGORY 6			-			
MOC :										
SB PW500-72-30440 R04 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R05)			CATEGORY 6			-			
MOC :										
SB PW500-72-30440 R04 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R05)			CATEGORY 6			-			
MOC :										
SB PW500-72-30440 R05 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30440 R05 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30440 E1	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30440 E2	REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY (SUPERSEDED BY PW500-72-30440 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30442 R01 E1	REPLACEMENT/MODIFICATION OF TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R02)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30442 R01 E2	REPLACEMENT/MODIFICATION OF TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R02)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30442 R02 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 R02 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 R03 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R04)			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 R03 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30442 R04)			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30442 E1	HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW500-72-30442 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30442 E2	HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF (SUPERSEDED BY PW500-72-30442 R01)			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30446 R01 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY (SUPERSEDED BY PW500-72-30446 R02)			CATEGORY 7			A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30446 R01 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY (SUPERSEDED BY PW500-72-30446 R02)			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30446 R02 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30446 R02 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30447 R01 E1	NEW COATING MODIFICATION OF GAS GENERATOR CASE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30447 R01 E2	NEW COATING MODIFICATION OF GAS GENERATOR CASE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30447 E1	NEW COATING MODIFICATION OF GAS GENERATOR CASE (SUPERSEDED BY PW500-72-30447 R01)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30447 E2	NEW COATING MODIFICATION OF GAS GENERATOR CASE (SUPERSEDED BY PW500-72-30447 R01)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30449 R01 E1	TURBOFAN ENGINE - HP TURBINE DISK ASSEMBLY - REPLACEMENT OF (SUPERSEDED BY PW500-72-30449 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30449 R01 E2	TURBOFAN ENGINE - HP TURBINE DISK ASSEMBLY - REPLACEMENT OF (SUPERSEDED BY PW500-72-30449 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30449 R02 E1	REPLACEMENT OF HP TURBINE DISK ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30449 R02 E2	REPLACEMENT OF HP TURBINE DISK ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30449 E1	REPLACEMENT OF HP TURBINE DISK ASSEMBLY (SUPERSEDED BY PW500-72-30449 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30449 E2	REPLACEMENT OF HP TURBINE DISK ASSEMBLY (SUPERSEDED BY PW500-72-30449 R01)			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30453 R01 E1	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R02)			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30453 R01 E2	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R02)			CATEGORY 6			-			
MOC :										
SB PW500-72-30453 R02 E1	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R03)			CATEGORY 6			-			
MOC :										
SB PW500-72-30453 R02 E2	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R03)			CATEGORY 6			-			
MOC :										
SB PW500-72-30453 R03 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
MOC :										
SB PW500-72-30453 R03 E2	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 6			-			
MOC :										
SB PW500-72-30453 E1	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30453 E2	REPLACEMENT OF NO. 4 CARBON SEAL (SUPERSEDED BY PW500-72-30453 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30455 R01 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R02)	ICT		CATEGORY 7	MTH 01-Nov-2012 HRS 1762 LDG 1460		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30455 R01 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R02)	ICT		CATEGORY 7	MTH 01-Nov-2012 HRS 1762 LDG 1460		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30455 R02 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R02 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R03 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R04)			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R03 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R04)			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30455 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R01)	ICT		CATEGORY 6	MTH 01-Nov-2012 HRS 1762 LDG 1460		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30455 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY PW500-72-30455 R01)	ICT		CATEGORY 6	MTH 01-Nov-2012 HRS 1762 LDG 1460		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30462 R01 E1	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161 (SUPERSEDED BY PW500-72-30462 R02)			CATEGORY 8			-			
MOC :										
SB PW500-72-30462 R01 E2	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161 (SUPERSEDED BY PW500-72-30462 R02)			CATEGORY 8			-			
MOC :										
SB PW500-72-30462 R02 E1	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161			CATEGORY 8			-			
MOC :										
SB PW500-72-30462 R02 E2	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161			CATEGORY 8			-			
MOC :										
SB PW500-72-30462 E1	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161 (SUPERSEDED BY PW500-72-30462 R01)			CATEGORY 8			-			
MOC :										
SB PW500-72-30462 E2	CONVERSION OF PW545A BUILD SPECIFICATION 1156 TO 884 CONVERSION OF PW545B BUILD SPECIFICATION 1194 TO 1161 (SUPERSEDED BY PW500-72-30462 R01)			CATEGORY 8			-			
MOC :										
SB PW500-72-30463 R01 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY PW500-72-30463 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30463 R01 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY PW500-72-30463 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30463 R02 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30463 R02 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30463 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY PW500-72-30463 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30463 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY PW500-72-30463 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30464 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30464 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30465 R01 E1	REPLACEMENT OF FUEL MANIFOLD TUBES (SUPERSEDED BY PW500-72-30465 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30465 R01 E2	REPLACEMENT OF FUEL MANIFOLD TUBES (SUPERSEDED BY PW500-72-30465 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30465 R02 E1	REPLACEMENT OF FUEL MANIFOLD TUBES			CATEGORY 7			-			
	MOC :									
SB PW500-72-30465 R02 E2	REPLACEMENT OF FUEL MANIFOLD TUBES			CATEGORY 7			-			
	MOC :									
SB PW500-72-30465 E1	REPLACEMENT OF FUEL MANIFOLD TUBES (SUPERSEDED BY PW500-72-30465 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30465 E2	REPLACEMENT OF FUEL MANIFOLD TUBES (SUPERSEDED BY PW500-72-30465 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30466 R01 E1	REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY (SUPERSEDED BY PW500-72-30466 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30466 R01 E2	REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY (SUPERSEDED BY PW500-72-30466 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30466 R02 E1	REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30466 R02 E2	REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30466 E1	REPLACEMENT OF 2ND STAGE TURBINE VANE ASSY (SUPERSEDED BY PW500-72-30466 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30466 E2	REPLACEMENT OF 2ND STAGE TURBINE VANE ASSY (SUPERSEDED BY PW500-72-30466 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30470 R01 E1	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30470 R01 E2	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30470 E1	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30470 R01)	MCO		CATEGORY 7	MTH 13-Jun-2013 HRS 1909.3 LDG 1667		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30470 E2	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30470 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30472 R01 E1	REPLACEMENT OF - N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30472 R01 E2	REPLACEMENT OF - N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30472 E1	REPLACEMENT OF N1 AND N2 SPEED SENSORS (SUPERSEDED BY PW500-72-30470 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30472 E2	REPLACEMENT OF N1 AND N2 SPEED SENSORS (SUPERSEDED BY PW500-72-30470 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30475 R02 PART A E1	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY (SUPERSEDED BY PW500-72-30475 R03) /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
MOC :										
SB PW500-72-30475 R02 PART A E2	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY (SUPERSEDED BY PW500-72-30475 R03) /INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
MOC :										
SB PW500-72-30475 R02 PART B E1	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY (SUPERSEDED BY PW500-72-30475 R03) /INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
MOC :										
SB PW500-72-30475 R02 PART B E2	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY (SUPERSEDED BY PW500-72-30475 R03) /INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30475 R02 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY (SUPERSEDED BY PW500-72-30475 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R02 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY (SUPERSEDED BY PW500-72-30475 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R03 PART A E1	ACCOMPLISH REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY REMOVE AND INSTALL FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R03 PART A E2	ACCOMPLISH REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY REMOVE AND INSTALL FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R03 PART B E1	ACCOMPLISH REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY REMOVE AND INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R03 PART B E2	ACCOMPLISH REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY REMOVE AND INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R03 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R03 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30479 R01 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R02)			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R01 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R02)			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R02 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R03)			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R02 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R03)			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R03 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R04)			CATEGORY 5			-			
	MOC :									
SB PW500-72-30479 R03 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R04)			CATEGORY 5			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30479 R04 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R05)			CATEGORY 5						
MOC :										
SB PW500-72-30479 R04 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R05)			CATEGORY 5						
MOC :										
SB PW500-72-30479 R05 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R06)			CATEGORY 5						
MOC :										
SB PW500-72-30479 R05 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R06)			CATEGORY 5						
MOC :										
SB PW500-72-30479 R06 E1	REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 3	MTH HRS		DUE DUE DUE		5012.2	463.6
MOC :										
SB PW500-72-30479 R06 E2	REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			CATEGORY 3	MTH HRS		DUE DUE DUE		5012.2	463.6
MOC :										
SB PW500-72-30479 E1	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R01)			CATEGORY 6						
MOC :										
SB PW500-72-30479 E2	REPLACEMENT OF #4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE (SUPERSEDED BY PW500-72-30479 R01)			CATEGORY 6						
MOC :										
SB PW500-72-30482 R01 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY PW500-72-30482 R02)			CATEGORY 3						
MOC :										
SB PW500-72-30482 R01 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY PW500-72-30482 R02)			CATEGORY 3						
MOC :										
SB PW500-72-30482 R02 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY PW500-72-30482 R03)			CATEGORY 3						
MOC :										
SB PW500-72-30482 R02 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY PW500-72-30482 R03)			CATEGORY 3						
MOC :										
SB PW500-72-30482 R03 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R02)			CATEGORY 10						
MOC :										
SB PW500-72-30482 R03 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R02)			CATEGORY 10						
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30482 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY PW500-72-30482 R01)			CATEGORY 3			-			
	MOC :									
SB PW500-72-30482 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY PW500-72-30482 R01)			CATEGORY 3			-			
	MOC :									
SB PW500-72-30483 R01 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30483 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30483 R01 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30483 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30483 R02 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30483 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30483 R02 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30483 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30483 R03 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R02)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30483 R03 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R02)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30483 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30483 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30483 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30483 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30485 R01 E1	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE (SUPERSEDED BY PW500-72-3048 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30485 R01 E2	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE (SUPERSEDED BY PW500-72-3048 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30485 R02 E1	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30485 R02 E2	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30486 R01 E1	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING (SUPERSEDED BY PW500-72-30486 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30486 R01 E2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING (SUPERSEDED BY PW500-72-30486 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30486 R02 E1	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING.			CATEGORY 7			-			
MOC :										
SB PW500-72-30486 R02 E2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING.			CATEGORY 7			-			
MOC :										
SB PW500-72-30486 E1	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING (SUPERSEDED BY PW500-72-30486 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30486 E2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING (SUPERSEDED BY PW500-72-30486 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30487 R03 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502)			CATEGORY 10			-			
MOC :										
SB PW500-72-30487 R03 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502)			CATEGORY 10			-			
MOC :										
SB PW500-72-30487 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY PW500-72-30487 R01)						-			
MOC :										
SB PW500-72-30487 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY PW500-72-30487 R01)						-			
MOC :										
SB PW500-72-30491 R01 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30491 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30491 R01 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30491 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30491 R02 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30491 R02 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30491 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30491 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30491 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY PW500-72-30491 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30492 R01 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30492 R01 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30492 R02 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30492 R02 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30492 R03 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30492 R03 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30492 R04 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER			CATEGORY 6			-			
	MOC :									
SB PW500-72-30492 R04 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER			CATEGORY 6			-			
	MOC :									
SB PW500-72-30492 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30492 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30495 R01 E1	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY PW500-72-30498)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30495 R01 E2	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY PW500-72-30498)			CATEGORY 10			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30495 E1	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY SB PW500-72-30495 R01)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30495 E2	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY SB PW500-72-30495 R01)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30496 R01 E1	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30496 R01 E2	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30496 E1	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE (SUPERSEDED BY PW500-72-30496 R01)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30496 E2	REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE (SUPERSEDED BY PW500-72-30496 R01)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30498 R01 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30498 R01 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30498 R02 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30498 R02 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R03)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30498 R03 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30498 R03 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30498 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30498 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R01)			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30502 R01 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R01 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R02 PART A E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03) FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R02 PART A E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03) FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R02 PART B E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03) ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R02 PART B E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03) ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R02 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R02 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R03 PART A E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04) REPLACE FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R03 PART A E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04) REPLACE FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R03 PART B E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04) REPLACE ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R03 PART B E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04) REPLACE ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R03 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04)			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R03 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04)			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30502 R04 PART A E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7				FUEL CONTROL GEARSHAFT SEAL		
	MOC :									
SB PW500-72-30502 R04 PART A E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7				FUEL CONTROL GEARSHAFT SEAL		
	MOC :									
SB PW500-72-30502 R04 PART B E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7				ACCESSORY GEARSHAFT SEAL		
	MOC :									
SB PW500-72-30502 R04 PART B E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7				ACCESSORY GEARSHAFT SEAL		
	MOC :									
SB PW500-72-30502 R04 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7						
	MOC :									
SB PW500-72-30502 R04 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7						
	MOC :									
SB PW500-72-30502 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R01)			CATEGORY 7						
	MOC :									
SB PW500-72-30502 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R01)			CATEGORY 7						
	MOC :									
SB PW500-72-30504 R01 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R02)			CATEGORY 7						
	MOC :									
SB PW500-72-30504 R01 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R02)			CATEGORY 7						
	MOC :									
SB PW500-72-30504 R02 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7						
	MOC :									
SB PW500-72-30504 R02 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7						
	MOC :									
SB PW500-72-30504 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R01)			CATEGORY 7						
	MOC :									
SB PW500-72-30504 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R01)			CATEGORY 7						
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30505 R01 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R02)			CATEGORY 3			-			
MOC :										
SB PW500-72-30505 R01 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R02)			CATEGORY 3			-			
MOC :										
SB PW500-72-30505 R02 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS	KMCO		CATEGORY 3	MTH 19-Jun-2015 HRS 2888.5 LDG 2899		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH 500-72-30505 R2 LEAK CHECK GOOD										
SB PW500-72-30505 R02 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS	KMCO		CATEGORY 3	MTH 19-Jun-2015 HRS 2888.5 LDG 2899		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PRATT & WHITNEY S.B. NO. PW 500-72-30505R2, LEAK CHECK GOOD.										
SB PW500-72-30505 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R01)	KMCO		CATEGORY 3	MTH 04-Dec-2014 HRS 2648.1 LDG 2620		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB PW500-72-30505 BY REPLACEMENT OF BLEED VALVE (BOV) GASKETS ON L/H ENGINE. LEAK CHECK GOOD.										
SB PW500-72-30505 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R01)			CATEGORY 3			-			
MOC :										
SB PW500-72-30506 R01 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30506 R01 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30506 R02 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
MOC :										
SB PW500-72-30506 R02 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
MOC :										
SB PW500-72-30506 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30506 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30507 E1	MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 8			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30507 E2	MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 8			-			
MOC :										
SB PW500-72-30508 R01 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS (SUPERSEDED BY PW500-72-30508 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30508 R01 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS (SUPERSEDED BY PW500-72-30508 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30508 R02 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30508 R02 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30508 R03 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30508 R03 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30508 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS (SUPERSEDED BY PW500-72-30508 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30508 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS (SUPERSEDED BY PW500-72-30508 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30511 R01 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS			CATEGORY 6			-			
MOC :										
SB PW500-72-30511 R01 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS			CATEGORY 6			-			
MOC :										
SB PW500-72-30511 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS (SUPERSEDED BY PW500-72-30511 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30511 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS (SUPERSEDED BY PW500-72-30511 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30512 R01 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R02)			CATEGORY 3			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30512 R01 E2	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R02)			CATEGORY 3			-			
MOC :										
SB PW500-72-30512 R02 E1	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R03)	KMCO		CATEGORY 3	MTH 10-Dec-2015 HRS 3091.4 LDG 3135		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH BY REPLACING FMU IAW PWC 545B MM CHAPTER 73-20-01 AND PW SB500-72-30512R2 INSTRUCTIONS. OPERATION AND LEAK GOOD.										
SB PW500-72-30512 R02 E2	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R03)	KMCO		CATEGORY 3	MTH 10-Dec-2015 HRS 3091.4 LDG 3135		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH BY REPLACING FMU IAW PWC 545B MM CHAPTER 73-20-01 AND PW SB500-72-30512R2 INSTRUCTIONS. OPERATION AND LEAK GOOD.										
SB PW500-72-30512 R03 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R04)			CATEGORY 3	MTH		-			
MOC :										
SB PW500-72-30512 R03 E2	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R04)			CATEGORY 3	MTH		-			
MOC :										
SB PW500-72-30512 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R01)			CATEGORY 3			-			
MOC :										
SB PW500-72-30512 E2	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R01)			CATEGORY 3			-			
MOC :										
SB PW500-72-30516 R01 E1	REPLACEMENT OF HP TURBINE SEAL RINGS (SUPERSEDED BY PW500-72-30516 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30516 R01 E2	REPLACEMENT OF HP TURBINE SEAL RINGS (SUPERSEDED BY PW500-72-30516 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30516 R02 E1	REPLACEMENT OF HP TURBINE SEAL RINGS			CATEGORY 7			-			
MOC :										
SB PW500-72-30516 R02 E2	REPLACEMENT OF HP TURBINE SEAL RINGS			CATEGORY 7			-			
MOC :										
SB PW500-72-30517 R01 E1	DELETION OF IGNITER FLANGE GASKETS			CATEGORY 6			-			
MOC :										
SB PW500-72-30517 R01 E2	DELETION OF IGNITER FLANGE GASKETS			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30517 E1	DELETION OF IGNITER FLANGE GASKETS (SUPERSEDED BY PW500-72-30517 R01)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30517 E2	DELETION OF IGNITER FLANGE GASKETS (SUPERSEDED BY PW500-72-30517 R01)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30518 E1	SALEABILITY CHANGE - TURBINE EXHAUST CASE END CONE			CATEGORY 9			-			
	MOC :									
SB PW500-72-30518 E2	SALEABILITY CHANGE - TURBINE EXHAUST CASE END CONE			CATEGORY 9			-			
	MOC :									
SB PW500-72-30521 R01 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30521 R01 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30523 R01 E1	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET			CATEGORY 7			-			
	MOC :									
SB PW500-72-30523 R01 E2	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET			CATEGORY 7			-			
	MOC :									
SB PW500-72-30523 E1	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET (SUPERSEDED BY PW500-72-30523 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30523 E2	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET (SUPERSEDED BY PW500-72-30523 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30526 E1	MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW500-72-30526 E2	MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW500-72-30527 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
	MOC :									
SB PW500-72-30527 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
	MOC :									
SB PW500-72-30534 R01 E1	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R02)			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30534 R01 E2	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30534 R02 E1	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30534 R02 E2	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30534 R03 E1	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R04)			CATEGORY 7			-			
MOC :										
SB PW500-72-30534 R03 E2	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R04)			CATEGORY 7			-			
MOC :										
SB PW500-72-30534 R04 E1	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30534 R04 E2	REPLACEMENT OF DATA COLLECTION UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30534 E1	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30534 E2	REPLACEMENT OF DATA COLLECTION UNIT (SUPERSEDED BY PW500-72-30534 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30535 R01 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER			CATEGORY 7			-			
MOC :										
SB PW500-72-30535 R01 E2	REPLACEMENT OF ENGINE SHIPPING CONTAINER			CATEGORY 7			-			
MOC :										
SB PW500-72-30535 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER (SUPERSEDED BY PW500-72-30535 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30535 E2	REPLACEMENT OF ENGINE SHIPPING CONTAINER (SUPERSEDED BY PW500-72-30535 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30540 E1	REPLACEMENT OF HIGH PRESSURE TURBINE AIR SEAL						-			
MOC :										
SB PW500-72-30540 E2	REPLACEMENT OF HIGH PRESSURE TURBINE AIR SEAL						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30541 PART A E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30541 R01) FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 PART A E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30541 R01) FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 PART B E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30541 R01) ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 PART B E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30541 R01) ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 PART A E1	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 PART A E2	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 PART B E1	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 PART B E2	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30541 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30541 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30542 E1	REPLACEMENT OF IGNITER CABLES			CATEGORY 7			-			
	MOC :									
SB PW500-72-30542 E2	REPLACEMENT OF IGNITER CABLES			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30543 R01 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
MOC :										
SB PW500-72-30543 R01 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
MOC :										
SB PW500-72-30543 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS (SUPERSEDED BY PW500-72-30543 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30543 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS (SUPERSEDED BY PW500-72-30543 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30545 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3	MTH HRS		6 300		28-Mar-2019 4733.93	2 m 19 d 185.33
MOC :										
SB PW500-72-30545 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3	MTH HRS		6 300		28-Mar-2019 4733.93	2 m 19 d 185.33
MOC :										
SB PW500-72-30548 R01 E1	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE (SUPERSEDED BY PW500-72-30548 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30548 R01 E2	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE (SUPERSEDED BY PW500-72-30548 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30548 R02 E1	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE			CATEGORY 7			-			
MOC :										
SB PW500-72-30548 R02 E2	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE			CATEGORY 7			-			
MOC :										
SB PW500-72-30548 E1	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE (SUPERSEDED BY PW500-72-30548 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30548 E2	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE (SUPERSEDED BY PW500-72-30548 R01)			CATEGORY 7			-			
MOC :										
ASB PW500-72-A30421 R02 E1	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE			CATEGORY 3			-			
MOC :										
ASB PW500-72-A30421 R02 E2	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE			CATEGORY 3			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
ASB PW500-72- A30452 R01 E1	TURBOFAN ENGINE - OIL SYSTEM - SPECIAL INSPECTION OF MOP (SUPERSEDED BY PW500-72-A30452 R02)			CATEGORY 3	MTH		-			
MOC :										
ASB PW500-72- A30452 R01 E2	TURBOFAN ENGINE - OIL SYSTEM - SPECIAL INSPECTION OF MOP (SUPERSEDED BY PW500-72-A30452 R02)			CATEGORY 3	MTH		-			
MOC :										
ASB PW500-72- A30452 R02 E1	SPECIAL INSPECTION OF MOP OIL SYSTEM (CANCELLED)			CATEGORY 10			-			
MOC :										
ASB PW500-72- A30452 R02 E2	SPECIAL INSPECTION OF MOP OIL SYSTEM (CANCELLED)			CATEGORY 10			-			
MOC :										
ASB PW500-72- A30452 E1	TURBOFAN ENGINE OIL SYSTEM - SPECIAL INSPECTION OF MOP (SUPERSEDED BY PW500-72-A30452 R01)	BLL		CATEGORY 3	MTH	20-Feb-2012	-			N/A
					HRS	1669				
					LDG	1393				
MOC : NOT APPLICABLE										
ASB PW500-72- A30452 E2	TURBOFAN ENGINE OIL SYSTEM - SPECIAL INSPECTION OF MOP (SUPERSEDED BY PW500-72-A30452 R01)	BLL		CATEGORY 3	MTH	20-Feb-2012	-			N/A
					HRS	1669				
					LDG	1393				
MOC : NOT APPLICABLE										
SL 560XL-73-12 R01	ENGINE FUEL AND CONTROL - TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30381R2, FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE/FAIRING/REPLACEMENT OF	BLL		RECOMMENDED	MTH	22-Dec-2011		A/R		N/A
					HRS	1602				
					LDG	1305				
MOC : NOT APPLICABLE - CW PR. ORIGINAL ISSUE OF SL. REV. 1 HAS NO EFFECT ON AIRCRAFT										
SL 560XL-73-12 73SL-12 : XL	ENGINE FUEL AND CONTROL - TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30381R2, FUEL MANIFOLD AND FUEL SHUT-OFF CABLE GROMMETS AND COVERPLATE/FAIRING/REPLACEMENT OF (SUPERSEDED BY SL560XL-73-12 R01)	BLL		RECOMMENDED	MTH	29-Jan-2010		A/R		Complete
					HRS	915				
MOC : COMPLIED WITH										
SB PW30381R2 E1	P & W SB30381R1	BLL			MTH	07-Dec-2009		-		Complete
					HRS	928				
MOC : COMPLIED WITH										
SB PW30381R2 E2	P & W SB30381R1	BLL			MTH	03-Dec-2009		-		Complete
					HRS	925				
MOC : COMPLIED WITH										
SB PW500-72- 30343 R03 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE (SUPERSEDED BY PW500-72-30343 R04)	BLL		CATEGORY 7	MTH	21-Jan-2009		-		Complete
					HRS	583				
					LDG	497				
MOC : COMPLIED WITH - PWC SB 30343R3 CW PR SB										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30343 R03 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE (SUPERSEDED BY PW500-72-30343 R04)	BLL		CATEGORY 7	MTH 21-Jan-2009 HRS 583 LDG 497		-			Complete
MOC : COMPLIED WITH - PWC SB 30343R3 CW PR SB										
SB PW500-72-30343 R05 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE (SUPERSEDED BY PW500-72-30343 R06)			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30343 R05 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE (SUPERSEDED BY PW500-72-30343 R06)			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30404 R03 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30404 R03 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30414 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 10			A/R			
MOC :										
SB PW500-72-30414 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE			CATEGORY 10			A/R			
MOC :										
ASB PW500-72-A30421 R01 E1	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R02)	BLL		CATEGORY 3	MTH 02-Nov-2010 HRS 1282 LDG 1059		-			N/A
MOC : NOT APPLICABLE - ASB IS NOT ACTUAL TO PART INSTALLED. THE PART HAS MORE THAN 250 HRS. INSTALLED. REF. 6-3.										
ASB PW500-72-A30421 R01 E2	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R02)	BLL		CATEGORY 3	MTH 02-Nov-2010 HRS 1282 LDG 1059		-			N/A
MOC : NOT APPLICABLE - ASB PW500-72-A30421 R1 IS NOT ACTUEL ON INSTALLED PART. PART HAS MORE THAN 250 HRS OF RUNNING TIME.REF. CESCOM 8-3.										
ASB PW500-72-A30421 E1	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R01)	BLL		CATEGORY 3	MTH 03-Sep-2010 HRS 1205 LDG 995		-			N/A
MOC : NOT APPLICABLE - AD IS NOT ACTUAL TO PART INSTALLED. THE PART HAS MORE THAN 250 HRS. INSTALLED. REF. CESCOM 6 -3.										
ASB PW500-72-A30421 E2	INSPECTION/REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/SERVO-VALVE (SUPERSEDED BY PW500-72-A30421 R01)	BLL		CATEGORY 3	MTH 03-Sep-2010 HRS 1205 LDG 995		-			N/A
MOC : NOT APPLICABLE - AD IS NOT ACTUAL TO PART INSTALLED. THE PART HAS MORE THAN 250 HRS. INSTALLED. REF. CESCOM 8 -3										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)			MANDATORY			-			
MOC :										
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS			MANDATORY			-			
MOC :										
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION			MANDATORY			-			
MOC :										
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM			MANDATORY			A/R			
MOC :										
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM			MANDATORY			A/R			
MOC :										
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS			MANDATORY			-			
MOC :										
FAA 2013-09-11 PARA (N)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM			MANDATORY			-			
MOC :										
FAA 2017-04-14 PARA (G)	ACCOMPLISH GENERAL VISUAL INSPECTIONS OF THE FUEL TUBE AND RIGHT ALTERNATING CURRENT (AC) GENERATOR WIRES FOR EVIDENCE OF DAMAGE, ALL APPLICABLE ADJUSTMENTS, AND ALL APPLICABLE CORRECTIVE ACTIONS	KMCO		MANDATORY	DAYS 08-Mar-2017		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD2017-04-14 EFFECTIVE DATE MAR 09,2017 BY COMPLYING WITH SL560XL-24-07 INSTRUCTIONS. REPORT SENT TO TEAM XL.										
FAA 2017-04-14 PARA (H)	SUBMIT A REPORT OF THE FINDINGS (BOTH POSITIVE AND NEGATIVE) OF THE INSPECTIONS REQUIRED BY PARAGRAPH (G) OF THIS AD TO TEXTRON AVIATION	KMCO		MANDATORY	DAYS 08-Mar-2017		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD2017-04-14 EFFECTIVE DATE MAR 09,2017 BY COMPLYING WITH SL560XL-24-07 INSTRUCTIONS. REPORT SENT TO TEAM XL.										
FAA 2017-04-14	ELECTRICAL POWER - INSPECTIONS OF THE FUEL TUBE AND RIGHT ALTERNATING CURRENT (AC) GENERATOR WIRES	KMCO		MANDATORY	MTH 08-Mar-2017		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD2017-04-14 EFFECTIVE DATE MAR 09,2017 BY COMPLYING WITH SL560XL-24-07 INSTRUCTIONS.										
FAA 1974-08-09 R02 053801	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION	BLL		MANDATORY	MTH 19-Mar-2010		-			Complete
MOC : COMPLIED WITH - COMMENTS: AD74-08-09REV2 PERF.										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION	KMCO		MANDATORY	MTH 04-Feb-2018 HRS 4035.2 LDG 4216		1000		5035.2	Complete 486.6
MOC : COMPLIED WITH - COMPLIED WITH AD 74-08-09 R3 (K(1) EFFECTIVE DATE MARCH 28, 2012. NEXT DUE 5035.2.										
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2			MANDATORY			-			
MOC :										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK			MANDATORY			-			
MOC :										
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS			MANDATORY			-			
MOC :										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT			MANDATORY	MTH		-			
MOC :										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KMCO			MTH 18-Jul-2018 HRS 4323.7 LDG 4518		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2017-16-01 EFFECTIVE DATE 24/OCT/2017 BY VISUAL INSPECTION, FOUND EQUIPMENT IS NOT INSTALLED IN AIRCRAFT NO FURTHER ACTION REQUIRED, ALL MAINTENANCE DONE IAW AD INSTRUCTIONS.										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	KMCO		MANDATORY	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2017-16-01 EFFECTIVE DATE 24/OCT/2017 BY VISUAL INSPECTION, FOUND EQUIPMENT IS NOT INSTALLED IN AIRCRAFT NO FURTHER ACTION REQUIRED, ALL MAINTENANCE DONE IAW AD INSTRUCTIONS.										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	KMCO		MANDATORY	MTH 18-Jul-2018 HRS 4323.7 LDG 4518		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2017-16-01 EFFECTIVE DATE 24/OCT/2017 BY VISUAL INSPECTION, FOUND EQUIPMENT IS NOT INSTALLED IN AIRCRAFT NO FURTHER ACTION REQUIRED, ALL MAINTENANCE DONE IAW AD INSTRUCTIONS.										
FAA 2012-09-01	LANDING GEAR - TORQUE LUG - INSPECTION	EKBI		MANDATORY	MTH 11-May-2012 HRS 1689 LDG 1378		-			Complete
MOC : COMPLIED WITH - AD 2012-09-01 PERF. PR. SB560XL-32-41R1 - TRANSMITTAL OF GOODRICH SB 3-1571-32-7.										
FAA 1999-23-22 R01	APPLIANCE AD - TRANSPORT CATEGORY MODE C XPD			MANDATORY			-			
MOC :										
FAA 1999-23-22 R02	APPLIANCE AD - TRANSPORT CATEGORY MODE C XPD			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2001-23-17 <i>34AD-09 : XL</i>	APPLIANCE AD - GARMIN INTERNATIONAL ICT		GNS 430 MANDATORY	MTH 19-Jan-2008 HRS 8		A/R			N/A
MOC : NOT APPLICABLE									
FAA 2006-22-05 <i>34AD-15 : XL</i>	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM ICT		MANDATORY	MTH 19-Jan-2008 HRS 8		A/R			N/A
MOC : NOT APPLICABLE									
FAA 2010-07-02	PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)	BLL	MANDATORY	MTH 09-Apr-2010 HRS 1020 LDG 817		A/R			Complete
MOC : COMPLIED WITH - AT MANUFACTURE									
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	ICT	MANDATORY	MTH 27-Jun-2012 HRS 1715 LDG 1393		-			Complete
MOC : COMPLIED WITH									
FAA 2012-26-15 PARA (G)(1)	REMOVE IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) (RESCINDED BY FAA 2012-26-15 R01) AFFECTED ADC, ADM, ADAHRS, OR DADC	MCO	MANDATORY	DAYS 16-Jan-2013 HRS 1731.8 LDG 1413		-			N/A
MOC : NOT APPLICABLE - AD IS EFFECTIVE JANUARY 24, 2013, AND IS NOT RELEVANT BY UNIT PART NUMBER IAW HONEYWELL SERVICE BULLETIN ADM/ADC/ADAHRS 34A01, DATED NOVEMBER 6, 2012. NO FURTHER ACTION REQUIRED.									
FAA 2012-26-15 PARA (G)(2)	PERFORM IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) (RESCINDED BY FAA 2012-26-15 R01) PITOT-STATIC CERTIFICATION TEST	MCO		DAYS 16-Jan-2013 HRS 1731.8 LDG 1413		-			N/A
MOC : NOT APPLICABLE - AD IS EFFECTIVE JANUARY 24, 2013, AND IS NOT RELEVANT BY UNIT PART NUMBER IAW HONEYWELL SERVICE BULLETIN ADM/ADC/ADAHRS 34A01, DATED NOVEMBER 6, 2012. NO FURTHER ACTION REQUIRED.									
FAA 2012-26-15 R01	APPLIANCE AD - AIR DATA PRESSURE TRANSDUCERS, AS INSTALLED IN AIR DATA COMPUTERS (ADC), AIR DATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS), AND DIGITAL AIR DATA COMPUTERS (DADC)	KMCO	MANDATORY	MTH 04-Dec-2014 HRS 2601.1 LDG 2533		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD 2012-26-15 R1 EFFECTIVE DATE DECEMBER 3 2014, BY INSPECTION, AFFECTED SERIAL NUMBER NOT INSTALLED IN AIRCRAFT AS PER TABLE 6 ON HONEYWELL SERVICE BULLETIN ADM/ADC/ADHRS-43-A01. ADC INSTALLED, P/N 7030700-71703 NO.1 S/N 07081512, NO.2 S/N 07081583.									
FAA 2012-26-15	APPLIANCE AD - IDENTIFY OUT OF SPEC AIR DATA COMPUTERS (ADC), AIRDATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS) AND DIGITAL AIR DATA COMPUTERS (DADC) (RESCINDED BY FAA 2012-26-15 R01)	MCO	MANDATORY	MTH 16-Jan-2013 HRS 1731.8 LDG 1413		-			N/A
MOC : NOT APPLICABLE - AD IS EFFECTIVE JANUARY 24, 2013, AND IS NOT RELEVANT BY UNIT PART NUMBER IAW HONEYWELL SERVICE BULLETIN ADM/ADC/ADAHRS 34A01, DATED NOVEMBER 6, 2012. NO FURTHER ACTION REQUIRED.									
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION		MANDATORY	MTH		-			
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-10-51-E	APPLIANCE AD - AVIADYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.		MANDATORY	MTH		-			
MOC :									
FAA 2015-10-51	APPLIANCE AD - AVIADYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS		MANDATORY			-			
MOC :									
EASA 2011-0090 R1	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS - IDENTIFICATION / REPLACEMENT - INTERTECHNIQUE (PART OF ZODIAC AEROSPACE), EROS	EKBI	MANDATORY	MTH 18-Oct-2011 HRS 1535 LDG 1257		-			N/A
MOC : NOT APPLICABLE									
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	KMCO	MANDATORY	MTH 10-Dec-2015 HRS 3044.4 LDG 3068		-			N/A
MOC : NOT APPLICABLE - INSPECTED PILOT AND CO-PILOTS O2 MASKS AND FOUND AD2015-08-07 EFFECTIVE DATE MARCH 28, 2012 DOES NOT APPLY DUE TO REGULATOR P/N MC10-16-150 BEING INSTALLED ON AIRCRAFT. NO FURTHER ACTION REQUIRED.									
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PARAGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	KMCO	MANDATORY	MTH 10-Dec-2015 HRS 3044.4 LDG 3068		-			N/A
MOC : NOT APPLICABLE - INSPECTED PILOT AND CO-PILOTS O2 MASKS AND FOUND AD2015-08-07 EFFECTIVE DATE MARCH 28, 2012 DOES NOT APPLY DUE TO REGULATOR P/N MC10-16-150 BEING INSTALLED ON AIRCRAFT. NO FURTHER ACTION REQUIRED.									
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES	KMCO	MANDATORY	MTH 10-Dec-2015 HRS 3044.4 LDG 3068		-			N/A
MOC : NOT APPLICABLE - INSPECTED PILOT AND CO-PILOTS O2 MASKS AND FOUND AD2015-08-07 EFFECTIVE DATE MARCH 28, 2012 DOES NOT APPLY DUE TO REGULATOR P/N MC10-16-150 BEING INSTALLED ON AIRCRAFT. NO FURTHER ACTION REQUIRED.									
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KMCO	MANDATORY	MTH 10-Dec-2015 DAYS 3044.4 HRS 3068 LDG		-			N/A
MOC : NOT APPLICABLE - INSPECTED PILOT AND CO-PILOT O2 MASKS AND FOUND AD2015-23-09 EFFECTIVE DATE DECEMBER 28, 2015 DOES NOT APPLY DUE TO P/N MC10-16-150 INSTALLED IN AIRCRAFT. NO FURTHER ACTION REQUIRED.									
FAA 2015-23-09 PARA (H)(1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KMCO	MANDATORY	MTH 10-Dec-2015 DAYS 3044.4 HRS 3068 LDG		-			N/A
MOC : NOT APPLICABLE - INSPECTED PILOT AND CO-PILOT O2 MASKS AND FOUND AD2015-23-09 EFFECTIVE DATE DECEMBER 28, 2015 DOES NOT APPLY DUE TO P/N MC10-16-150 INSTALLED IN AIRCRAFT. NO FURTHER ACTION REQUIRED.									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-23-09 PARA (H)(2)(I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KMCO		MANDATORY	MTH 10-Dec-2015 DAYS 3044.4 HRS 3068 LDG		-			N/A
MOC : NOT APPLICABLE - INSPECTED PILOT AND CO-PILOT O2 MASKS AND FOUND AD2015-23-09 EFFECTIVE DATE DECEMBER 28, 2015 DOES NOT APPLY DUE TO P/N MC10-16-150 INSTALLED IN AIRCRAFT. NO FURTHER ACTIONREQUIRED.										
FAA 2015-23-09 PARA (H)(2)(II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KMCO		MANDATORY	MTH 10-Dec-2015 DAYS 3044.4 HRS 3068 LDG		-			N/A
MOC : NOT APPLICABLE - INSPECTED PILOT AND CO-PILOT O2 MASKS AND FOUND AD2015-23-09 EFFECTIVE DATE DECEMBER 28, 2015 DOES NOT APPLY DUE TO P/N MC10-16-150 INSTALLED IN AIRCRAFT. NO FURTHER ACTIONREQUIRED.										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KMCO		MANDATORY	MTH 10-Dec-2015 HRS 3044.4 LDG 3068		-			N/A
MOC : NOT APPLICABLE - INSPECTED PILOT AND CO-PILOT O2 MASKS AND FOUND AD2015-23-09 EFFECTIVE DATE DECEMBER 28, 2015 DOES NOT APPLY DUE TO P/N MC10-16-150 INSTALLED IN AIRCRAFT. NO FURTHER ACTIONREQUIRED.										
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KMCO		MANDATORY	MTH 10-Dec-2015 HRS 3044.4 LDG 3068		-			N/A
MOC : NOT APPLICABLE - INSPECTED PILOT AND CO-PILOT O2 MASKS AND FOUND AD2015-23-09 EFFECTIVE DATE DECEMBER 28, 2015 DOES NOT APPLY DUE TO P/N MC10-16-150 INSTALLED IN AIRCRAFT. NO FURTHER ACTIONREQUIRED.										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A..1 SUPERSEDED BY FAA AD 2017-18-12	MCO		MANDATORY	MTH 10-Jul-2016 HRS 3318.1 LDG 3360		-			N/A
MOC : NOT APPLICABLE										
FAA 2016-11-20 PARA (H)(1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	MCO		MANDATORY	MTH 10-Jul-2016 HRS 3318.1 LDG 3360		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2016-11-20 PARAGRAPH (H)(1) EFFECTIVE DATE JULY 15, 2016. ESSEX PB&R PROTECTIVE BREATHING EQUIPMENT INSTALLED IN PILOT AND COPILOT POSITIONS NOT B/E AEROSPACE PBE. NO FURTHER ACTION REQUIRED.										
FAA 2016-11-20 PARA (H)(2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	MCO		MANDATORY	MTH 10-Jul-2016 HRS 3318.1 LDG 3360		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2016-11-20 PARAGRAPH (H)(2) EFFECTIVE DATE JULY 15, 2016. ESSEX PB&R PROTECTIVE BREATHING EQUIPMENT INSTALLED IN PILOT AND COPILOT POSITIONS NOT B/E AEROSPACE PBE. NO FURTHER ACTION REQUIRED.										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	MCO	MANDATORY	MTH 10-Jul-2016 HRS 3318.1 LDG 3360		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD2016-11-20 EFFECTIVE DATE JULY 15, 2016. ESSEX PB&R PROTECTIVE BREATHING EQUIPMENT INSTALLED IN PILOT AND COPILOT POSITIONS NOT B/E AEROSPACE PBE. NO FURTHER ACTION REQUIRED.									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KMCO	MANDATORY	MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2017-18-12, EFFECTIVE DATE: OCTOBER16, 2017 BY INSPECTION AND FOUND THE EQUIPMENT LISTED IN THIS AD IS NOT INSTALLED IN THIS AIRCRAFT. NO ACTION REQUIRED.									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KMCO	MANDATORY	MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2017-18-12, EFFECTIVE DATE: OCTOBER16, 2017 BY INSPECTION AND FOUND THE EQUIPMENT LISTED IN THIS AD IS NOT INSTALLED IN THIS AIRCRAFT. NO ACTION REQUIRED.									
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KMCO	MANDATORY	MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2017-18-12, EFFECTIVE DATE: OCTOBER16, 2017 BY INSPECTION AND FOUND THE EQUIPMENT LISTED IN THIS AD IS NOT INSTALLED IN THIS AIRCRAFT. NO ACTION REQUIRED.									
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	KMCO	MANDATORY	MTH 27-Dec-2017 HRS 3977.6 LDG 4149 APUH 1898.5 APUS 4229		-			N/A
MOC : NOT APPLICABLE - COMPLIED WITH AD 2017-18-12, EFFECTIVE DATE: OCTOBER16, 2017 BY INSPECTION AND FOUND THE EQUIPMENT LISTED IN THIS AD IS NOT INSTALLED IN THIS AIRCRAFT. NO ACTION REQUIRED.									
FAA 2012-06-01	MODIFY THE DRAIN INSTALLATION OF THE TAILCONE STINGER ON THE AFT CANTED BULKHEAD	ICT	MANDATORY	MTH 27-Jun-2012 HRS 1715 LDG 1393		-			Complete
MOC : COMPLIED WITH									
FAA 2010-18-09 PARA (E)(2) E1	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE	BLL	MANDATORY	MTH 02-Nov-2010 HRS 1282 LDG 1059		-			N/A
MOC : NOT APPLICABLE - ASB IS NOT ACTUAL TO PART INSTALLED. THE PART HAS MORE THAN 250 HRS. INSTALLED. REF. 6-3.									



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2010-18-09 PARA (E)(2) E2	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE REMOVE	BLL		MANDATORY	MTH 02-Nov-2010 HRS 1282 LDG 1059		-			N/A
MOC : NOT APPLICABLE - ASB PW500-72-A30421 R1 IS NOT ACTUEL ON INSTALLED PART. PART HAS MORE THAN 250 HRS OF RUNNING TIME.REF. CESCOM 8-3.										
FAA 2010-18-09 PARA (E)(3) E1	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING	BLL		MANDATORY	MTH 03-Sep-2010 HRS 1205 LDG 995		-			N/A
MOC : NOT APPLICABLE - AD IS NOT ACTUAL TO PART INSTALLED. THE PART HAS MORE THAN 250 HRS. INSTALLED. REF. CESCOM 6 -3.										
FAA 2010-18-09 PARA (E)(3) E2	ACCOMPLISH INTERCOMPRESSOR BLEED VALVE/SERVO VALVE ENGINE TESTING	BLL		MANDATORY	MTH 03-Sep-2010 HRS 1205 LDG 995		-			N/A
MOC : NOT APPLICABLE - AD IS NOT ACTUAL TO PART INSTALLED. THE PART HAS MORE THAN 250 HRS. INSTALLED. REF. CESCOM 8 -3										
FAA 2010-18-09 E1	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE	BLL		MANDATORY	MTH 02-Nov-2010 HRS 1282 LDG 1059		-			N/A
MOC : NOT APPLICABLE - ASB IS NOT ACTUAL TO PART INSTALLED. THE PART HAS MORE THAN 250 HRS. INSTALLED. REF. 6-3.										
FAA 2010-18-09 E2	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE	BLL		MANDATORY	MTH 02-Nov-2010 HRS 1282 LDG 1059		-			N/A
MOC : NOT APPLICABLE - ASB PW500-72-A30421 R1 IS NOT ACTUEL ON INSTALLED PART. PART HAS MORE THAN 250 HRS OF RUNNING TIME.REF. CESCOM 8-3.										
TCCA CF-2010-19 STEP A,B,C,D,E,F,G E1	INCORPORATION INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION OF ASB A30421			MANDATORY	MTH 10-Sep-2014 HRS 2512.2 LDG 2402		A/R			Complete
MOC : COMPLIED WITH										
TCCA CF-2010-19 STEP A,B,C,D,E,F,G E2	INCORPORATION INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION OF ASB A30421			MANDATORY	MTH 10-Sep-2014 HRS 2512.2 LDG 2402		A/R			Complete
MOC : COMPLIED WITH										
TCCA CF-2010-19 STEP H. E1	TEST INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION PROCEDURE PART A			MANDATORY	MTH 10-Sep-2014 HRS 2512.2 LDG 2402		A/R			Complete
MOC : COMPLIED WITH										
TCCA CF-2010-19 STEP H. E2	TEST INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION PROCEDURE PART A			MANDATORY	MTH 10-Sep-2014 HRS 2512.2 LDG 2402		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
TCCA CF-2010-19 E1	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION	MANDATORY	MTH 10-Sep-2014 HRS 2512.2 LDG 2402				A/R			Complete

MOC : COMPLIED WITH

TCCA CF-2010-19 E2	INTERCOMPRESSOR BLEED VALVE/SERVO VALVE MALFUNCTION	MANDATORY	MTH 10-Sep-2014 HRS 2512.2 LDG 2402				A/R			Complete
-----------------------	---	-----------	---	--	--	--	-----	--	--	----------

MOC : COMPLIED WITH



CESCOM 10 - Aircraft Status Report

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	4548.6	4778	07-Jan-2019	.9
ENG 1	4501.6	4711	07-Jan-2019	.92
ENG 2	4501.6	4711	07-Jan-2019	.92
APU	2202	4829	07-Jan-2019	.53

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
23FO-01XL <i>23FO-01 : XL</i>	ST-3100 TELEPHONE SYS AIRCELL FACTORY OPTION	*CF		807D FO	MTH 19-Jan-2008		-			
23FO-05XL/C <i>23FO-05 : XL/C</i>	RECORDER: FLIGHT DATA JAA ALLIEDSIGNAL FACTORY OPTION	*CF		634C FO	MTH 19-Jan-2008		-			
25FO-04XL <i>25FO-04 : XL</i>	COCKPIT SPEAKER MUTE FACTORY OPTION	*CF		674B FO	MTH 19-Jan-2008		-			
34FO-06XL/E <i>34FO-06 : XL/E</i>	2ND ADF: HONEYWELL FACTORY OPTION	*CF		659E FO	MTH 19-Jan-2008		-			
34FO-22XL <i>34FO-22 : XL</i>	UNS-1ESP (SECOND) UNIVERSAL FACTORY OPTION	*CF		697Q FO	MTH 19-Jan-2008		-			
34FO-23XL <i>34FO-23 : XL</i>	PERFORMANCE DATABASE- UNIVERSA FACTORY OPTION	*CF		698F FO	MTH 19-Jan-2008		-			
34FO-26XL <i>34FO-26 : XL</i>	DUAL MODE S DIV XPDR W EN SURV FACTORY OPTION	*CF		624F FO	MTH 19-Jan-2008		-			
34FO-31XL <i>34FO-31 : XL</i>	UL701 UNILINK-UNIVERSAL PROVIS FACTORY OPTION	*CF		675Q FO	MTH 19-Jan-2008		-			
73FO-01XL <i>73FO-01 : XL</i>	CHIP DETECTOR: ENGINE FACTORY OPTION	*CF		10M FO	MTH 19-Jan-2008		-			