



CESCOM 20 - Projected Maintenance Due

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**

Aircraft Model: **560XLS - CITATION XLS (MSG)**

Aircraft Serial: **560XL-5757**

Unit: **5757** Reg No: **N401AS**

Airworthiness: **19-Jan-2008**

Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	4548.6	4778	07-Jan-2019	.9	0.66	72.97	54	111	3
ENG 1	4501.6	4711	07-Jan-2019	.92	0.66	72.97	54	111	3
ENG 2	4501.6	4711	07-Jan-2019	.92	0.66	72.97	54	111	3
APU	2202	4829	07-Jan-2019	.53	0.66	72.97	54	111	3

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

New Requirements/Action Items

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
723110 E1	LP COMPRESSOR SECTION - ENGINE MOUNT GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY AND CONDITION OF THE ENGINE MOUNT			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	New Req
723110 E2	LP COMPRESSOR SECTION - ENGINE MOUNT GENERAL VISUAL INSPECTION: DO A CHECK FOR SECURITY AND CONDITION OF THE ENGINE MOUNT			MTH 04-Feb-2018 HRS 4024.6 LDG 4216		800		4824.6	New Req
723200 E1	HP COMPRESSOR SECTION - COMPRESSOR SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
723200 E2	HP COMPRESSOR SECTION - COMPRESSOR SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
724000 E1	COMBUSTION SECTION - COMBUSTION SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
724000 E2	COMBUSTION SECTION - COMBUSTION SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
725050 E1	TURBINE SECTION - TURBINE SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
725050 E2	TURBINE SECTION - TURBINE SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
727000 E1	BYPASS SECTION - BYPASS SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
727000 E2	BYPASS SECTION - BYPASS SECTION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
731070 E1	FUEL DISTRIBUTION - EMERGENCY FUEL SHUTOFF SYSTEM OPERATIONAL CHECK: DO A CHECK FOR THE RIGGING AND OPERATION OF THE EMERGENCY FUEL SHUTOFF SYSTEM			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
731070 E2	FUEL DISTRIBUTION - EMERGENCY FUEL SHUTOFF SYSTEM OPERATIONAL CHECK: DO A CHECK FOR THE RIGGING AND OPERATION OF THE EMERGENCY FUEL SHUTOFF SYSTEM			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
742050 E1	IGNITION - IGNITION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
742050 E2	IGNITION - IGNITION (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
751040 E1	AIR SYSTEM - AIR SYSTEM (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
751040 E2	AIR SYSTEM - AIR SYSTEM (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
771000 E1	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE INDICATING SPEED SENSOR (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
771000 E2	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE INDICATING SPEED SENSOR (ENGINE HSI) SPECIAL DETAILED INSPECTION			MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req

NOTE: Item codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference).



CESCOM 20 - Projected Maintenance Due

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**

Aircraft Model: **560XLS - CITATION XLS (MSG)**

Aircraft Serial: **560XL-5757**

Unit: **5757** Reg No: **N401AS**

Airworthiness: **19-Jan-2008**

Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	4548.6	4778	07-Jan-2019	.9	0.66	72.97	54	111	3
ENG 1	4501.6	4711	07-Jan-2019	.92	0.66	72.97	54	111	3
ENG 2	4501.6	4711	07-Jan-2019	.92	0.66	72.97	54	111	3
APU	2202	4829	07-Jan-2019	.53	0.66	72.97	54	111	3

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

New Requirements/Action Items

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
781010 E1	ENGINE EXHAUST - TURBINE EXHAUST CASE AND MIXER (ENGINE HSI) SPECIAL DETAILED INSPECTION				MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
781010 E2	ENGINE EXHAUST - TURBINE EXHAUST CASE AND MIXER (ENGINE HSI) SPECIAL DETAILED INSPECTION				MTH 19-Jan-2008 HRS 47		2500		5012.2	New Req
723140 E1	LP COMPRESSOR SECTION - LOW PRESSURE COMPRESSOR SECTION (ENGINE TBO) RESTORATION				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
723140 E2	LP COMPRESSOR SECTION - LOW PRESSURE COMPRESSOR SECTION (ENGINE TBO) RESTORATION				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
723210 E1	HP COMPRESSOR SECTION - HIGH PRESSURE COMPRESSOR SECTION (ENGINE TBO) RESTORATION				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
723210 E2	HP COMPRESSOR SECTION - HIGH PRESSURE COMPRESSOR SECTION (ENGINE TBO) RESTORATION				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
724010 E1	COMBUSTION SECTION - COMBUSTION SECTION (ENGINE TBO) RESTORATION				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
724010 E2	COMBUSTION SECTION - COMBUSTION SECTION (ENGINE TBO) RESTORATION				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
725060 E1	TURBINE SECTION - TURBINE SECTION (ENGINE TBO) RESTORATION				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
725060 E2	TURBINE SECTION - TURBINE SECTION (ENGINE TBO) RESTORATION				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
726010 E1	ACCESSORY GEARBOX - ACCESSORY GEARBOX (ENGINE TBO) RESTORATION				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
726010 E2	ACCESSORY GEARBOX - ACCESSORY GEARBOX (ENGINE TBO) RESTORATION				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
727030 E1	BYPASS SECTION - BYPASS SECTION (ENGINE TBO) RESTORATION				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
727030 E2	BYPASS SECTION - BYPASS SECTION (ENGINE TBO) RESTORATION				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731004 E1	INSPECT FUEL MANIFOLD				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731004 E2	INSPECT FUEL MANIFOLD				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731015 E1	INSPECT AND FUNCTIONAL TEST FUEL FILTER DIFFERENTIAL PRESSURE SWITCH				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731015 E2	INSPECT AND FUNCTIONAL TEST FUEL FILTER DIFFERENTIAL PRESSURE SWITCH				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731080 E1	FUEL DISTRIBUTION - FUEL DISTRIBUTION (ENGINE TBO) RESTORATION				MTH 19-Jan-2008 HRS 47		5000		5047	New Req
731080 E2	FUEL DISTRIBUTION - FUEL DISTRIBUTION (ENGINE TBO) RESTORATION				MTH 19-Jan-2008 HRS 47		5000		5047	New Req

NOTE: Item codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference).



CESCOM 20 - Projected Maintenance Due

Owner: **COLUMBIA COLLIER
PROPERTIES, LLC**

Aircraft Model: **560XLS - CITATION XLS (MSG)**

Aircraft Serial: **560XL-5757**

Unit: **5757** Reg No: **N401AS**

Airworthiness: **19-Jan-2008**

Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	4548.6	4778	07-Jan-2019	.9	0.66	72.97	54	111	3
ENG 1	4501.6	4711	07-Jan-2019	.92	0.66	72.97	54	111	3
ENG 2	4501.6	4711	07-Jan-2019	.92	0.66	72.97	54	111	3
APU	2202	4829	07-Jan-2019	.53	0.66	72.97	54	111	3

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

New Requirements/Action Items

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
731105 E1	VISUAL INSPECTION AND CHECK FREEDOM OF MOVEMENT OF FUEL SHUT-OFF CABLE			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
731105 E2	VISUAL INSPECTION AND CHECK FREEDOM OF MOVEMENT OF FUEL SHUT-OFF CABLE			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
731125 E1	INSPECT FUEL SHUT-OFF VALVE			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
731125 E2	INSPECT FUEL SHUT-OFF VALVE			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
732003 E1	INSPECT EEC			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
732003 E2	INSPECT EEC			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
732010 E1	INSPECT T0 SENSOR			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
732010 E2	INSPECT T0 SENSOR			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
732015 E1	INSPECT T1 FCU SENSOR			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
732015 E2	INSPECT T1 FCU SENSOR			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
732040 E1	FUEL CONTROLLING - FUEL CONTROLLING (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
732040 E2	FUEL CONTROLLING - FUEL CONTROLLING (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
741000 E1	CLEAN AND INSPECT IGNITION EXCITER BOX			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
741000 E2	CLEAN AND INSPECT IGNITION EXCITER BOX			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
741015 E1	CLEAN AND INSPECT IGNITION PLUGS			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
741015 E2	CLEAN AND INSPECT IGNITION PLUGS			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
742060 E1	IGNITION - IGNITION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
742060 E2	IGNITION - IGNITION (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
751050 E1	INSPECT LINEAR VARIABLE DIFFERENTIAL TRANSFORMER			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
751050 E2	INSPECT LINEAR VARIABLE DIFFERENTIAL TRANSFORMER			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
751060 E1	AIR SYSTEM - AIR SYSTEM (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47			5000		5047	New Req
751060 E2	AIR SYSTEM - AIR SYSTEM (ENGINE TBO) RESTORATION			MTH 19-Jan-2008 HRS 47			5000		5047	New Req



CESCOM 20 - Projected Maintenance Due

Owner: **COLUMBIA COLLIER
PROPERTIES, LLC**

Aircraft Model: **560XLS - CITATION XLS (MSG)**

Aircraft Serial: **560XL-5757**

Unit: **5757** Reg No: **N401AS**

Airworthiness: **19-Jan-2008**

Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/ Landings	Date	Average	Projected	Hours	Events/ Landings	Days	Months
AIRCRAFT	4548.6	4778	07-Jan-2019	.9	0.66	72.97	54	111	3
ENG 1	4501.6	4711	07-Jan-2019	.92	0.66	72.97	54	111	3
ENG 2	4501.6	4711	07-Jan-2019	.92	0.66	72.97	54	111	3
APU	2202	4829	07-Jan-2019	.53	0.66	72.97	54	111	3

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

New Requirements/Action Items

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
753000 E1	EXAMINE THE BOV TORQUE MOTOR		MTH HRS	19-Jan-2008 47		5000		5047	New Req
753000 E2	EXAMINE THE BOV TORQUE MOTOR		MTH HRS	19-Jan-2008 47		5000		5047	New Req
753001 E1	INSPECT P3 AIR INERTIAL SEPARATOR		MTH HRS	19-Jan-2008 47		5000		5047	New Req
753001 E2	INSPECT P3 AIR INERTIAL SEPARATOR		MTH HRS	19-Jan-2008 47		5000		5047	New Req
753005 E1	INSPECT COMPRESSOR AIR BLEED VALVE		MTH HRS	19-Jan-2008 47		5000		5047	New Req
753005 E2	INSPECT COMPRESSOR AIR BLEED VALVE		MTH HRS	19-Jan-2008 47		5000		5047	New Req
771010 E1	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE INDICATING SPEED SENSOR SYSTEM (ENGINE TBO) RESTORATION		MTH HRS	19-Jan-2008 47		5000		5047	New Req
771010 E2	ENGINE INDICATING (N1, N2, AND ITT) - ENGINE INDICATING SPEED SENSOR SYSTEM (ENGINE TBO) RESTORATION		MTH HRS	19-Jan-2008 47		5000		5047	New Req
771014 E1	INSPECT N1 SPEED SENSOR		MTH HRS	19-Jan-2008 47		5000		5047	New Req
771014 E2	INSPECT N1 SPEED SENSOR		MTH HRS	19-Jan-2008 47		5000		5047	New Req
771015 E1	INSPECT N2 SPEED SENSOR		MTH HRS	19-Jan-2008 47		5000		5047	New Req
771015 E2	INSPECT N2 SPEED SENSOR		MTH HRS	19-Jan-2008 47		5000		5047	New Req
772002 E1	INSPECT AND FUNCTIONAL CHECK T6 HARNESS AND THERMOCOUPLES		MTH HRS	19-Jan-2008 47		5000		5047	New Req
772002 E2	INSPECT AND FUNCTIONAL CHECK T6 HARNESS AND THERMOCOUPLES		MTH HRS	19-Jan-2008 47		5000		5047	New Req
772010 E1	INSPECT AND FUNCTIONAL CHECK T1 HARNESS		MTH HRS	19-Jan-2008 47		5000		5047	New Req
772010 E2	INSPECT AND FUNCTIONAL CHECK T1 HARNESS		MTH HRS	19-Jan-2008 47		5000		5047	New Req
774040 E1	DATA COLLECTION UNIT - DOWNLOAD DATA		MTH HRS	19-Jan-2008 47		5000		5047	New Req
774040 E2	DATA COLLECTION UNIT - DOWNLOAD DATA		MTH HRS	19-Jan-2008 47		5000		5047	New Req
781020 E1	ENGINE EXHAUST - TURBINE EXHAUST CASE AND MIXER (ENGINE TBO) RESTORATION		MTH HRS	19-Jan-2008 47		5000		5047	New Req
781020 E2	ENGINE EXHAUST - TURBINE EXHAUST CASE AND MIXER (ENGINE TBO) RESTORATION		MTH HRS	19-Jan-2008 47		5000		5047	New Req
792010 E1	INSPECT AND FUNCTIONAL TEST OIL FILTER DIFFERENTIAL PRESSURE SWITCH		MTH HRS	19-Jan-2008 47		5000		5047	New Req



CESCOM 20 - Projected Maintenance Due

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**

Aircraft Model: **560XLS - CITATION XLS (MSG)**

Aircraft Serial: **560XL-5757**

Unit: **5757** Reg No: **N401AS**

Airworthiness: **19-Jan-2008**

Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	4548.6	4778	07-Jan-2019	.9	0.66	72.97	54	111	3
ENG 1	4501.6	4711	07-Jan-2019	.92	0.66	72.97	54	111	3
ENG 2	4501.6	4711	07-Jan-2019	.92	0.66	72.97	54	111	3
APU	2202	4829	07-Jan-2019	.53	0.66	72.97	54	111	3

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

New Requirements/Action Items

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
792010 E2	INSPECT AND FUNCTIONAL TEST OIL FILTER DIFFERENTIAL PRESSURE SWITCH			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
793001 E1	INSPECT CHIP DETECTOR/COLLECTOR			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
793001 E2	INSPECT CHIP DETECTOR/COLLECTOR			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
793006 E1	INSPECT AND FUNCTION TEST OIL TANK FILLER CAP			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
793006 E2	INSPECT AND FUNCTION TEST OIL TANK FILLER CAP			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
793021 E1	INSPECT OIL LEVEL INDICATOR (SIGHT GLASS)			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
793021 E2	INSPECT OIL LEVEL INDICATOR (SIGHT GLASS)			MTH 19-Jan-2008 HRS 47		5000		5047	New Req
26-21-01-7100 AFT	AFT ENGINE FIRE EXTINGUISHER BOTTLE LOW PRESSURE SWITCH OPERATIONAL CHECK			MTH		60 MTH		31-Mar-2021	New Req
26-21-01-7100 FORWARD	FWD ENGINE FIRE EXTINGUISHER BOTTLE LOW PRESSURE SWITCH OPERATIONAL CHECK			MTH		60 MTH		31-Dec-2022	New Req
26-21-01-7101 APU	AUXILIARY POWER UNIT FIRE EXTINGUISHER BOTTLE LOW PRESSURE SWITCH OPERATIONAL CHECK			MTH		60 MTH		31-Dec-2022	New Req

Scheduled Maintenance Tasks

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30545 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			MTH HRS		6 MTH 300 HRS		28-Mar-2019 4733.93	2 m 19 d 185.33
SB PW500-72-30545 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			MTH HRS		6 MTH 300 HRS		28-Mar-2019 4733.93	2 m 19 d 185.33

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560XL-24-20	ELECTRICAL POWER - AC J-BOX WIRE BUNDLE ANCHOR INSTALLATION			MTH HRS		24 MTH 2600 HRS		03-Oct-2019 6493.48	8 m 24 d 1944.88
SB PW500-72-30479 R06 E1	REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			MTH HRS MSC		DUE		5012.2	463.6
SB PW500-72-30479 R06 E2	REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE			MTH HRS MSC		DUE		5012.2	463.6

NOTE: Item codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference).



CESCOM 20 - Projected Maintenance Due

Owner: **COLUMBIA COLLIER PROPERTIES, LLC**
 Aircraft Model: **560XLS - CITATION XLS (MSG)**
 Aircraft Serial: **560XL-5757**
 Unit: **5757** Reg No: **N401AS**
 Airworthiness: **19-Jan-2008**
 Print Date: **09-Jan-2019 9:17AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	4548.6	4778	07-Jan-2019	.9	0.66	72.97	54	111	3
ENG 1	4501.6	4711	07-Jan-2019	.92	0.66	72.97	54	111	3
ENG 2	4501.6	4711	07-Jan-2019	.92	0.66	72.97	54	111	3
APU	2202	4829	07-Jan-2019	.53	0.66	72.97	54	111	3

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Airworthiness Directives

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION									
		KMCO								
				MANDATORY	MTH 04-Feb-2018					
					HRS 4035.2	1000			5035.2	486.6
					LDG 4216					
COMPLIED WITH AD 74-08-09 R3 (K(1) EFFECTIVE DATE MARCH 28, 2012. NEXT DUE 5035.2.										